

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Addison ES	2nd Floor Hallway, High Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, High Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, Low Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, Low Water Fountain Adjacent to Room 206	< 1		
Addison ES	1st Floor Hallway, High Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, High Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, Low Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, Low Water Fountain Adjacent to Room 111	< 1		
Addison ES	Basement Floor Hallway, High Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, High Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, Low Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, Low Water Fountain Adjacent to Room B03	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Aiton ES	4th Floor, Adjacent to Stairwell	< 1		
Aiton ES	4th Floor, Adjacent to Stairwell	< 1		
Aiton ES	4th Floor, Adjacent to Elevator	< 1		
Aiton ES	4th Floor, Adjacent to Elevator	< 1		
Aiton ES	3rd Floor, Adjacent to Stairwell	< 1		
Aiton ES	3rd Floor, Adjacent to Stairwell	< 1		
Aiton ES	3rd Floor, Adjacent to Elevator	< 1		
Aiton ES	3rd Floor, Adjacent to Elevator	< 1		
Aiton ES	2nd Floor, Adjacent to Stairwell	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Aiton ES	2nd Floor, Adjacent to Stairwell	< 1		
Aiton ES	2nd Floor, Adjacent to Elevator	< 1		
Aiton ES	2nd Floor, Adjacent to Elevator	< 1		
Aiton ES	1st Floor, Inside Room 2	< 1		
Aiton ES	1st Floor, Inside Room 2	< 1		
Aiton ES	1st Floor, Inside Room 1	< 1		
Aiton ES	1st Floor, Inside Room 1	< 1		
Aiton ES	1st Floor, Adjacent to Health Suite	< 1		
Aiton ES	1st Floor, Adjacent to Health Suite	< 1		
Aiton ES	1st Floor, Main Lobby	< 1		
Aiton ES	1st Floor, Main Lobby	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Amidon ES	1st Floor, Across from Room 117	< 1		
Amidon ES	1st Floor, Across from Room 117	< 1		
Amidon ES	1st Floor, Inside Room 117	< 1		
Amidon ES	1st Floor, Inside Room 117	< 1		
Amidon ES	1st Floor, Inside Room 124	< 1		
Amidon ES	1st Floor, Inside Room 124	< 1		
Amidon ES	1st Floor, Adjacent to Room 133	< 1		
Amidon ES	1st Floor, Adjacent to Room 133	< 1		
Amidon ES	2nd Floor, Across from Room 203	< 1		
Amidon ES	2nd Floor, Across from Room 203	< 1		
Amidon ES	2nd Floor, Adjacent to Room 206-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 206-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 219-B	< 1		
Amidon ES	2nd Floor, Adjacent to Room 219-B	< 1		
Amidon ES	2nd Floor, Adjacent to Room 225-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 225-A	< 1		
Amidon ES	Inside Teacher's Lounge	< 1		
Amidon ES	Inside Teacher's Lounge	< 1		
Amidon ES	Inside Gymnasium	< 1		
Amidon ES	Inside Gymnasium	< 1		
Amidon ES	Outside Gymnasium	< 1		
Amidon ES	Outside Gymnasium	< 1		
Amidon ES	Inside Cafeteria	< 1		
Amidon ES	Inside Cafeteria	< 1		
Amidon ES	Inside Pre-K, Adjacent to Toilet	< 1		
Amidon ES	Inside Pre-K, Adjacent to Toilet	< 1		
Amidon ES	2nd Floor Hallway, Between Girls and Boys Restroom	< 1		
Amidon ES	2nd Floor Hallway, Between Girls and Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 221	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 221	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 224	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 224	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 210	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 210	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 213	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 213	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Bancroft ES	1st Floor Hallway, Main Bldg, Adjacent to Main Office	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Adjacent to Main Office	< 1		
Bancroft ES	1st Floor Hallway, Main Office, Adjacent to Room 122	< 1		
Bancroft ES	1st Floor Hallway, Main Office, Adjacent to Room 122	< 1		
Bancroft ES	Basement Floor, Inside Cafeteria	< 1		
Bancroft ES	Basement Floor, Inside Cafeteria	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Inside Health Suite	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Inside Health Suite	< 1		
Bancroft ES	2nd Floor Hallway, North Bldg, Across from Room 324	< 1		
Bancroft ES	2nd Floor Hallway, North Bldg, Across from Room 324	< 1		
Bancroft ES	1st Floor Hallway, North Bldg, Adjacent to Room 310	< 1		
Bancroft ES	1st Floor Hallway, North Bldg, Adjacent to Room 310	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 313	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 313	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 314	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 314	< 1		
Bancroft ES	Basement Floor Hallway, North Bldg, Across from Room 303	< 1		
Bancroft ES	Basement Floor Hallway, North Bldg, Across from Room 303	< 1		
Bancroft ES	Basement Floor, South Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, South Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, North Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, North Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, Inside Library Area	< 1		
Bancroft ES	Basement Floor, Inside Library Area	< 1		
Bancroft ES	Playground Area, Southwest Side (High)	1.3		
Bancroft ES	Playground Area, Southwest Side (High)	< 1		
Bancroft ES	Playground Area, Southwest Side (Low)	1.1		
Bancroft ES	Playground Area, Southwest Side (Low)	< 1		
Bancroft ES	Playground Area, Southeast Side (High)	1.4		
Bancroft ES	Playground Area, Southeast Side (High)	1.3		
Bancroft ES	Playground Area, Southeast Side (Low)	1.3		
Bancroft ES	Playground Area, Southeast Side (Low)	1		
Bancroft ES	Playground Area, Northeast Side (High)	< 1		
Bancroft ES	Playground Area, Northeast Side (High)	< 1		
Bancroft ES	Playground Area, Northeast Side (Low)	< 1		
Bancroft ES	Playground Area, Northeast Side (Low)	< 1		
Bancroft ES	Playground Area, Northwest Side (High)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Bancroft ES	Playground Area, Northwest Side (High)	< 1		
Bancroft ES	Playground Area, Northwest Side (Low)	< 1		
Bancroft ES	Playground Area, Northwest Side (Low)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Banneker ES	3rd Floor Hallway, Adjacent to Room 305	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 305	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 321	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 321	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 315	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 315	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 220	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 220	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Girls Restroom	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Girls Restroom	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 113	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 113	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 118	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 118	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Right Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Right Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Left Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Left Side)	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Banneker ES	Basement Hallway, Adjacent to Electrical Storage Room	< 1		
Banneker ES	Basement Hallway, Adjacent to Electrical Storage Room	< 1		
Banneker ES	Inside Cafeteria, (Right Side)	< 1		
Banneker ES	Inside Cafeteria, (Right Side)	< 1		
Banneker ES	Inside Cafeteria, (Left Side)	< 1		
Banneker ES	Inside Cafeteria, (Left Side)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Barnard ES	2nd Floor, Across from Art Room (Short)	< 1		
Barnard ES	2nd Floor, Across from Art Room (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Short)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Barnard ES	1st Floor, Across from Main Office (Tall)	< 1		
Barnard ES	1st Floor, Across from Main Office (Tall)	< 1		
Barnard ES	1st Floor, Across from Main Office (Short)	< 1		
Barnard ES	1st Floor, Across from Main Office (Short)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Tall)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Tall)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Short)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Short)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Tall)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Tall)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Short)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Short)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Beers ES	Lunch Room Cafeteria	< 1		
Beers ES	Lunch Room Cafeteria	< 1		
Beers ES	Inside Classroom A-112	5.5		
Beers ES	Inside Classroom A-112	< 1		
Beers ES	Inside Classroom A-108	3.4		
Beers ES	Inside Classroom A-108	< 1		
Beers ES	Inside Health Suite	< 1		
Beers ES	Inside Health Suite	< 1		
Beers ES	In Hallway, by Health Suite Office	< 1		
Beers ES	In Hallway, by Health Suite Office	< 1		
Beers ES	In Hallway, by Classroom B-206	< 1		
Beers ES	In Hallway, by Classroom B-206	< 1		
Beers ES	In Hallway, by Classroom B-201	< 1		
Beers ES	In Hallway, by Classroom B-201	< 1		
Beers ES	In Hallway, by Computer Lab in D Building	< 1		
Beers ES	In Hallway, by Computer Lab in D Building	< 1		
Beers ES	In Hallway, by Classroom D-201	< 1		
Beers ES	In Hallway, by Classroom D-201	< 1		
Beers ES	In Hallway,by Planetarium	< 1		
Beers ES	In Hallway,by Planetarium	< 1		
Beers ES	In Hallway, by Classroom D-101	< 1		
Beers ES	In Hallway, by Classroom D-101	< 1		
Beers ES	In Hallway, by Classroom D-109	< 1		
Beers ES	In Hallway, by Classroom D-109	< 1		
Beers ES	In Hallway, by Classroom D-106	< 1		
Beers ES	In Hallway, by Classroom D-106	< 1		
Beers ES	In Hallway, by Classroom D-104	< 1		
Beers ES	In Hallway, by Classroom D-104	< 1		
Beers ES	In Hallway, by Classroom A-208	< 1		
Beers ES	In Hallway, by Classroom A-208	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ballou SHS	Cafeteria #1	< 1		
Ballou SHS	Cafeteria #1	< 1		
Ballou SHS	Cafeteria #2	< 1		
Ballou SHS	Cafeteria #2	< 1		
Ballou SHS	1st Floor, Outside Gymnasium (Low)	< 1		
Ballou SHS	1st Floor, Outside Gymnasium (Low)	< 1		
Ballou SHS	1st Floor, Outside Gymnasium (High)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Ballou SHS	1st Floor, Outside Gymnasium (High)	< 1		
Ballou SHS	1st Floor, Adjacent to Room 104	< 1		
Ballou SHS	1st Floor, Adjacent to Room 104	< 1		
Ballou SHS	1st Floor, Outside Auditorium, Adjacent to Room 111	< 1		
Ballou SHS	1st Floor, Outside Auditorium, Adjacent to Room 111	< 1		
Ballou SHS	1st Floor, Adjacent to Room 114	< 1		
Ballou SHS	1st Floor, Adjacent to Room 114	< 1		
Ballou SHS	1st Floor, Outside Auditorium, Adjacent to Room 115	< 1		
Ballou SHS	1st Floor, Outside Auditorium, Adjacent to Room 115	< 1		
Ballou SHS	1st Floor, Across from Room 121	< 1		
Ballou SHS	1st Floor, Across from Room 121	< 1		
Ballou SHS	1st Floor, Across from Room 124	< 1		
Ballou SHS	1st Floor, Across from Room 124	< 1		
Ballou SHS	1st Floor, Adjacent to Room 129	< 1		
Ballou SHS	1st Floor, Adjacent to Room 129	< 1		
Ballou SHS	2nd Floor, Across from Room 204	< 1		
Ballou SHS	2nd Floor, Across from Room 204	< 1		
Ballou SHS	2nd Floor, Adjacent to Room 209	< 1		
Ballou SHS	2nd Floor, Adjacent to Room 209	< 1		
Ballou SHS	2nd Floor, Adjacent to Room 215	< 1		
Ballou SHS	2nd Floor, Adjacent to Room 215	< 1		
Ballou SHS	3rd Floor, Adjacent to Room 307	< 1		
Ballou SHS	3rd Floor, Adjacent to Room 307	< 1		
Ballou SHS	3rd Floor, Adjacent to Room 315	< 1		
Ballou SHS	3rd Floor, Adjacent to Room 315	< 1		
Ballou SHS	Lower Basement, Adjacent to Room 7	< 1		
Ballou SHS	Lower Basement, Adjacent to Room 7	< 1		
Ballou SHS	Basement, Adjacent to Room 30	< 1		
Ballou SHS	Basement, Adjacent to Room 30	< 1		
Ballou SHS	Basement, Adjacent to Room 40	< 1		
Ballou SHS	Basement, Adjacent to Room 40	< 1		
Ballou SHS	3rd Floor, Between Restrooms	< 1		
Ballou SHS	3rd Floor, Between Restrooms	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Brent ES	1st Floor, Inside Room 102	< 1		
Brent ES	1st Floor, Inside Room 102	< 1		
Brent ES	1st Floor, Inside Room 104	< 1		
Brent ES	1st Floor, Inside Room 104	< 1		
Brent ES	1st Floor, Inside Room 108	< 1		
Brent ES	1st Floor, Inside Room 108	< 1		
Brent ES	1st Floor, Inside Room 110	< 1		
Brent ES	1st Floor, Inside Room 110	< 1		
Brent ES	1st Floor, Beside Room 111	< 1		
Brent ES	1st Floor, Beside Room 111	< 1		
Brent ES	1st Floor, Inside Room 116	< 1		
Brent ES	1st Floor, Inside Room 116	< 1		
Brent ES	1st Floor, Inside Room 118	< 1		
Brent ES	1st Floor, Inside Room 118	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Brent ES	2nd Floor, Adjacent to Room 204	< 1		
Brent ES	2nd Floor, Adjacent to Room 204	< 1		
Brent ES	2nd Floor, Adjacent to Room 210	< 1		
Brent ES	2nd Floor, Adjacent to Room 210	< 1		
Brent ES	3rd Floor, Adjacent to Room 304	< 1		
Brent ES	3rd Floor, Adjacent to Room 304	< 1		
Brent ES	3rd Floor, Adjacent to Room 310	< 1		
Brent ES	3rd Floor, Adjacent to Room 310	< 1		
Brent ES	2nd Floor, Inside Teacher's Lounge	< 1		
Brent ES	2nd Floor, Inside Teacher's Lounge	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Brightwood ES	1st Floor, Outside Rooms 104 & 105 (High)	< 1		
Brightwood ES	1st Floor, Outside Rooms 104 & 105 (High)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (Low)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (Low)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (High)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (High)	< 1		
Brightwood ES	1st Floor, Inside Room 125	< 1		
Brightwood ES	1st Floor, Inside Room 125	< 1		
Brightwood ES	1st Floor, Inside Room 128	< 1		
Brightwood ES	1st Floor, Inside Room 128	< 1		
Brightwood ES	1st Floor, Inside Room 130	< 1		
Brightwood ES	1st Floor, Inside Room 130	< 1		
Brightwood ES	1st Floor, Inside Room 136	< 1		
Brightwood ES	1st Floor, Inside Room 136	< 1		
Brightwood ES	1st Floor, Inside Room 137	< 1		
Brightwood ES	1st Floor, Inside Room 137	< 1		
Brightwood ES	1st Floor, Inside Room 142	< 1		
Brightwood ES	1st Floor, Inside Room 142	< 1		
Brightwood ES	1st Floor, Inside Room 143	< 1		
Brightwood ES	1st Floor, Inside Room 143	< 1		
Brightwood ES	1st Floor, Inside Room 145	< 1		
Brightwood ES	1st Floor, Inside Room 145	< 1		
Brightwood ES	1st Floor, Inside Room 146	< 1		
Brightwood ES	1st Floor, Inside Room 146	< 1		
Brightwood ES	1st Floor, Inside Room 147	< 1		
Brightwood ES	1st Floor, Inside Room 147	< 1		
Brightwood ES	2nd Floor Hallway (Low)	< 1		
Brightwood ES	2nd Floor Hallway (Low)	< 1		
Brightwood ES	2nd Floor Hallway (High)	< 1		
Brightwood ES	2nd Floor Hallway (High)	< 1		
Brightwood ES	2nd Floor, Inside Room 206	< 1		
Brightwood ES	2nd Floor, Inside Room 206	< 1		
Brightwood ES	2nd Floor, Inside Room 208	< 1		
Brightwood ES	2nd Floor, Inside Room 208	< 1		
Brightwood ES	2nd Floor, Inside Room 210	< 1		
Brightwood ES	2nd Floor, Inside Room 210	< 1		
Brightwood ES	2nd Floor, Inside Room 212	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Brightwood ES	2nd Floor, Inside Room 212	< 1		
Brightwood ES	2nd Floor, Inside Room 213	< 1		
Brightwood ES	2nd Floor, Inside Room 213	< 1		
Brightwood ES	2nd Floor, Inside Room 214	< 1		
Brightwood ES	2nd Floor, Inside Room 214	< 1		
Brightwood ES	2nd Floor, Inside Room 216	< 1		
Brightwood ES	2nd Floor, Inside Room 216	< 1		
Brightwood ES	2nd Floor, Inside Room 218	< 1		
Brightwood ES	2nd Floor, Inside Room 218	< 1		
Brightwood ES	2nd Floor, Inside Room 224	< 1		
Brightwood ES	2nd Floor, Inside Room 224	< 1		
Brightwood ES	2nd Floor, Inside Room 228	< 1		
Brightwood ES	2nd Floor, Inside Room 228	< 1		
Brightwood ES	2nd Floor, Inside Room 235	< 1		
Brightwood ES	2nd Floor, Inside Room 235	< 1		
Brightwood ES	2nd Floor, Inside Room 237	< 1		
Brightwood ES	2nd Floor, Inside Room 237	< 1		
Brightwood ES	2nd Floor, Inside Room 239	< 1		
Brightwood ES	2nd Floor, Inside Room 239	< 1		
Brightwood ES	3rd Floor Hallway (Low)	< 1		
Brightwood ES	3rd Floor Hallway (Low)	< 1		
Brightwood ES	3rd Floor Hallway (High)	< 1		
Brightwood ES	3rd Floor Hallway (High)	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 309	< 1		
Brightwood ES	3rd Floor, Inside Room 309	< 1		
Brightwood ES	3rd Floor, Inside Room 310	< 1		
Brightwood ES	3rd Floor, Inside Room 310	< 1		
Brightwood ES	3rd Floor, Inside Room 312	< 1		
Brightwood ES	3rd Floor, Inside Room 312	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 314	< 1		
Brightwood ES	3rd Floor, Inside Room 314	< 1		
Brightwood ES	3rd Floor, Inside Room 316	< 1		
Brightwood ES	3rd Floor, Inside Room 316	< 1		
Brightwood ES	3rd Floor, Inside Room 331	< 1		
Brightwood ES	3rd Floor, Inside Room 331	< 1		
Brightwood ES	3rd Floor, Inside Room 325	< 1		
Brightwood ES	3rd Floor, Inside Room 325	< 1		
Brightwood ES	3rd Floor, Inside Room 325 (Tap)	< 1		
Brightwood ES	3rd Floor, Inside Room 325 (Tap)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Browne EC	3rd Floor Hallway, Outside Room 3-228	< 1		
Browne EC	3rd Floor Hallway, Outside Room 3-228	< 1		
Browne EC	3rd Floor Hallway, Outside Room 3-337	< 1		
Browne EC	3rd Floor Hallway, Outside Room 3-337	< 1		
Browne EC	3rd Floor Hallway, Outside Room 3-307	< 1		
Browne EC	3rd Floor Hallway, Outside Room 3-307	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-300	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-300	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-273	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-273	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-239	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-239	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-235	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-235	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-269	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-269	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-217	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-217	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-213	< 1		
Browne EC	2nd Floor Hallway, Outside Room 2-213	< 1		
Browne EC	1st Floor, Inside Classroom 1-119	8.1		
Browne EC	1st Floor, Inside Classroom 1-119	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-119	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-119	< 1		
Browne EC	1st Floor, Inside Classroom 1-112	< 1		
Browne EC	1st Floor, Inside Classroom 1-112	< 1		
Browne EC	1st Floor, Inside Classroom 1-111	< 1		
Browne EC	1st Floor, Inside Classroom 1-111	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-108	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-108	< 1		
Browne EC	1st Floor, Inside Classroom 1-108	< 1		
Browne EC	1st Floor, Inside Classroom 1-108	< 1		
Browne EC	1st Floor, Inside Classroom 1-103		59	Lead filter was installed
Browne EC	1st Floor, Inside Classroom 1-103	7.6		
Browne EC	<i>1st Floor, Inside Classroom 1-103 - Retest</i>	2.6		
Browne EC	<i>1st Floor, Inside Classroom 1-103 - Retest</i>	2.6		
Browne EC	1st Floor, Inside Classroom 1-105	< 1		
Browne EC	1st Floor, Inside Classroom 1-105	3.8		
Browne EC	1st Floor, Inside Classroom 1-124	< 1		
Browne EC	1st Floor, Inside Classroom 1-124	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-124	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-124	< 1		
Browne EC	1st Floor, Inside Classroom 1-128	< 1		
Browne EC	1st Floor, Inside Classroom 1-128	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-134	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-134	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-207	4.6		
Browne EC	1st Floor Hallway, Outside Classroom 1-207	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-137	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-137	< 1		
Browne EC	1st Floor Hallway, Outside Classroom 1-179	5.7		
Browne EC	1st Floor Hallway, Outside Classroom 1-179	5.4		
Browne EC	1st Floor Hallway, Outside Classroom 1-157	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Browne EC	1st Floor Hallway, Outside Classroom 1-157	< 1		
Browne EC	Inside Cafeteria, Right Side of Counter	< 1		
Browne EC	Inside Cafeteria, Right Side of Counter	< 1		
Browne EC	Inside Cafeteria, Left Side of Counter	< 1		
Browne EC	Inside Cafeteria, Left Side of Counter	< 1		
Browne EC	1st Floor, Inside Classroom 1-140	2.6		
Browne EC	1st Floor, Inside Classroom 1-140	< 1		
Browne EC	1st Floor, Inside Classroom 1-137	< 1		
Browne EC	1st Floor, Inside Classroom 1-137	< 1		
Browne EC	1st Floor, Inside Gymnasium	< 1		
Browne EC	1st Floor, Inside Gymnasium	< 1		
Browne EC	1st Floor, Outside Gymnasium	< 1		
Browne EC	1st Floor, Outside Gymnasium	< 1		
Browne EC	Inside Boys Locker Room	3.8		
Browne EC	Inside Boys Locker Room	< 1		
Browne EC	Hallway, Outside Gymnasium	< 1		
Browne EC	Hallway, Outside Gymnasium	< 1		
Percentage of Passed Samples				98.53%
Percentage of Failed Samples				1.47%
Bunker Hill ES	1st Floor, Across from Room 1-039	< 1		
Bunker Hill ES	1st Floor, Across from Room 1-039	< 1		
Bunker Hill ES	2nd Floor, Across from Library	< 1		
Bunker Hill ES	2nd Floor, Across from Library	< 1		
Bunker Hill ES	2nd Floor, Across from Storage Room	< 1		
Bunker Hill ES	2nd Floor, Across from Storage Room	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-092	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-092	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-088	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-088	< 1		
Bunker Hill ES	1st Floor, Adjacent to Storage Room	< 1		
Bunker Hill ES	1st Floor, Adjacent to Storage Room	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-097	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-097	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-086	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-086	< 1		
Bunker Hill ES	1st Floor, Outside Auditorium	< 1		
Bunker Hill ES	1st Floor, Outside Auditorium	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-123	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-123	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-131	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-131	< 1		
Bunker Hill ES	1st Floor, Adjacent to Room 1-061	< 1		
Bunker Hill ES	1st Floor, Adjacent to Room 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-055	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-055	< 1		
Bunker Hill ES	Basement Floor, Inside Cafeteria	< 1		
Bunker Hill ES	Basement Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Burrville ES	1st Floor Lobby, Behind Admin. Office	1.3		
Burrville ES	1st Floor Lobby, Behind Admin. Office	2.2		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Burrville ES	1st Floor Hallway, Outside Mechanical Room	< 1		
Burrville ES	1st Floor Hallway, Outside Mechanical Room	< 1		
Burrville ES	1st Floor Hallway, Outside Girls and Boys Restroom	3.8		
Burrville ES	1st Floor Hallway, Outside Girls and Boys Restroom	5.6		
Burrville ES	1st Floor Hallway, Outside Room 113/114 (L)	< 1		
Burrville ES	1st Floor Hallway, Outside Room 113/114 (L)	< 1		
Burrville ES	1st Floor Hallway, Outside Room 113/114 (R)	< 1		
Burrville ES	1st Floor Hallway, Outside Room 113/114 (R)	< 1		
Burrville ES	1st Floor, Inside Room 111	< 1		
Burrville ES	1st Floor, Inside Room 111	< 1		
Burrville ES	1st Floor, Inside Room 113	< 1		
Burrville ES	1st Floor, Inside Room 113	< 1		
Burrville ES	1st Floor, Inside Room 114	< 1		
Burrville ES	1st Floor, Inside Room 114	< 1		
Burrville ES	1st Floor, Inside Room 115	< 1		
Burrville ES	1st Floor, Inside Room 115	< 1		
Burrville ES	1st Floor, Inside Room 110	< 1		
Burrville ES	1st Floor, Inside Room 110	< 1		
Burrville ES	1st Floor, Inside Room 108	< 1		
Burrville ES	1st Floor, Inside Room 108	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (R)	1.2		
Burrville ES	2nd Floor, Inside Teacher's Lounge	1.9		
Burrville ES	2nd Floor, Inside Teacher's Lounge	3.2		
Burrville ES	2nd Floor, Inside Music Room	< 1		
Burrville ES	2nd Floor, Inside Music Room	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Double Doors/Opp. Room 241	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Double Doors/Opp. Room 241	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (L)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (L)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (R)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (R)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 228	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 228	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 227	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Burrville ES	2nd Floor Hallway, Inside Room 227	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (L)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (L)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (R)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (R)	< 1		
Burrville ES	2nd Floor, Inside Room 221	< 1		
Burrville ES	2nd Floor, Inside Room 221	< 1		
Burrville ES	2nd Floor, Inside Room 224	< 1		
Burrville ES	2nd Floor, Inside Room 224	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Burroughs ES	Basement Floor Hallway, Adjacent to Room 19	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 20	< 1		
Burroughs ES	Basement Floor, Inside Room 20	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 20	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 20	< 1		
Burroughs ES	Basement Floor, Inside Room 21	< 1		
Burroughs ES	Basement Floor, Inside Room 21	< 1		
Burroughs ES	Basement Floor, Inside Room 22	< 1		
Burroughs ES	Basement Floor, Inside Room 22	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 3	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 3	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 8	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 8	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 9	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 9	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 14	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 14	< 1		
Burroughs ES	1st Floor (New Wing) Hallway, Across from Room 27	< 1		
Burroughs ES	1st Floor (New Wing) Hallway, Across from Room 27	< 1		
Burroughs ES	1st Floor (New Wing), Bubbler Attached to Sink Inside Room 34	< 1		
Burroughs ES	1st Floor (New Wing), Bubbler Attached to Sink Inside Room 34	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 35	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 35	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 25	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 25	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
C.W. Harris ES	2nd Floor, Across from Room 246	< 1		
C.W. Harris ES	2nd Floor, Across from Room 246	< 1		
C.W. Harris ES	1st Floor, Inside Room 149	< 1		
C.W. Harris ES	1st Floor, Inside Room 149	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
C.W. Harris ES	1st Floor, Inside Room 153	< 1		
C.W. Harris ES	1st Floor, Inside Room 153	< 1		
C.W. Harris ES	1st Floor, Across from Boiler Room	< 1		
C.W. Harris ES	1st Floor, Across from Boiler Room	< 1		
C.W. Harris ES	1st Floor, Inside Cafeteria	< 1		
C.W. Harris ES	1st Floor, Inside Cafeteria	< 1		
C.W. Harris ES	1st Floor, Near Room 109	< 1		
C.W. Harris ES	1st Floor, Near Room 109	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 106	1.8		
Cleveland ES	1st Floor, Inside Room 106	< 1		
Cleveland ES	1st Floor, Inside Room 111	1.1		
Cleveland ES	1st Floor, Inside Room 111	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 212	1.2		
Cleveland ES	2nd Floor, Inside Room 212	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	2.8		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 304	1.2		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Cleveland ES	3rd Floor, Inside Room 304	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 313	1.6		
Cleveland ES	3rd Floor, Inside Room 313	2.1		
Cleveland ES	3rd Floor, Inside Room 314	1.2		
Cleveland ES	3rd Floor, Inside Room 314	< 1		
Cleveland ES	3rd Floor Hallway (Low)	< 1		
Cleveland ES	3rd Floor Hallway (Low)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Columbia Heights SHS	4th Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	4th Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	4th Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	4th Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Girls Bathroom (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Girls Bathroom (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Girls Bathroom (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Girls Bathroom (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent Classroom 111 (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent Classroom 111 (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent Classroom 111 (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent Classroom 111 (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Girls Bathroom (Low)	< 1		
Columbia Heights SHS	3rd Floor, Adjacent to Girls Bathroom (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (High)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (High)	1.2		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (Low)	< 1		
Columbia Heights SHS	2nd Floor, Adjacent to Classroom 237 (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (High)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (Low)	< 1		
Columbia Heights SHS	1st Floor, Adjacent to Boys Bathroom (Low)	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2.5		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		
Davis ES	1st Floor, Inside Teacher's Lounge	2.3		
Davis ES	1st Floor, Inside Teacher's Lounge	10		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Weight Room	1.3		
Davis ES	Lunch Room, Adjacent to Weight Room	2.1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	3.6		
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	1.6		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Drew ES	1st Floor, Auditorium Lobby (Upper)	1.4		
Drew ES	1st Floor, Auditorium Lobby (Upper)	2		
Drew ES	1st Floor, Auditorium Lobby (Lower)	1.8		
Drew ES	1st Floor, Auditorium Lobby (Lower)	2.4		
Drew ES	1st Floor, Inside Cafeteria	2.8		
Drew ES	1st Floor, Inside Cafeteria	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Lower)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Lower)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Upper)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Upper)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Drew ES	1st Floor, Inside Health Suite	12		
Drew ES	1st Floor, Inside Health Suite	< 1		
Drew ES	1st Floor, Inside Room 104	< 1		
Drew ES	1st Floor, Inside Room 104	< 1		
Drew ES	1st Floor, Inside Room 108	< 1		
Drew ES	1st Floor, Inside Room 108	< 1		
Drew ES	1st Floor, Outside Room 107 (Upper)	< 1		
Drew ES	1st Floor, Outside Room 107 (Upper)	< 1		
Drew ES	1st Floor, Outside Room 107 (Lower)	< 1		
Drew ES	1st Floor, Outside Room 107 (Lower)	< 1		
Drew ES	1st Floor, Inside Room 105	< 1		
Drew ES	1st Floor, Inside Room 105	< 1		
Drew ES	1st Floor, Inside Room 107	< 1		
Drew ES	1st Floor, Inside Room 107	5.7		
Drew ES	1st Floor, Inside Room 106	1.8		
Drew ES	1st Floor, Inside Room 106	< 1		
Drew ES	4th Floor Hallway, Outside Room 411	< 1		
Drew ES	4th Floor Hallway, Outside Room 411	< 1		
Drew ES	4th Floor Hallway, Outside Room 404 (Upper)	< 1		
Drew ES	4th Floor Hallway, Outside Room 404 (Upper)	1.4		
Drew ES	4th Floor Hallway, Outside Room 404 (Lower)	1.2		
Drew ES	4th Floor Hallway, Outside Room 404 (Lower)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Upper)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Upper)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Lower)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Lower)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 200 (Upper)	1.4		
Drew ES	2nd Floor Hallway, Outside Room 200 (Upper)	1.8		
Drew ES	2nd Floor Hallway, Outside Room 200 (Lower)	1.6		
Drew ES	2nd Floor Hallway, Outside Room 200 (Lower)	1.3		
Drew ES	2nd Floor Hallway, Inside Teacher's Lounge	< 1		
Drew ES	2nd Floor Hallway, Inside Teacher's Lounge	< 1		
Drew ES	2nd Floor Hallway, Inside Room 207	< 1		
Drew ES	2nd Floor Hallway, Inside Room 207	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Upper)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Upper)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Lower)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Lower)	< 1		
Drew ES	2nd Floor, Inside Room 207	< 1		
Drew ES	2nd Floor, Inside Room 207	< 1		
Drew ES	2nd Floor, Inside Room 205	1.1		
Drew ES	2nd Floor, Inside Room 205	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Duke Ellington SHS	3rd Floor, Adjacent to Classroom 306	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Duke Ellington SHS	3rd Floor, Adjacent to Classroom 306	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Classroom 208	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Classroom 208	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Classroom 254	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Classroom 254	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Studio A	< 1		
Duke Ellington SHS	2nd Floor, Adjacent to Studio A	< 1		
Duke Ellington SHS	1st Floor, Adjacent to Classroom 108	< 1		
Duke Ellington SHS	1st Floor, Adjacent to Classroom 108	< 1		
Duke Ellington SHS	1st Floor, Adjacent to Classroom 116	< 1		
Duke Ellington SHS	1st Floor, Adjacent to Classroom 116	1.2		
Duke Ellington SHS	1st Floor, Adjacent to Locker 255	< 1		
Duke Ellington SHS	1st Floor, Adjacent to Locker 255	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Elliot MS	1st Floor Hallway, Outside Room 200, at Entrance to Gymnasium	< 1		
Elliot MS	1st Floor Hallway, Outside Room 200, at Entrance to Gymnasium	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 307	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 307	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 303	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 303	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 301	< 1		
Elliot MS	2nd Floor Hallway, Outside Room 301	< 1		
Elliot MS	2nd Floor Hallway, Outside Staff Resource Room	< 1		
Elliot MS	2nd Floor Hallway, Outside Staff Resource Room	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Elliot MS	1st Floor Hallway, Outside Computer Lab	< 1		
Elliot MS	1st Floor Hallway, Outside Computer Lab	< 1		
Elliot MS	1st Floor Hallway, Outside Room 208	< 1		
Elliot MS	1st Floor Hallway, Outside Room 208	< 1		
Elliot MS	1st Floor Hallway, Outside Room 176	< 1		
Elliot MS	1st Floor Hallway, Outside Room 176	< 1		
Elliot MS	1st Floor Hallway, Outside Library	< 1		
Elliot MS	1st Floor Hallway, Outside Library	< 1		
Elliot MS	1st Floor Hallway, Outside Room 210	< 1		
Elliot MS	1st Floor Hallway, Outside Room 210	< 1		
Elliot MS	Basement Hallway, Outside Stairs	< 1		
Elliot MS	Basement Hallway, Outside Stairs	< 1		
Elliot MS	Basement Hallway, Outside Room 102	< 1		
Elliot MS	Basement Hallway, Outside Room 102	< 1		
Elliot MS	Basement Hallway, Outside Room I-099	< 1		
Elliot MS	Basement Hallway, Outside Room I-099	< 1		
Elliot MS	Sub-Basement, Inside Cafeteria, Right of Kitchen	< 1		
Elliot MS	Sub-Basement, Inside Cafeteria, Right of Kitchen	< 1		
Elliot MS	Sub-Basement, Inside Cafeteria, Left of Kitchen	< 1		
Elliot MS	Sub-Basement, Inside Cafeteria, Left of Kitchen	< 1		
Elliot MS	Sub-Basement, Outside Boiler Room	< 1		
Elliot MS	Sub-Basement, Outside Boiler Room	< 1		
Elliot MS	Sub-Basement, Inside Multi-Purpose Room	< 1		
Elliot MS	Sub-Basement, Inside Multi-Purpose Room	< 1		
Elliot MS	Basement Hallway, Outside Room 103	< 1		
Elliot MS	Basement Hallway, Outside Room 103	< 1		
Elliot MS	Basement Hallway, Outside Room 105	< 1		
Elliot MS	Basement Hallway, Outside Room 105	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Evans MS	3rd Floor, Adjacent to Classroom 317	< 1		
Evans MS	3rd Floor, Adjacent to Classroom 317	< 1		
Evans MS	3rd Floor, Adjacent to Classroom 306	< 1		
Evans MS	3rd Floor, Adjacent to Classroom 306	< 1		
Evans MS	3rd Floor, Adjacent to Classroom 329	< 1		
Evans MS	3rd Floor, Adjacent to Classroom 329	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 234	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 234	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 206	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 206	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 211	< 1		
Evans MS	2nd Floor, Adjacent to Classroom 211	< 1		
Evans MS	1st Floor, Adjacent to Classroom 111	< 1		
Evans MS	1st Floor, Adjacent to Classroom 111	< 1		
Evans MS	1st Floor, Adjacent to Classroom 144	< 1		
Evans MS	1st Floor, Adjacent to Classroom 144	< 1		
Evans MS	1st Floor, Adjacent to Classroom 150	< 1		
Evans MS	1st Floor, Adjacent to Classroom 150	< 1		
Evans MS	Basement Floor, Adjacent to Classroom 078	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Evans MS	Basement Floor, Adjacent to Classroom 078	< 1		
Evans MS	Basement Floor, Adjacent to Classroom 070	< 1		
Evans MS	Basement Floor, Adjacent to Classroom 070	< 1		
Evans MS	Basement Floor, Adjacent to Classroom 024	< 1		
Evans MS	Basement Floor, Adjacent to Classroom 024	< 1		
Evans MS	Basement Floor, Inside Lunch Room	< 1		
Evans MS	Basement Floor, Inside Lunch Room	< 1		
Evans MS	Basement Floor, Inside Lunch Room	< 1		
Evans MS	Basement Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ferebee Hope ES	4th Floor Hallway, Across from Room 406	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 406	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 405	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 405	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 403	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 403	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 402	< 1		
Ferebee Hope ES	4th Floor Hallway, Across from Room 402	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 306	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 306	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 305	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 305	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 303	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 303	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 302	< 1		
Ferebee Hope ES	3rd Floor Hallway, Across from Room 302	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 206	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 206	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 205	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 205	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 204	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 204	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 203	< 1		
Ferebee Hope ES	2nd Floor Hallway, Across from Room 203	< 1		
Ferebee Hope ES	1st Floor, Inside Room 106	< 1		
Ferebee Hope ES	1st Floor, Inside Room 106	< 1		
Ferebee Hope ES	1st Floor, Inside Room 105	< 1		
Ferebee Hope ES	1st Floor, Inside Room 105	< 1		
Ferebee Hope ES	1st Floor, Inside Room 102	< 1		
Ferebee Hope ES	1st Floor, Inside Room 102	< 1		
Ferebee Hope ES	1st Floor, Inside Teacher's Lounge	< 1		
Ferebee Hope ES	1st Floor, Inside Teacher's Lounge	< 1		
Ferebee Hope ES	1st Floor, Inside Room 103	< 1		
Ferebee Hope ES	1st Floor, Inside Room 103	< 1		
Ferebee Hope ES	1st Floor, Inside Room 104	< 1		
Ferebee Hope ES	1st Floor, Inside Room 104	< 1		
Ferebee Hope ES	1st Floor Hallway, Across from Teacher's Lounge	< 1		
Ferebee Hope ES	1st Floor Hallway, Across from Teacher's Lounge	< 1		
Ferebee Hope ES	1st Floor, Inside Health Suite	< 1		
Ferebee Hope ES	1st Floor, Inside Health Suite	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Ferebee Hope ES	1st Floor Hallway, At the Entrance to Gymnasium (East Side)	< 1		
Ferebee Hope ES	1st Floor Hallway, At the Entrance to Gymnasium (East Side)	< 1		
Ferebee Hope ES	1st Floor Hallway, At the Entrance to Gymnasium (West Side)	< 1		
Ferebee Hope ES	1st Floor Hallway, At the Entrance to Gymnasium (West Side)	< 1		
Ferebee Hope ES	1st Floor, Inside Boys' Locker Room	< 1		
Ferebee Hope ES	1st Floor, Inside Boys' Locker Room	< 1		
Ferebee Hope ES	1st Floor Auditorium Hallway, Adjacent to Boys Restroom (East Side)	< 1		
Ferebee Hope ES	1st Floor Auditorium Hallway, Adjacent to Boys Restroom (East Side)	< 1		
Ferebee Hope ES	1st Floor Auditorium Hallway, Adjacent to Boys Restroom (West Side)	< 1		
Ferebee Hope ES	1st Floor Auditorium Hallway, Adjacent to Boys Restroom (West Side)	< 1		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 1	13		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 1	11		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 2	4.3		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 2	2.6		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 3		23	Lead filter was installed
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 3	13		
Ferebee Hope ES	<i>1st Floor, (W. Rice Bldg.), Inside Classroom Area 3 - Retest</i>	< 1		
Ferebee Hope ES	<i>1st Floor, (W. Rice Bldg.), Inside Classroom Area 3 - Retest</i>	< 1		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 4 (East Side)	2.3		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 4 (East Side)	11		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 4 (West Side)	6.9		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 4 (West Side)	7.2		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 5	4.6		
Ferebee Hope ES	1st Floor, (W. Rice Bldg.), Inside Classroom Area 5	8.6		
Ferebee Hope ES	2nd Floor (W. Rice Bldg.) Hallway, Between Boys' and Girls' Restroom	< 1		
Ferebee Hope ES	2nd Floor (W. Rice Bldg.) Hallway, Between Boys' and Girls' Restroom	< 1		
Ferebee Hope ES	2nd Floor Hallway, Adjacent to Girls Locker Room Entrance	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Ferebee Hope ES	2nd Floor Hallway, Adjacent to Girls Locker Room Entrance	< 1		
Ferebee Hope ES	2nd Floor, Inside Girls Locker Room	< 1		
Ferebee Hope ES	2nd Floor, Inside Girls Locker Room	< 1		
Percentage of Passed Samples				98.53%
Percentage of Failed Samples				1.47%
Francis JHS	3rd Floor Hallway, Outside Room 304	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 304	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 303	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 303	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 203	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 203	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 204	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 204	< 1		
Francis JHS	1st Floor Hallway, Outside Room 100	< 1		
Francis JHS	1st Floor Hallway, Outside Room 100	< 1		
Francis JHS	1st Floor, Inside Teacher's Lounge	< 1		
Francis JHS	1st Floor, Inside Teacher's Lounge	< 1		
Francis JHS	1st Floor, Inside Students' Cafeteria	< 1		
Francis JHS	1st Floor, Inside Students' Cafeteria	< 1		
Francis JHS	1st Floor Hallway, Outside Electrical Room	< 1		
Francis JHS	1st Floor Hallway, Outside Electrical Room	< 1		
Francis JHS	1st Floor, Inside Room 108	< 1		
Francis JHS	1st Floor, Inside Room 108	< 1		
Francis JHS	1st Floor, Inside Room 110	< 1		
Francis JHS	1st Floor, Inside Room 110	< 1		
Francis JHS	1st Floor, Inside Room 107	< 1		
Francis JHS	1st Floor, Inside Room 107	< 1		
Francis JHS	1st Floor, Inside Room 105	< 1		
Francis JHS	1st Floor, Inside Room 105	< 1		
Francis JHS	1st Floor, Inside Room 103	< 1		
Francis JHS	1st Floor, Inside Room 103	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Garfield ES	2nd Floor, Adjacent to Room 2-J	< 1		
Garfield ES	2nd Floor, Adjacent to Room 2-J	< 1		
Garfield ES	1st Floor, Adjacent to Main Office	< 1		
Garfield ES	1st Floor, Adjacent to Main Office	< 1		
Garfield ES	1st Floor, Inside Health Suite	< 1		
Garfield ES	1st Floor, Inside Health Suite	< 1		
Garfield ES	1st Floor, Across from Room 1-F	< 1		
Garfield ES	1st Floor, Across from Room 1-F	< 1		
Garfield ES	Basement Floor, Inside Cafeteria	< 1		
Garfield ES	Basement Floor, Inside Cafeteria	< 1		
Garfield ES	Basement Floor, Inside Cafeteria, Adjacent to Snack Bar	< 1		
Garfield ES	Basement Floor, Inside Cafeteria, Adjacent to Snack Bar	< 1		
Garfield ES	1st Floor, Adjacent to Teacher's Lounge	< 1		
Garfield ES	1st Floor, Adjacent to Teacher's Lounge	< 1		
Garfield ES	1st Floor, Across from Room 102	< 1		
Garfield ES	1st Floor, Across from Room 102	< 1		
Garfield ES	1st Floor, Inside Room 102	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Garfield ES	1st Floor, Inside Room 102	< 1		
Garfield ES	1st Floor, Inside Room 101	< 1		
Garfield ES	1st Floor, Inside Room 101	< 1		
Garfield ES	2nd Floor, Across from Girls Restroom	< 1		
Garfield ES	2nd Floor, Across from Girls Restroom	< 1		
Garfield ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Garfield ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Garnet-Patterson MS	1st Floor Hallway, Outside Room 110	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Room 110	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Left of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Left of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Right of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Right of Kitchen	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Gymnasium	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Gymnasium	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 308	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 308	< 1		
Garnet-Patterson MS	3rd Floor, Inside Teacher's Lounge	< 1		
Garnet-Patterson MS	3rd Floor, Inside Teacher's Lounge	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 303	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 303	< 1		
Garnet-Patterson MS	2nd Floor Hallway, Outside Room 216	< 1		
Garnet-Patterson MS	2nd Floor Hallway, Outside Room 216	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Garrison ES	1st Floor, Outside Room 108	< 1		
Garrison ES	1st Floor, Outside Room 108	< 1		
Garrison ES	1st Floor, Inside Room 109	< 1		
Garrison ES	1st Floor, Inside Room 109	< 1		
Garrison ES	1st Floor, Inside Room 110	< 1		
Garrison ES	1st Floor, Inside Room 110	< 1		
Garrison ES	1st Floor, Across from Room 128	< 1		
Garrison ES	1st Floor, Across from Room 128	< 1		
Garrison ES	2nd Floor, Inside Room 201	1.6		
Garrison ES	2nd Floor, Inside Room 201	< 1		
Garrison ES	2nd Floor, Inside Room 207	< 1		
Garrison ES	2nd Floor, Inside Room 207	< 1		
Garrison ES	2nd Floor, Beside Room 212	< 1		
Garrison ES	2nd Floor, Beside Room 212	< 1		
Garrison ES	Outside Library	< 1		
Garrison ES	Outside Library	< 1		
Garrison ES	Outside Main Office	< 1		
Garrison ES	Outside Main Office	< 1		
Garrison ES	Inside Cafeteria	< 1		
Garrison ES	Inside Cafeteria	< 1		
Garrison ES	1st Floor, Beside Room 122	< 1		
Garrison ES	1st Floor, Beside Room 122	< 1		
Garrison ES	Inside Health Suite	< 1		
Garrison ES	Inside Health Suite	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Green ES	3rd Floor Hallway, Outside Room 315	< 1		
Green ES	3rd Floor Hallway, Outside Room 315	< 1		
Green ES	3rd Floor Hallway, Outside Room 308	< 1		
Green ES	3rd Floor Hallway, Outside Room 308	< 1		
Green ES	2nd Floor Hallway, Outside Room 208	< 1		
Green ES	2nd Floor Hallway, Outside Room 208	< 1		
Green ES	2nd Floor Hallway, Outside Room 214	< 1		
Green ES	2nd Floor Hallway, Outside Room 214	< 1		
Green ES	2nd Floor Hallway, Outside Room 218	< 1		
Green ES	2nd Floor Hallway, Outside Room 218	< 1		
Green ES	2nd Floor, Inside Room 225	< 1		
Green ES	2nd Floor, Inside Room 225	< 1		
Green ES	1st Floor, Inside Room 130	< 1		
Green ES	1st Floor, Inside Room 130	< 1		
Green ES	1st Floor, Inside Room 131	< 1		
Green ES	1st Floor, Inside Room 131	< 1		
Green ES	1st Floor Hallway, Outside Room 132	< 1		
Green ES	1st Floor Hallway, Outside Room 132	< 1		
Green ES	1st Floor, Inside All Purpose Room	< 1		
Green ES	1st Floor, Inside All Purpose Room	< 1		
Green ES	1st Floor Hallway, Outside Room 115	< 1		
Green ES	1st Floor Hallway, Outside Room 115	2.5		
Green ES	1st Floor, Inside Nurse's Suite	< 1		
Green ES	1st Floor, Inside Nurse's Suite	3.3		
Green ES	1st Floor Hallway, Outside Room 108	< 1		
Green ES	1st Floor Hallway, Outside Room 108	< 1		
Percentage of Passed Samples				100.00%
				0.00%
Hamilton Bldg.	2nd Floor, Adjacent to Exit	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Exit	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Room 205	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Room 205	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Main Entrance	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Main Entrance	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to the Bathroom	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to the Bathroom	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Room 237	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Room 237	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Main Entrance (Right Side)	< 1		
Hamilton Bldg.	2nd Floor, Adjacent to Main Entrance (Right Side)	< 1		
Hamilton Bldg.	2nd Floor, In Main Office	2		
Hamilton Bldg.	2nd Floor, In Main Office	2		
Hamilton Bldg.	2nd Floor, Adjacent to Room 2004	1.6		
Hamilton Bldg.	2nd Floor, Adjacent to Room 2004	1.5		
Hamilton Bldg.	2nd Floor, Adjacent to Room 2007	1.1		
Hamilton Bldg.	2nd Floor, Adjacent to Room 2007	1.5		
Hamilton Bldg.	2nd Floor, Inside the Gymnasium	< 1		
Hamilton Bldg.	2nd Floor, Inside the Gymnasium	< 1		
Hamilton Bldg.	2nd Floor, Inside the Gymnasium	< 1		
Hamilton Bldg.	2nd Floor, Inside the Gymnasium	< 1		
Hamilton Bldg.	1st Floor, Inside Room 1005	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Hamilton Bldg.	1st Floor, Inside Room 1005	< 1		
Hamilton Bldg.	1st Floor, Inside Room 1014	< 1		
Hamilton Bldg.	1st Floor, Inside Room 1014	< 1		
Hamilton Bldg.	1st Floor, Inside Room 1004	3.4		
Hamilton Bldg.	1st Floor, Inside Room 1004	3.8		
Hamilton Bldg.	1st Floor, Inside Room 1019	2.2		
Hamilton Bldg.	1st Floor, Inside Room 1019	3.9		
Hamilton Bldg.	1st Floor, Adjacent to Storage Room	< 1		
Hamilton Bldg.	1st Floor, Adjacent to Storage Room	1.3		
Percentage of Passed Samples				100.00%
				0.00%
Hardy ES	1st Floor Hallway, Outside Room 102 (Upper)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Upper)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Lower)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Lower)	< 1		
Hardy ES	3rd Floor Hallway, Near Elevator (Upper)	< 1		
Hardy ES	3rd Floor Hallway, Near Elevator (Upper)	< 1		
Hardy ES	3rd Floor Hallway, Near Elevator (Lower)	< 1		
Hardy ES	3rd Floor Hallway, Near Elevator (Lower)	< 1		
Hardy ES	3rd Floor Hallway, Near Exit to Hardy Field (Upper)	< 1		
Hardy ES	3rd Floor Hallway, Near Exit to Hardy Field (Upper)	< 1		
Hardy ES	3rd Floor Hallway, Near Exit to Hardy Field (Lower)	< 1		
Hardy ES	3rd Floor Hallway, Near Exit to Hardy Field (Lower)	< 1		
Hardy ES	2nd Floor Hallway, Outside Room 212 (Upper)	< 1		
Hardy ES	2nd Floor Hallway, Outside Room 212 (Upper)	< 1		
Hardy ES	2nd Floor Hallway, Outside Room 212 (Lower)	< 1		
Hardy ES	2nd Floor Hallway, Outside Room 212 (Lower)	< 1		
Hardy ES	2nd Floor, Inside Gymnasium (Upper)	< 1		
Hardy ES	2nd Floor, Inside Gymnasium (Upper)	< 1		
Hardy ES	2nd Floor, Inside Gymnasium (Lower)	< 1		
Hardy ES	2nd Floor, Inside Gymnasium (Lower)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Upper)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Upper)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Lower)	< 1		
Hardy ES	1st Floor Hallway, Outside Room 102 (Lower)	< 1		
Hardy ES	2nd Floor, Adjacent to Security Desk (Upper)	2.6		
Hardy ES	2nd Floor, Adjacent to Security Desk (Upper)	5.7		
Hardy ES	2nd Floor, Adjacent to Security Desk (Lower)	5.2		
Hardy ES	2nd Floor, Adjacent to Security Desk (Lower)	4.5		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hart MS	3rd Floor, Adjacent to Classroom 321 (Upper)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 321 (Upper)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 321 (Lower)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 321 (Lower)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Hart MS	3rd Floor, Adjacent to Classroom 305 (Upper)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 305 (Upper)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 305 (Lower)	< 1		
Hart MS	3rd Floor, Adjacent to Classroom 305 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 206 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 206 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 206 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 206 (Lower)	5.2		
Hart MS	2nd Floor, Adjacent to Classroom 226 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 226 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 226 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 226 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 226 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 232 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 232 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 232 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 232 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 237 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 237 (Upper)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 237 (Lower)	< 1		
Hart MS	2nd Floor, Adjacent to Classroom 237 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 123 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 123 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 123 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 123 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Exit (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Exit (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Exit (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Exit (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 119 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 119 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 119 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 119 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 103 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 103 (Upper)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 103 (Lower)	< 1		
Hart MS	1st Floor, Adjacent to Classroom 103 (Lower)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Hart MS	1st Floor, in Gymnasium, Boys Locker Room (Upper)	< 1		
Hart MS	1st Floor, in Gymnasium, Boys Locker Room (Upper)	< 1		
Hart MS	1st Floor, in Gymnasium, Boys Locker Room (Lower)	< 1		
Hart MS	1st Floor, in Gymnasium, Boys Locker Room (Lower)	< 1		
Hart MS	Basement Floor, Adjacent to Room 011 (Upper)	< 1		
Hart MS	Basement Floor, Adjacent to Room 011 (Upper)	< 1		
Hart MS	Basement Floor, Adjacent to Room 011 (Lower)	< 1		
Hart MS	Basement Floor, Adjacent to Room 011 (Lower)	< 1		
Hart MS	Basement Floor, Inside Lunch Room (Upper)	< 1		
Hart MS	Basement Floor, Inside Lunch Room (Upper)	< 1		
Hart MS	Basement Floor, Inside Lunch Room (Lower)	< 1		
Hart MS	Basement Floor, Inside Lunch Room (Lower)	< 1		
Hart MS	Basement Floor, Adjacent to Stairwell 3 (Upper)	< 1		
Hart MS	Basement Floor, Adjacent to Stairwell 3 (Upper)	< 1		
Hart MS	Basement Floor, Adjacent to Stairwell 3 (Lower)	< 1		
Hart MS	Basement Floor, Adjacent to Stairwell 3 (Lower)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hendley ES	Ground Floor, Inside Cafeteria	< 1		
Hendley ES	Ground Floor, Inside Cafeteria	< 1		
Hendley ES	Ground Floor Hallway, Adjacent to P.E. Teacher's Office	< 1		
Hendley ES	Ground Floor Hallway, Adjacent to P.E. Teacher's Office	< 1		
Hendley ES	Ground Floor Hallway, Adjacent to Room 7	< 1		
Hendley ES	Ground Floor Hallway, Adjacent to Room 7	< 1		
Hendley ES	Ground Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Hendley ES	Ground Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom	< 1		
Hendley ES	1st Floor, Inside Health Suite	< 1		
Hendley ES	1st Floor, Inside Health Suite	< 1		
Hendley ES	1st Floor Hallway, Adjacent to Teacher's Lounge	< 1		
Hendley ES	1st Floor Hallway, Adjacent to Teacher's Lounge	< 1		
Hendley ES	1st Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom	< 1		
Hendley ES	1st Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom	< 1		
Hendley ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Hendley ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Hendley ES	2nd Floor Hallway, Adjacent to Room 201	< 1		
Hendley ES	2nd Floor Hallway, Adjacent to Room 201	< 1		
Hendley ES	3rd Floor Hallway, Adjacent to Room 301	< 1		
Hendley ES	3rd Floor Hallway, Adjacent to Room 301	< 1		
Hendley ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Hendley ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Hendley ES	2nd Floor, Inside Room 202	< 1		
Hendley ES	2nd Floor, Inside Room 202	< 1		
Hendley ES	2nd Floor, Inside Room 203	4.9		
Hendley ES	2nd Floor, Inside Room 203	2.7		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Houston ES	2nd Floor, Adjacent to Room 212	< 1		
Houston ES	2nd Floor, Adjacent to Room 212	< 1		
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hyde ES	1st Floor Lobby, Adjacent to Classroom 105	< 1		
Hyde ES	1st Floor Lobby, Adjacent to Classroom 105	< 1		
Hyde ES	2nd Floor Lobby, Adjacent to Classroom 203	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Hyde ES	2nd Floor Lobby, Adjacent to Classroom 203	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
J.O. Wilson ES	3rd Floor, Adjacent to Room 308	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 308	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 312	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 312	< 1		
J.O. Wilson ES	3rd Floor, Across from Room 301	< 1		
J.O. Wilson ES	3rd Floor, Across from Room 301	< 1		
J.O. Wilson ES	2nd Floor, Across from Room 201	< 1		
J.O. Wilson ES	2nd Floor, Across from Room 201	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 212	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 212	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 208	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 208	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 329	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 329	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 328	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 328	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 321	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 321	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 322	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 322	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 221	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 221	< 1		
J.O. Wilson ES	2nd Floor, Room in Classroom 221	< 1		
J.O. Wilson ES	2nd Floor, Room in Classroom 221	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 220	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 223	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 223	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222 (Sink)	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222 (Sink)	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222	< 1		
J.O. Wilson ES	1st Floor, Inside Lunch Room	< 1		
J.O. Wilson ES	1st Floor, Inside Lunch Room	< 1		
J.O. Wilson ES	1st Floor, Near Custodian's Closet	< 1		
J.O. Wilson ES	1st Floor, Near Custodian's Closet	< 1		
J.O. Wilson ES	1st Floor, Near Mechanical Room	< 1		
J.O. Wilson ES	1st Floor, Near Mechanical Room	< 1		
J.O. Wilson ES	1st Floor, Inside Room 121	4.7		
J.O. Wilson ES	1st Floor, Inside Room 121	2.5		
J.O. Wilson ES	1st Floor, Inside Room 123	< 1		
J.O. Wilson ES	1st Floor, Inside Room 123	< 1		
J.O. Wilson ES	1st Floor, Across from Main Office	< 1		
J.O. Wilson ES	1st Floor, Across from Main Office	< 1		
J.O. Wilson ES	1st Floor, Inside Room 108	< 1		
J.O. Wilson ES	1st Floor, Inside Room 108	< 1		
J.O. Wilson ES	1st Floor, Across from Room 108C	< 1		
J.O. Wilson ES	1st Floor, Across from Room 108C	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
J.O. Wilson ES	1st Floor, Inside Room 109	< 1		
J.O. Wilson ES	1st Floor, Inside Room 109	< 1		
J.O. Wilson ES	1st Floor, Inside Room 112	< 1		
J.O. Wilson ES	1st Floor, Inside Room 112	< 1		
J.O. Wilson ES	1st Floor, Inside Room 111	< 1		
J.O. Wilson ES	1st Floor, Inside Room 111	< 1		
J.O. Wilson ES	1st Floor, Inside Room 110	< 1		
J.O. Wilson ES	1st Floor, Inside Room 110	< 1		
J.O. Wilson ES	1st Floor, Adjacent to Room 110	< 1		
J.O. Wilson ES	1st Floor, Adjacent to Room 110	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor, Inside Room 307	1.4		
Janney ES	3rd Floor, Inside Room 307	1.1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 304	< 1		
Janney ES	3rd Floor, Inside Room 304	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Outside Room 207	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Janney ES	2nd Floor, Outside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 209	1.1		
Janney ES	2nd Floor, Inside Room 209	1.2		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.7		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.3		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	4.3		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Jefferson MS	1st Floor, Adjacent to Main Office (Left Side)	< 1		
Jefferson MS	1st Floor, Adjacent to Main Office (Left Side)	< 1		
Jefferson MS	1st Floor, Adjacent to Room 109 (Right Side)	< 1		
Jefferson MS	1st Floor, Adjacent to Room 109 (Right Side)	< 1		
Jefferson MS	1st Floor, Adjacent to Room 105 (Left Side)	< 1		
Jefferson MS	1st Floor, Adjacent to Room 105 (Left Side)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Jefferson MS	3rd Floor, Adjacent to Room 301 (Left Side)	< 1		
Jefferson MS	3rd Floor, Adjacent to Room 301 (Left Side)	< 1		
Jefferson MS	2nd Floor, Adjacent to Room 219 (Right Side)	< 1		
Jefferson MS	2nd Floor, Adjacent to Room 219 (Right Side)	< 1		
Jefferson MS	2nd Floor, Adjacent to Room 207 (Left Side)	< 1		
Jefferson MS	2nd Floor, Adjacent to Room 207 (Left Side)	< 1		
Jefferson MS	1st Floor, Inside Gymnasium Girls Locker Room	< 1		
Jefferson MS	1st Floor, Inside Gymnasium Girls Locker Room	< 1		
Jefferson MS	1st Floor, Inside Gymnasium Boys Locker Room	< 1		
Jefferson MS	1st Floor, Inside Gymnasium Boys Locker Room	< 1		
Jefferson MS	Basement Floor, Adjacent to Boiler Room (Right Side)	< 1		
Jefferson MS	Basement Floor, Adjacent to Boiler Room (Right Side)	< 1		
Jefferson MS	Basement Floor, Inside Lunch Room	< 1		
Jefferson MS	Basement Floor, Inside Lunch Room	< 1		
Jefferson MS	Basement Floor, Adjacent to Room 01 (Left Side)	< 1		
Jefferson MS	Basement Floor, Adjacent to Room 01 (Left Side)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	1.7		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	< 1		
Johnson MS	3rd Floor, Outside Room 315A (Up)	9		
Johnson MS	3rd Floor, Outside Room 315A (Up)	14		
Johnson MS	3rd Floor, Outside Room 315A (Down)	7		
Johnson MS	3rd Floor, Outside Room 315A (Down)	8.7		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	2.6		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.2		
Johnson MS	1st Floor, Adjacent to Elevator	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Johnson MS	1st Floor, Adjacent to Elevator	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
K.C. Lewis ES	1st Floor Hallway, Between Boys and Girls Restroom	< 1		
K.C. Lewis ES	1st Floor Hallway, Between Boys and Girls Restroom	< 1		
K.C. Lewis ES	1st Floor Hallway, Adjacent to Classroom 135	< 1		
K.C. Lewis ES	1st Floor Hallway, Adjacent to Classroom 135	< 1		
K.C. Lewis ES	2nd Floor Hallway, Adjacent to Boys and Girls Restroom	< 1		
K.C. Lewis ES	2nd Floor Hallway, Adjacent to Boys and Girls Restroom	< 1		
K.C. Lewis ES	2nd Floor Hallway, Adjacent to Classroom 208	< 1		
K.C. Lewis ES	2nd Floor Hallway, Adjacent to Classroom 208	< 1		
K.C. Lewis ES	3rd Floor Hallway, Between Boys and Girls Restroom	< 1		
K.C. Lewis ES	3rd Floor Hallway, Between Boys and Girls Restroom	< 1		
K.C. Lewis ES	3rd Floor Hallway, Adjacent to Classroom 307	< 1		
K.C. Lewis ES	3rd Floor Hallway, Adjacent to Classroom 307	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kelly Miller ES	1st Floor, Inside Cafeteria	< 1		
Kelly Miller ES	1st Floor, Inside Cafeteria	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Kelly Miller ES	1st Floor, Outside Cafeteria (Tall)	< 1		
Kelly Miller ES	1st Floor, Outside Cafeteria (Tall)	< 1		
Kelly Miller ES	1st Floor, Outside Cafeteria (Short)	< 1		
Kelly Miller ES	1st Floor, Outside Cafeteria (Short)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Room A118 (Tall)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Room A118 (Tall)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Room A118 (Short)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Room A118 (Short)	< 1		
Kelly Miller ES	1st Floor, Inside Gymnasium Entrance Door	< 1		
Kelly Miller ES	1st Floor, Inside Gymnasium Entrance Door	< 1		
Kelly Miller ES	1st Floor, Inside Gymnasium, Adjacent to Room D122	< 1		
Kelly Miller ES	1st Floor, Inside Gymnasium, Adjacent to Room D122	< 1		
Kelly Miller ES	1st Floor, Inside Room 135	< 1		
Kelly Miller ES	1st Floor, Inside Room 135	< 1		
Kelly Miller ES	1st Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Elevator (Short)	< 1		
Kelly Miller ES	1st Floor, Adjacent to Elevator (Short)	< 1		
Kelly Miller ES	2nd Floor, Near Elevator Room A218 (Tall)	< 1		
Kelly Miller ES	2nd Floor, Near Elevator Room A218 (Tall)	< 1		
Kelly Miller ES	2nd Floor, Near Elevator Room A218 (Short)	< 1		
Kelly Miller ES	2nd Floor, Near Elevator Room A218 (Short)	< 1		
Kelly Miller ES	2nd Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	2nd Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	2nd Floor, Adjacent to Elevator (Short)	< 1		
Kelly Miller ES	2nd Floor, Adjacent to Elevator (Short)	< 1		
Kelly Miller ES	3rd Floor, Near Elevator Storage Room (Tall)	< 1		
Kelly Miller ES	3rd Floor, Near Elevator Storage Room (Tall)	< 1		
Kelly Miller ES	3rd Floor, Near Elevator Storage Room (Short)	< 1		
Kelly Miller ES	3rd Floor, Near Elevator Storage Room (Short)	< 1		
Kelly Miller ES	3rd Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	3rd Floor, Adjacent to Elevator (Tall)	< 1		
Kelly Miller ES	3rd Floor, Adjacent to Elevator (Short)	< 1		
Kelly Miller ES	3rd Floor, Adjacent to Elevator (Short)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	2.2		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ketcham ES	2nd Floor, Adjacent to Room 204	< 1		
Ketcham ES	2nd Floor, Adjacent to Room 204	< 1		
Ketcham ES	1st Floor, Adjacent to Room 104	< 1		
Ketcham ES	1st Floor, Adjacent to Room 104	< 1		
Ketcham ES	Ground Floor, Adjacent to Girls Restroom, Stair F	< 1		
Ketcham ES	Ground Floor, Adjacent to Girls Restroom, Stair F	< 1		
Ketcham ES	1st Floor, Adjacent to Preschool Room 2	< 1		
Ketcham ES	1st Floor, Adjacent to Preschool Room 2	< 1		
Ketcham ES	3rd Floor, Adjacent to Boys and Girls Restroom	< 1		
Ketcham ES	3rd Floor, Adjacent to Boys and Girls Restroom	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 2	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 2	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 1	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 1	< 1		
Ketcham ES	1st Floor, Inside Pre-K Room	< 1		
Ketcham ES	1st Floor, Inside Pre-K Room	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	2.3		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Key ES	Outisde, On Playground	< 1		
Key ES	Outisde, On Playground	< 1		
Key ES	Ground Floor, Adjacent to Girls Restroom	< 1		
Key ES	Ground Floor, Adjacent to Girls Restroom	< 1		
Key ES	1st Floor, Adjacent to Room 103	< 1		
Key ES	1st Floor, Adjacent to Room 103	< 1		
Key ES	1st Floor, Across from Room 103	< 1		
Key ES	1st Floor, Across from Room 103	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Key ES	2nd Floor, Adjacent to Room 207	< 1		
Key ES	2nd Floor, Adjacent to Room 207	< 1		
Key ES	2nd Floor, Across from Room 203	< 1		
Key ES	2nd Floor, Across from Room 203	< 1		
Key ES	2nd Floor, Inside Teacher's Lounge	< 1		
Key ES	2nd Floor, Inside Teacher's Lounge	< 1		
Key ES	1st Floor, Inside Room 106	< 1		
Key ES	1st Floor, Inside Room 106	< 1		
Key ES	1st Floor, Inside Room 105	< 1		
Key ES	1st Floor, Inside Room 105	< 1		
Key ES	1st Floor, Inside Room 104	< 1		
Key ES	1st Floor, Inside Room 104	< 1		
Key ES	1st Floor, Inside Room 103	< 1		
Key ES	1st Floor, Inside Room 103	< 1		
Key ES	1st Floor, Inside Room 102	< 1		
Key ES	1st Floor, Inside Room 102	< 1		
Key ES	1st Floor, Inside Room 101	< 1		
Key ES	1st Floor, Inside Room 101	< 1		
Key ES	2nd Floor, Inside Room 202	< 1		
Key ES	2nd Floor, Inside Room 202	< 1		
Key ES	2nd Floor, Inside Room 201	< 1		
Key ES	2nd Floor, Inside Room 201	< 1		
Key ES	2nd Floor, Inside Room 203	< 1		
Key ES	2nd Floor, Inside Room 203	< 1		
Key ES	2nd Floor, Inside Room 204	< 1		
Key ES	2nd Floor, Inside Room 204	< 1		
Key ES	2nd Floor, Inside Room 206	< 1		
Key ES	2nd Floor, Inside Room 206	< 1		
Key ES	2nd Floor, Inside Room 205	< 1		
Key ES	2nd Floor, Inside Room 205	< 1		
Key ES	2nd Floor, Inside Room 207	< 1		
Key ES	2nd Floor, Inside Room 207	< 1		
Key ES	2nd Floor, Inside Room 208	< 1		
Key ES	2nd Floor, Inside Room 208	< 1		
Key ES	2nd Floor, Inside Room 209	< 1		
Key ES	2nd Floor, Inside Room 209	< 1		
Key ES	2nd Floor, Inside Room 210	< 1		
Key ES	2nd Floor, Inside Room 210	< 1		
Key ES	2nd Floor, Inside Room 211	< 1		
Key ES	2nd Floor, Inside Room 211	< 1		
Key ES	2nd Floor, Inside Room 212	< 1		
Key ES	2nd Floor, Inside Room 212	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kimball ES	2nd Floor, Adjacent to Science Lab	< 1		
Kimball ES	2nd Floor, Adjacent to Science Lab	< 1		
Kimball ES	2nd Floor, Adjacent to Room 200	1.2		
Kimball ES	2nd Floor, Adjacent to Room 200	< 1		
Kimball ES	1st Floor, Adjacent to Room 100	< 1		
Kimball ES	1st Floor, Adjacent to Room 100	< 1		
Kimball ES	1st Floor, Adjacent to Girls Restroom	< 1		
Kimball ES	1st Floor, Adjacent to Girls Restroom	< 1		
Kimball ES	2nd Floor, Outside Auditorium	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Kimball ES	2nd Floor, Outside Auditorium	1.4		
Kimball ES	1st Floor, Inside Room 102	< 1		
Kimball ES	1st Floor, Inside Room 102	< 1		
Kimball ES	2nd Floor, Adjacent to Teacher's Lounge	< 1		
Kimball ES	2nd Floor, Adjacent to Teacher's Lounge	< 1		
Kimball ES	2nd Floor, Adjacent to Room 212	< 1		
Kimball ES	2nd Floor, Adjacent to Room 212	< 1		
Kimball ES	1st Floor, Adjacent to Room 108	< 1		
Kimball ES	1st Floor, Adjacent to Room 108	< 1		
Kimball ES	1st Floor, Adjacent to Room 112	< 1		
Kimball ES	1st Floor, Adjacent to Room 112	< 1		
Kimball ES	1st Floor, Inside Room 109	< 1		
Kimball ES	1st Floor, Inside Room 109	< 1		
Kimball ES	1st Floor, Inside Principal's Office	< 1		
Kimball ES	1st Floor, Inside Principal's Office	< 1		
Kimball ES	1st Floor, Adjacent to Room 115	3.4		
Kimball ES	1st Floor, Adjacent to Room 115	3.3		
Kimball ES	Basement Floor, Across from Room 004	< 1		
Kimball ES	Basement Floor, Across from Room 004	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kramer MS	3rd Floor Hallway, Adjacent to Room 306	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 306	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 305	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 305	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 317	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 317	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 318	< 1		
Kramer MS	3rd Floor Hallway, Adjacent to Room 318	< 1		
Kramer MS	2nd Floor Hallway, Between NE Fan Room and Teacher's Lounge	< 1		
Kramer MS	2nd Floor Hallway, Between NE Fan Room and Teacher's Lounge	< 1		
Kramer MS	2nd Floor, Inside Teacher's Lounge	< 1		
Kramer MS	2nd Floor, Inside Teacher's Lounge	< 1		
Kramer MS	2nd Floor Hallway, Adjacent to Room 204	< 1		
Kramer MS	2nd Floor Hallway, Adjacent to Room 204	< 1		
Kramer MS	2nd Floor Hallway, Adjacent to Room 201	< 1		
Kramer MS	2nd Floor Hallway, Adjacent to Room 201	< 1		
Kramer MS	2nd Floor Hallway, Between NE Fan Room and Room 213	< 1		
Kramer MS	2nd Floor Hallway, Between NE Fan Room and Room 213	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Room 103	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Room 103	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Main Office	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Main Office	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Health Suite	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Health Suite	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Room 111	< 1		
Kramer MS	1st Floor Hallway, Adjacent to Room 111	< 1		
Kramer MS	1st Floor Hallway, Inside Boys' Locker Room	< 1		
Kramer MS	1st Floor Hallway, Inside Boys' Locker Room	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Kramer MS	1st Floor Hallway, Inside Girls' Locker Room	< 1		
Kramer MS	1st Floor Hallway, Inside Girls' Locker Room	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Custodial's Office	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Custodial's Office	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Storage 22	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Storage 22	< 1		
Kramer MS	Basement Floor Hallway, Across from Storage 15	< 1		
Kramer MS	Basement Floor Hallway, Across from Storage 15	< 1		
Kramer MS	Basement Floor, Inside Cafeteria (Boys' Restroom Side)	< 1		
Kramer MS	Basement Floor, Inside Cafeteria (Boys' Restroom Side)	< 1		
Kramer MS	Basement Floor, Inside Cafeteria (Girls' Restroom Side)	< 1		
Kramer MS	Basement Floor, Inside Cafeteria (Girls' Restroom Side)	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Mechanical Electrical Room 1	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Mechanical Electrical Room 1	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Room 14 (Exit to Parking Lot)	< 1		
Kramer MS	Basement Floor Hallway, Adjacent to Room 14 (Exit to Parking Lot)	< 1		
Kramer MS	Annex Bldg, Hallway, Adjacent to Room 128	< 1		
Kramer MS	Annex Bldg, Hallway, Adjacent to Room 128	< 1		
Kramer MS	Annex Bldg, Inside Room 120	< 1		
Kramer MS	Annex Bldg, Inside Room 120	< 1		
Kramer MS	Annex Bldg, Hallway, Adjacent to Room 103	< 1		
Kramer MS	Annex Bldg, Hallway, Adjacent to Room 103	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Lafayette ES	Team 4 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 4 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 4 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 4 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Left Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Right Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Right Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Left Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Left Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Left Side	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Lafayette ES	Team 2 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Washing Machine	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Washing Machine	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Ice Box	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Ice Box	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Right Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Right Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Left Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Left Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Exit	< 1		
Lafayette ES	Basement Floor, Adjacent to the Exit	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Langdon ES	Basement Floor, Inside Cafeteria	1.1		
Langdon ES	Basement Floor, Inside Cafeteria	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Speech Clinic Room	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Speech Clinic Room	< 1		
Langdon ES	1st Floor, Inside Health Suite	< 1		
Langdon ES	1st Floor, Inside Health Suite	< 1		
Langdon ES	1st Floor, Inside Auditorium	2.1		
Langdon ES	1st Floor, Inside Auditorium	1.8		
Langdon ES	1st Floor Hallway, Adjacent to Room 111	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Room 111	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Room 116	2.9		
Langdon ES	1st Floor Hallway, Adjacent to Room 116	3.2		
Langdon ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 214	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 214	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Langley JHS	1st Floor, Inside Room 149	< 1		
Langley JHS	1st Floor, Inside Room 149	< 1		
Langley JHS	1st Floor, Inside Room 143	< 1		
Langley JHS	1st Floor, Inside Room 143	< 1		
Langley JHS	1st Floor, Inside Room 137	< 1		
Langley JHS	1st Floor, Inside Room 137	< 1		
Langley JHS	1st Floor, Inside Room 133	< 1		
Langley JHS	1st Floor, Inside Room 133	< 1		
Langley JHS	1st Floor, Inside Staff Lounge	< 1		
Langley JHS	1st Floor, Inside Staff Lounge	< 1		
Langley JHS	1st Floor, Inside Room 125	< 1		
Langley JHS	1st Floor, Inside Room 125	< 1		
Langley JHS	1st Floor, Inside Room 122	< 1		
Langley JHS	1st Floor, Inside Room 122	< 1		
Langley JHS	1st Floor, Inside Room 113	< 1		
Langley JHS	1st Floor, Inside Room 113	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	1.2		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 301	3.3		
Langley JHS	3rd Floor Hallway, Outside Room 301	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Lasalle ES	1st Floor Hallway, Outside Principal's Office	< 1		
Lasalle ES	1st Floor Hallway, Outside Principal's Office	< 1		
Lasalle ES	1st Floor Hallway, Outside Men's Restroom	< 1		
Lasalle ES	1st Floor Hallway, Outside Men's Restroom	< 1		
Lasalle ES	1st Floor Hallway, Outside Incinerator Room	< 1		
Lasalle ES	1st Floor Hallway, Outside Incinerator Room	< 1		
Lasalle ES	1st Floor Hallway, Outside Room 121	< 1		
Lasalle ES	1st Floor Hallway, Outside Room 121	< 1		
Lasalle ES	3rd Floor Hallway, Outside Room 308	< 1		
Lasalle ES	3rd Floor Hallway, Outside Room 308	< 1		
Lasalle ES	3rd Floor Hallway, Outside Room 302	< 1		
Lasalle ES	3rd Floor Hallway, Outside Room 302	< 1		
Lasalle ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Lasalle ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Lasalle ES	2nd Floor Hallway, Outside Room 208	< 1		
Lasalle ES	2nd Floor Hallway, Outside Room 208	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Lasalle ES	Ground Floor Hallway, Outside Custodial' Office	< 1		
Lasalle ES	Ground Floor Hallway, Outside Custodial' Office	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Leckie ES	1st Floor Hallway, Adjacent to Teacher's Restroom	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Teacher's Restroom	< 1		
Leckie ES	1st Floor Hallway, Inside Health Suite	< 1		
Leckie ES	1st Floor Hallway, Inside Health Suite	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Room 121	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Room 121	< 1		
Leckie ES	1st Floor, Inside All Purpose Room	< 1		
Leckie ES	1st Floor, Inside All Purpose Room	< 1		
Leckie ES	Basement Floor, Inside Recreation Room	< 1		
Leckie ES	Basement Floor, Inside Recreation Room	< 1		
Leckie ES	Basement Floor, Adjacent to Recreation Room	< 1		
Leckie ES	Basement Floor, Adjacent to Recreation Room	< 1		
Leckie ES	Basement Floor, Inside Room 14	< 1		
Leckie ES	Basement Floor, Inside Room 14	< 1		
Leckie ES	Basement Floor, Inside Room 21	< 1		
Leckie ES	Basement Floor, Inside Room 21	< 1		
Leckie ES	Basement Floor, Inside Room 24	< 1		
Leckie ES	Basement Floor, Inside Room 24	< 1		
Leckie ES	Basement Floor, Inside Room 30	< 1		
Leckie ES	Basement Floor, Inside Room 30	< 1		
Leckie ES	2nd Floor, Adjacent to Room 214	< 1		
Leckie ES	2nd Floor, Adjacent to Room 214	< 1		
Leckie ES	2nd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	2nd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Room 312	< 1		
Leckie ES	3rd Floor, Adjacent to Room 312	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Logan ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Logan ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Logan ES	1st Floor Hallway, Adjacent to Room 101	< 1		
Logan ES	1st Floor Hallway, Adjacent to Room 101	< 1		
Logan ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Logan ES	2nd Floor Hallway, Adjacent to Room 212	6.8		
Logan ES	Basement Floor, Inside Cafeteria	< 1		
Logan ES	Basement Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ludlow Taylor ES	3rd Floor Stairs	< 1		
Ludlow Taylor ES	3rd Floor Stairs	< 1		
Ludlow Taylor ES	2nd Floor Hallway, Adjacent to Stairs	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Ludlow Taylor ES	2nd Floor Hallway, Adjacent to Stairs	< 1		
Ludlow Taylor ES	2nd Floor Stairs	< 1		
Ludlow Taylor ES	2nd Floor Stairs	< 1		
Ludlow Taylor ES	1st Floor, Outside Classroom	< 1		
Ludlow Taylor ES	1st Floor, Outside Classroom	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 100	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 100	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 101	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 101	< 1		
Ludlow Taylor ES	1st Floor Hallway, Adjacent to Classroom	< 1		
Ludlow Taylor ES	1st Floor Hallway, Adjacent to Classroom	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 116A	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 116A	< 1		
Ludlow Taylor ES	1st Floor, Adjacent to Gymnasium	< 1		
Ludlow Taylor ES	1st Floor, Adjacent to Gymnasium	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Luke Moore Academy	1st Floor Hallway, Outside Women's Restroom	< 1		
Luke Moore Academy	1st Floor Hallway, Outside Women's Restroom	< 1		
Luke Moore Academy	1st Floor Hallway, Outside Men's Restroom	< 1		
Luke Moore Academy	1st Floor Hallway, Outside Men's Restroom	< 1		
Luke Moore Academy	2nd Floor Hallway, Left of Men's Restroom	< 1		
Luke Moore Academy	2nd Floor Hallway, Left of Men's Restroom	< 1		
Luke Moore Academy	2nd Floor Hallway, Right of Women's Restroom	< 1		
Luke Moore Academy	2nd Floor Hallway, Right of Women's Restroom	< 1		
Luke Moore Academy	Ground Floor Hallway, Outside Room B22 (High)	< 1		
Luke Moore Academy	Ground Floor Hallway, Outside Room B22 (High)	< 1		
Luke Moore Academy	Ground Floor Hallway, Outside Room B22 (Low)	< 1		
Luke Moore Academy	Ground Floor Hallway, Outside Room B22 (Low)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
M.C. Terrell ES	3rd Floor, Adjacent to Room 302	< 1		
M.C. Terrell ES	3rd Floor, Adjacent to Room 302	< 1		
M.C. Terrell ES	3rd Floor, Adjacent to the Bathroom	< 1		
M.C. Terrell ES	3rd Floor, Adjacent to the Bathroom	< 1		
M.C. Terrell ES	3rd Floor, Adjacent to Room 308		270	Lead filter was installed
M.C. Terrell ES	3rd Floor, Adjacent to Room 308	9.7		
M.C. Terrell ES	3rd Floor, Adjacent to Room 308 - Retest	< 1		
M.C. Terrell ES	3rd Floor, Adjacent to Room 308 - Retest	< 1		
M.C. Terrell ES	2nd Floor, Adjacent to Storage Room	8.3		
M.C. Terrell ES	2nd Floor, Adjacent to Storage Room	9.9		
M.C. Terrell ES	2nd Floor, Adjacent to Room 203	< 1		
M.C. Terrell ES	2nd Floor, Adjacent to Room 203	< 1		
M.C. Terrell ES	2nd Floor, Adjacent to Room 205	< 1		
M.C. Terrell ES	2nd Floor, Adjacent to Room 205	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
M.C. Terrell ES	2nd Floor, Adjacent to Room 208	4.3		
M.C. Terrell ES	2nd Floor, Adjacent to Room 208	4.2		
M.C. Terrell ES	2nd Floor, Adjacent to Media Center	< 1		
M.C. Terrell ES	2nd Floor, Adjacent to Media Center	< 1		
M.C. Terrell ES	1st Floor, Adjacent to Elevator	< 1		
M.C. Terrell ES	1st Floor, Adjacent to Elevator	1.8		
M.C. Terrell ES	1st Floor, Adjacent to Room 103	< 1		
M.C. Terrell ES	1st Floor, Adjacent to Room 103	< 1		
M.C. Terrell ES	1st Floor, Adjacent to the Bathroom	3.2		
M.C. Terrell ES	1st Floor, Adjacent to the Bathroom	1.3		
M.C. Terrell ES	1st Floor, Adjacent to Room 108	< 1		
M.C. Terrell ES	1st Floor, Adjacent to Room 108	< 1		
M.C. Terrell ES	Ground Floor, Inside Lunch Room	< 1		
M.C. Terrell ES	Ground Floor, Inside Lunch Room	< 1		
M.C. Terrell ES	Ground Floor, In the Kitchen	< 1		
M.C. Terrell ES	Ground Floor, In the Kitchen	< 1		
M.C. Terrell ES	Ground Floor, In the Gymnasium Girls Bathroom	< 1		
M.C. Terrell ES	Ground Floor, In the Gymnasium Girls Bathroom	< 1		
M.C. Terrell ES	Ground Floor, In the Gymnasium Boys Bathroom	< 1		
M.C. Terrell ES	Ground Floor, In the Gymnasium Boys Bathroom	< 1		
M.C. Terrell ES	Ground Floor, Adjacent to the Lunch Room	< 1		
M.C. Terrell ES	Ground Floor, Adjacent to the Lunch Room	< 1		
M.C. Terrell ES	Ground Floor, Inside Teacher's Room	3.6		
M.C. Terrell ES	Ground Floor, Inside Teacher's Room	1.3		
M.C. Terrell ES	Ground Floor, Pre-K, Adjacent to the Bathroom	< 1		
M.C. Terrell ES	Ground Floor, Pre-K, Adjacent to the Bathroom	< 1		
M.C. Terrell ES	Ground Floor, Pre-K, Adjacent to the Exit	< 1		
M.C. Terrell ES	Ground Floor, Pre-K, Adjacent to the Exit	< 1		
M.C. Terrell ES	Basement Floor, Adjacent to the Bathroom	< 1		
M.C. Terrell ES	Basement Floor, Adjacent to the Bathroom	< 1		
Percentage of Passed Samples				97.73%
Percentage of Failed Samples				2.27%
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (Low)	< 1		
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (Low)	< 1		
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (High)	< 1		
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (High)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (Low)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (Low)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (High)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
MacFarland MS	3rd Floor Hallway, Adjacent to Classroom 302	< 1		
MacFarland MS	3rd Floor Hallway, Adjacent to Classroom 302	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
MacFarland MS	3rd Floor Hallway, Adjacent to Classroom 303/300	< 1		
MacFarland MS	3rd Floor Hallway, Adjacent to Classroom 303/300	< 1		
MacFarland MS	2nd Floor Hallway, Adjacent to Classroom 252	< 1		
MacFarland MS	2nd Floor Hallway, Adjacent to Classroom 252	< 1		
MacFarland MS	2nd Floor Hallway, Adjacent to Classroom 203	< 1		
MacFarland MS	2nd Floor Hallway, Adjacent to Classroom 203	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Classroom 152	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Classroom 152	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Classroom 158	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Classroom 158	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Women's Restroom	< 1		
MacFarland MS	1st Floor Hallway, Adjacent to Women's Restroom	< 1		
MacFarland MS	Basement, Inside Cafeteria	< 1		
MacFarland MS	Basement, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Malcolm X ES	4th Floor Hallway, Right Side	< 1		
Malcolm X ES	4th Floor Hallway, Right Side	< 1		
Malcolm X ES	4th Floor Hallway, Left Side	< 1		
Malcolm X ES	4th Floor Hallway, Left Side	< 1		
Malcolm X ES	3rd Floor Hallway, Right Side	< 1		
Malcolm X ES	3rd Floor Hallway, Right Side	< 1		
Malcolm X ES	3rd Floor Hallway, Left Side	< 1		
Malcolm X ES	3rd Floor Hallway, Left Side	< 1		
Malcolm X ES	2nd Floor Hallway, Right Side	< 1		
Malcolm X ES	2nd Floor Hallway, Right Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Left Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Left Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Right Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Right Side	< 1		
Malcolm X ES	1st Floor, Pre-K Classroom	< 1		
Malcolm X ES	1st Floor, Pre-K Classroom	< 1		
Malcolm X ES	1st Floor, Lunchroom	< 1		
Malcolm X ES	1st Floor, Lunchroom	< 1		
Malcolm X ES	1st Floor, Lunchroom, Adjacent to the Exit	< 1		
Malcolm X ES	1st Floor, Lunchroom, Adjacent to the Exit	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Mamie D Lee ES	1st Floor, Inside Room 11	< 1		
Mamie D Lee ES	1st Floor, Inside Room 11	< 1		
Mamie D Lee ES	1st Floor, Inside Room 13	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Mamie D Lee ES	1st Floor, Inside Room 13	< 1		
Mamie D Lee ES	1st Floor, Inside Room 15	< 1		
Mamie D Lee ES	1st Floor, Inside Room 15	< 1		
Mamie D Lee ES	1st Floor, Inside Room 17	< 1		
Mamie D Lee ES	1st Floor, Inside Room 17	< 1		
Mamie D Lee ES	1st Floor, Inside Room 19	< 1		
Mamie D Lee ES	1st Floor, Inside Room 19	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 20	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 20	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 22	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 22	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 24	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 24	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 26	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 26	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 28	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 28	< 1		
Mamie D Lee ES	1st Floor, Inside Cafeteria	< 1		
Mamie D Lee ES	1st Floor, Inside Cafeteria	< 1		
Mamie D Lee ES	1st Floor Hallway, Outside PE Office	< 1		
Mamie D Lee ES	1st Floor Hallway, Outside PE Office	< 1		
Mamie D Lee ES	1st Floor, Inside Room 10	< 1		
Mamie D Lee ES	1st Floor, Inside Room 10	< 1		
Mamie D Lee ES	1st Floor, Inside Room 12	< 1		
Mamie D Lee ES	1st Floor, Inside Room 12	< 1		
Mamie D Lee ES	1st Floor Hallway	< 1		
Mamie D Lee ES	1st Floor Hallway	< 1		
Mamie D Lee ES	1st Floor, Medical and Dental Office	< 1		
Mamie D Lee ES	1st Floor, Medical and Dental Office	< 1		
Mamie D Lee ES	1st Floor, Inside Kitchen	< 1		
Mamie D Lee ES	1st Floor, Inside Kitchen	< 1		
Mamie D Lee ES	1st Floor, Inside Room 14	< 1		
Mamie D Lee ES	1st Floor, Inside Room 14	< 1		
Mamie D Lee ES	1st Floor, Inside Room 16	< 1		
Mamie D Lee ES	1st Floor, Inside Room 16	< 1		
Mamie D Lee ES	1st Floor, Inside Room 18	< 1		
Mamie D Lee ES	1st Floor, Inside Room 18	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 21	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 21	< 1		
Mamie D Lee ES	2nd Floor Hallway	< 1		
Mamie D Lee ES	2nd Floor Hallway	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 23	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 23	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 25	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 25	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 27	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 27	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 29	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 29	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Mann ES	2nd Floor, Adjacent to Room 205	< 1		
Mann ES	2nd Floor, Adjacent to Room 205	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	Inside Cafeteria	< 1		
Mann ES	Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Marie Reed LC	2nd Floor, Outside A&S Room 5	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 5	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 6	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 6	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 8	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 8	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 3	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 3	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 4	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 4	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 1	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 1	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 2	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 2	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 7	< 1		
Marie Reed LC	2nd Floor, Outside A&S Room 7	< 1		
Marie Reed LC	1st Floor, Outside Cafeteria by Auditorium Entrance	< 1		
Marie Reed LC	1st Floor, Outside Cafeteria by Auditorium Entrance	< 1		
Marie Reed LC	1st Floor, Inside Teacher's Lounge	< 1		
Marie Reed LC	1st Floor, Inside Teacher's Lounge	< 1		
Marie Reed LC	1st Floor, Inside Auditorium	8.2		
Marie Reed LC	1st Floor, Inside Auditorium	2.8		
Marie Reed LC	1st Floor Hallway, Outside Storage 11	< 1		
Marie Reed LC	1st Floor Hallway, Outside Storage 11	< 1		
Marie Reed LC	1st Floor, Outside Toilet	< 1		
Marie Reed LC	1st Floor, Outside Toilet	< 1		
Marie Reed LC	1st Floor, Inside Small Cafeteria	< 1		
Marie Reed LC	1st Floor, Inside Small Cafeteria	< 1		
Marie Reed LC	1st Floor Hallway, Outside Main Office, by Girls Restroom	< 1		
Marie Reed LC	1st Floor Hallway, Outside Main Office, by Girls Restroom	< 1		
Marie Reed LC	1st Floor, Inside Main Office	2.1		
Marie Reed LC	1st Floor, Inside Main Office	2.1		
Marie Reed LC	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Marie Reed LC	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Marie Reed LC	Pool Balcony Hallway	< 1		
Marie Reed LC	Pool Balcony Hallway	< 1		
Marie Reed LC	Inside Boys Pool Locker Room	6		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Marie Reed LC	Inside Boys Pool Locker Room	6.7		
Marie Reed LC	Outside Men's Office (Pool Level)	2.3		
Marie Reed LC	Outside Men's Office (Pool Level)	1.6		
Marie Reed LC	Inside Girls Pool Locker Room	< 1		
Marie Reed LC	Inside Girls Pool Locker Room	< 1		
Marie Reed LC	Ground Floor, Inside Gymnasium	1.4		
Marie Reed LC	Ground Floor, Inside Gymnasium	1.8		
Marie Reed LC	Ground Floor Hallway, Outside Gymnasium, Adjacent to Girls Restroom	< 1		
Marie Reed LC	Ground Floor Hallway, Outside Gymnasium, Adjacent to Girls Restroom	< 1		
Marie Reed LC	Ground Floor Hallway, Outside Gymnasium, Adjacent to Boys Restroom	3.8		
Marie Reed LC	Ground Floor Hallway, Outside Gymnasium, Adjacent to Boys Restroom	3.7		
Marie Reed LC	Basement Clinic Hallway, Adjacent to Men's Restroom	< 1		
Marie Reed LC	Basement Clinic Hallway, Adjacent to Men's Restroom	< 1		
Marie Reed LC	Basement Clinic Hallway, Adjacent to Women's Restroom	2.4		
Marie Reed LC	Basement Clinic Hallway, Adjacent to Women's Restroom	2.6		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Marshall ES	Mezzanine Level Hallway, Outside Women's Restroom	< 1		
Marshall ES	Mezzanine Level Hallway, Outside Women's Restroom	< 1		
Marshall ES	Mezzanine Level Hallway, Adjacent to Ramp	< 1		
Marshall ES	Mezzanine Level Hallway, Adjacent to Ramp	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 5	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 5	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 4	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 4	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 1	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 1	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 2	< 1		
Marshall ES	Above Plaza Level, at Entrance to Stairwell 2	< 1		
Marshall ES	Plaza Level Hallway, Outside Teacher's Lounge by Door	< 1		
Marshall ES	Plaza Level Hallway, Outside Teacher's Lounge by Door	< 1		
Marshall ES	Plaza Level Hallway, Outside Teacher's Lounge by Steps	< 1		
Marshall ES	Plaza Level Hallway, Outside Teacher's Lounge by Steps	< 1		
Marshall ES	Plaza Level Hallway, Outside Restroom	< 1		
Marshall ES	Plaza Level Hallway, Outside Restroom	< 1		
Marshall ES	Plaza Level Hallway, Between Girls/Boys Restrooms	< 1		
Marshall ES	Plaza Level Hallway, Between Girls/Boys Restrooms	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Marshall ES	Below Plaza Level, Hallway Between Boys/Girls Restrooms (Up)	< 1		
Marshall ES	Below Plaza Level, Hallway Between Boys/Girls Restrooms (Up)	< 1		
Marshall ES	Below Plaza Level, Hallway Between Boys/Girls Restrooms (Down)	< 1		
Marshall ES	Below Plaza Level, Hallway Between Boys/Girls Restrooms (Down)	< 1		
Marshall ES	Plaza Level, Lobby Hallway	< 1		
Marshall ES	Plaza Level, Lobby Hallway	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Maury ES	Inside Cafeteria	< 1		
Maury ES	Inside Cafeteria	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Up)	1.4		
Maury ES	Basement, Between Rooms W022 & W020 (Up)	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W030	< 1		
Maury ES	Basement, In Room W030	1.2		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E140	< 1		
Maury ES	1st Floor, In Room E140	< 1		
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	2nd Floor, Across from Room 202	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Meyer ES	2nd Floor, Across from Room 202	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Miner ES	2nd Floor, Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Bathroom (Right Side)	< 1		
Miner ES	2nd Floor, Bathroom (Right Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 209	< 1		
Miner ES	2nd Floor, Inside Classroom 209	< 1		
Miner ES	2nd Floor, Inside Classroom 211	< 1		
Miner ES	2nd Floor, Inside Classroom 211	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 213	< 1		
Miner ES	2nd Floor, Inside Classroom 213	< 1		
Miner ES	2nd Floor, Inside Classroom 215	< 1		
Miner ES	2nd Floor, Inside Classroom 215	< 1		
Miner ES	2nd Floor, Inside Classroom 217	< 1		
Miner ES	2nd Floor, Inside Classroom 217	< 1		
Miner ES	2nd Floor, Inside Classroom 219	< 1		
Miner ES	2nd Floor, Inside Classroom 219	< 1		
Miner ES	2nd Floor, Inside Classroom 225	< 1		
Miner ES	2nd Floor, Inside Classroom 225	< 1		
Miner ES	2nd Floor, Inside Classroom 227	< 1		
Miner ES	2nd Floor, Inside Classroom 227	< 1		
Miner ES	2nd Floor, Inside Classroom 229	< 1		
Miner ES	2nd Floor, Inside Classroom 229	< 1		
Miner ES	2nd Floor, Inside Classroom 231	< 1		
Miner ES	2nd Floor, Inside Classroom 231	< 1		
Miner ES	2nd Floor, Inside Classroom 233	< 1		
Miner ES	2nd Floor, Inside Classroom 233	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 234	1.1		
Miner ES	2nd Floor, Inside Classroom 234	< 1		
Miner ES	2nd Floor, Inside Classroom 238	< 1		
Miner ES	2nd Floor, Inside Classroom 238	< 1		
Miner ES	2nd Floor Bathroom (Right Side)	< 1		
Miner ES	2nd Floor Bathroom (Right Side)	< 1		
Miner ES	2nd Floor Bathroom (Left Side)	< 1		
Miner ES	2nd Floor Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 255	< 1		
Miner ES	2nd Floor, Inside Classroom 255	< 1		
Miner ES	2nd Floor, Pet Room (Right Side)	< 1		
Miner ES	2nd Floor, Pet Room (Right Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 251	< 1		
Miner ES	2nd Floor, Inside Classroom 251	< 1		
Miner ES	2nd Floor, Inside Classroom 249	< 1		
Miner ES	2nd Floor, Inside Classroom 249	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Miner ES	2nd Floor, Inside Classroom 243	< 1		
Miner ES	2nd Floor, Inside Classroom 243	< 1		
Miner ES	2nd Floor, Inside Classroom 241	< 1		
Miner ES	2nd Floor, Inside Classroom 241	< 1		
Miner ES	1st Floor, Adjacent to Room 146 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 146 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Tall)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Tall)	< 1		
Miner ES	1st Floor, Inside Room 135	< 1		
Miner ES	1st Floor, Inside Room 135	< 1		
Miner ES	1st Floor, Inside Room 133	< 1		
Miner ES	1st Floor, Inside Room 133	< 1		
Miner ES	1st Floor, Inside Room 131	< 1		
Miner ES	1st Floor, Inside Room 131	< 1		
Miner ES	1st Floor, Inside Room 129	< 1		
Miner ES	1st Floor, Inside Room 129	< 1		
Miner ES	1st Floor, Inside Room 127	< 1		
Miner ES	1st Floor, Inside Room 127	< 1		
Miner ES	1st Floor, Inside Room 123	< 1		
Miner ES	1st Floor, Inside Room 123	< 1		
Miner ES	1st Floor, Inside Room 121	< 1		
Miner ES	1st Floor, Inside Room 121	< 1		
Miner ES	1st Floor, Inside Room 119	< 1		
Miner ES	1st Floor, Inside Room 119	< 1		
Miner ES	1st Floor, Inside Room 117	< 1		
Miner ES	1st Floor, Inside Room 117	< 1		
Miner ES	1st Floor, Inside Room 115	< 1		
Miner ES	1st Floor, Inside Room 115	< 1		
Miner ES	1st Floor, Inside Room 111	< 1		
Miner ES	1st Floor, Inside Room 111	< 1		
Miner ES	1st Floor, Inside Room 109	< 1		
Miner ES	1st Floor, Inside Room 109	< 1		
Miner ES	1st Floor, Inside Room 107	< 1		
Miner ES	1st Floor, Inside Room 107	< 1		
Miner ES	1st Floor, Inside Room 105	< 1		
Miner ES	1st Floor, Inside Room 105	< 1		
Miner ES	1st Floor, Inside Room 103	< 1		
Miner ES	1st Floor, Inside Room 103	< 1		
Miner ES	1st Floor, Inside Room 101	< 1		
Miner ES	1st Floor, Inside Room 101	< 1		
Miner ES	1st Floor Pet Center #2, Adjacent to Room 103	< 1		
Miner ES	1st Floor Pet Center #2, Adjacent to Room 103	< 1		
Miner ES	1st Floor, Inside Room 132	< 1		
Miner ES	1st Floor, Inside Room 132	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 200B	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Murch ES	2nd Floor, Across from Room 200B	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Nalle ES	1st Floor, Inside Room 118	< 1		
Nalle ES	1st Floor, Inside Room 118	< 1		
Nalle ES	Basement Floor, Across from Room 130	< 1		
Nalle ES	Basement Floor, Across from Room 130	< 1		
Nalle ES	2nd Floor, Across from Room 230	< 1		
Nalle ES	2nd Floor, Across from Room 230	< 1		
Nalle ES	2nd Floor, Across from Library	< 1		
Nalle ES	2nd Floor, Across from Library	< 1		
Nalle ES	2nd Floor, Across from Room 206	< 1		
Nalle ES	2nd Floor, Across from Room 206	< 1		
Nalle ES	2nd Floor, Adjacent to Room 211	< 1		
Nalle ES	2nd Floor, Adjacent to Room 211	< 1		
Nalle ES	1st Floor, Adjacent to Room 111	< 1		
Nalle ES	1st Floor, Adjacent to Room 111	< 1		
Nalle ES	1st Floor, Across from Room 106	< 1		
Nalle ES	1st Floor, Across from Room 106	< 1		
Nalle ES	Basement Floor, Across from Room 6	< 1		
Nalle ES	Basement Floor, Across from Room 6	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (1)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (1)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (2)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (2)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Noyes ES	1st Floor, Inside Classroom 129	1.6		
Noyes ES	1st Floor, Inside Classroom 129	8.6		
Noyes ES	1st Floor, Inside Classroom 131	< 1		
Noyes ES	1st Floor, Inside Classroom 131	< 1		
Noyes ES	1st Floor, Inside Classroom 128	< 1		
Noyes ES	1st Floor, Inside Classroom 128	< 1		
Noyes ES	1st Floor, Inside Classroom 130	< 1		
Noyes ES	1st Floor, Inside Classroom 130	< 1		
Noyes ES	1st Floor, Inside Classroom 133	< 1		
Noyes ES	1st Floor, Inside Classroom 133	< 1		
Noyes ES	1st Floor, Inside Classroom 135	< 1		
Noyes ES	1st Floor, Inside Classroom 135	< 1		
Noyes ES	1st Floor, Inside Classroom 132	< 1		
Noyes ES	1st Floor, Inside Classroom 132	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Noyes ES	1st Floor, Inside Classroom 134	< 1		
Noyes ES	1st Floor, Inside Classroom 134	< 1		
Noyes ES	1st Floor, Inside Classroom 112	< 1		
Noyes ES	1st Floor, Inside Classroom 112	< 1		
Noyes ES	1st Floor, Outside Gymnasium (Tall)	< 1		
Noyes ES	1st Floor, Outside Gymnasium (Tall)	< 1		
Noyes ES	1st Floor, Outside Gymnasium (Short)	< 1		
Noyes ES	1st Floor, Outside Gymnasium (Short)	< 1		
Noyes ES	1st Floor, Outside Auditorium (Tall)	< 1		
Noyes ES	1st Floor, Outside Auditorium (Tall)	< 1		
Noyes ES	1st Floor, Outside Auditorium (Short)	< 1		
Noyes ES	1st Floor, Outside Auditorium (Short)	< 1		
Noyes ES	1st Floor, Across from Room 106 (Tall)	< 1		
Noyes ES	1st Floor, Across from Room 106 (Tall)	< 1		
Noyes ES	1st Floor, Across from Room 106 (Short)	< 1		
Noyes ES	1st Floor, Across from Room 106 (Short)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to Room 202 (Tall)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to Room 202 (Tall)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to Room 202 (Short)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to Room 202 (Short)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to elevator (Tall)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to elevator (Tall)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to elevator (Short)	< 1		
Noyes ES	2nd Floor Hallway, Adjacent to elevator (Short)	< 1		
Noyes ES	2nd Floor, Inside Classroom 203	< 1		
Noyes ES	2nd Floor, Inside Classroom 203	< 1		
Noyes ES	2nd Floor, Inside Classroom 204	< 1		
Noyes ES	2nd Floor, Inside Classroom 204	< 1		
Noyes ES	2nd Floor, Inside Classroom 205	< 1		
Noyes ES	2nd Floor, Inside Classroom 205	< 1		
Noyes ES	2nd Floor, Inside Classroom 206	< 1		
Noyes ES	2nd Floor, Inside Classroom 206	< 1		
Noyes ES	2nd Floor, Inside Classroom 212	< 1		
Noyes ES	2nd Floor, Inside Classroom 212	< 1		
Noyes ES	2nd Floor, Inside Classroom 213	< 1		
Noyes ES	2nd Floor, Inside Classroom 213	< 1		
Noyes ES	2nd Floor, Inside Classroom 214	< 1		
Noyes ES	2nd Floor, Inside Classroom 214	< 1		
Noyes ES	2nd Floor, Inside Classroom 216	< 1		
Noyes ES	2nd Floor, Inside Classroom 216	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.4		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.8		
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Outside Resource Room	< 1		
Orr ES	1st Floor, Outside Resource Room	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Oyster ES	1st Floor, Inside Room 107	< 1		
Oyster ES	1st Floor, Inside Room 107	< 1		
Oyster ES	1st Floor Hallway (Low)	< 1		
Oyster ES	1st Floor Hallway (Low)	< 1		
Oyster ES	1st Floor Hallway (High)	< 1		
Oyster ES	1st Floor Hallway (High)	< 1		
Oyster ES	2nd Floor, Inside Room 201	< 1		
Oyster ES	2nd Floor, Inside Room 201	< 1		
Oyster ES	2nd Floor, Inside Room 202	< 1		
Oyster ES	2nd Floor, Inside Room 202	< 1		
Oyster ES	2nd Floor, Inside Room 210	< 1		
Oyster ES	2nd Floor, Inside Room 210	< 1		
Oyster ES	2nd Floor, Inside Room 211	< 1		
Oyster ES	2nd Floor, Inside Room 211	< 1		
Oyster ES	2nd Floor, Gymnasium (Low)	< 1		
Oyster ES	2nd Floor, Gymnasium (Low)	< 1		
Oyster ES	2nd Floor, Gymnasium (High)	< 1		
Oyster ES	2nd Floor, Gymnasium (High)	< 1		
Oyster ES	3rd Floor, Inside Room 301	< 1		
Oyster ES	3rd Floor, Inside Room 301	< 1		
Oyster ES	3rd Floor, Inside Room 304	< 1		
Oyster ES	3rd Floor, Inside Room 304	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Oyster ES	3rd Floor, Inside Room 308	< 1		
Oyster ES	3rd Floor, Inside Room 308	< 1		
Oyster ES	3rd Floor, Inside Room 313	< 1		
Oyster ES	3rd Floor, Inside Room 313	< 1		
Oyster ES	3rd Floor Hallway (Low)	< 1		
Oyster ES	3rd Floor Hallway (Low)	< 1		
Oyster ES	3rd Floor Hallway (High)	< 1		
Oyster ES	3rd Floor Hallway (High)	< 1		
Oyster ES	3rd Floor, Inside Room 316	< 1		
Oyster ES	3rd Floor, Inside Room 316	< 1		
Oyster ES	4th Floor, Inside Room 401	< 1		
Oyster ES	4th Floor, Inside Room 401	< 1		
Oyster ES	4th Floor, Inside Room 405	< 1		
Oyster ES	4th Floor, Inside Room 405	< 1		
Oyster ES	4th Floor, Inside Room 407	< 1		
Oyster ES	4th Floor, Inside Room 407	< 1		
Oyster ES	4th Floor, Inside Room 410	< 1		
Oyster ES	4th Floor, Inside Room 410	< 1		
Oyster ES	4th Floor, Inside Room 412	< 1		
Oyster ES	4th Floor, Inside Room 412	< 1		
Oyster ES	4th Floor, Inside Room 415	< 1		
Oyster ES	4th Floor, Inside Room 415	< 1		
Oyster ES	4th Floor Hallway (Low)	< 1		
Oyster ES	4th Floor Hallway (Low)	< 1		
Oyster ES	4th Floor Hallway (High)	< 1		
Oyster ES	4th Floor Hallway (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Parkview ES	Basement Floor Hallway to Cafeteria	< 1		
Parkview ES	Basement Floor Hallway to Cafeteria	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 101	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 101	< 1		
Parkview ES	Basement Floor, Inside Room 103	< 1		
Parkview ES	Basement Floor, Inside Room 103	< 1		
Parkview ES	Basement Floor, Inside Room 102	< 1		
Parkview ES	Basement Floor, Inside Room 102	< 1		
Parkview ES	Basement Floor, Inside Room 101	< 1		
Parkview ES	Basement Floor, Inside Room 101	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 114	1.2		
Parkview ES	Basement Floor Hallway, Adjacent to Room 114	1.3		
Parkview ES	Basement Floor, Inside Room 114	< 1		
Parkview ES	Basement Floor, Inside Room 114	< 1		
Parkview ES	Basement Floor, Inside Room 113	< 1		
Parkview ES	Basement Floor, Inside Room 113	< 1		
Parkview ES	Basement Floor, Inside Room 112	< 1		
Parkview ES	Basement Floor, Inside Room 112	< 1		
Parkview ES	Basement Floor Hallway to Gymnasium	< 1		
Parkview ES	Basement Floor Hallway to Gymnasium	< 1		
Parkview ES	1st Floor Hallway, Across from Room 208	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Parkview ES	1st Floor Hallway, Across from Room 208	< 1		
Parkview ES	1st Floor, Inside Room 213	< 1		
Parkview ES	1st Floor, Inside Room 213	< 1		
Parkview ES	1st Floor, Inside Room 214	< 1		
Parkview ES	1st Floor, Inside Room 214	< 1		
Parkview ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Parkview ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Parkview ES	1st Floor Hallway, Across from Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Across from Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Inside Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Inside Teacher's Lounge 207	< 1		
Parkview ES	1st Floor, Inside Room 212	< 1		
Parkview ES	1st Floor, Inside Room 212	< 1		
Parkview ES	1st Floor, Inside Room 215	< 1		
Parkview ES	1st Floor, Inside Room 215	< 1		
Parkview ES	2nd Floor Hallway, Across from Library	< 1		
Parkview ES	2nd Floor Hallway, Across from Library	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 301	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 301	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 307	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 307	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Payne ES	1st Floor, Outside Library	< 1		
Payne ES	1st Floor, Outside Library	< 1		
Payne ES	1st Floor, Inside Cafeteria	< 1		
Payne ES	1st Floor, Inside Cafeteria	< 1		
Payne ES	1st Floor, Beside Nurse's Suite	< 1		
Payne ES	1st Floor, Beside Nurse's Suite	< 1		
Payne ES	1st Floor, Across from Room 133	< 1		
Payne ES	1st Floor, Across from Room 133	< 1		
Payne ES	2nd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	2nd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	2nd Floor, Beside Room 212	< 1		
Payne ES	2nd Floor, Beside Room 212	< 1		
Payne ES	2nd Floor, Beside Room 224	< 1		
Payne ES	2nd Floor, Beside Room 224	< 1		
Payne ES	3rd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	3rd Floor, Adjacent to Women's Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Peabody ES	1st Floor Outside Main Office	< 1		
Peabody ES	1st Floor Outside Main Office	< 1		
Peabody ES	2nd Floor, Adjacent to Room 6	< 1		
Peabody ES	2nd Floor, Adjacent to Room 6	< 1		
Peabody ES	3rd Floor Outside Room 10	< 1		
Peabody ES	3rd Floor Outside Room 10	< 1		
Peabody ES	4th Floor, Open Space, Sink #1	< 1		
Peabody ES	4th Floor, Open Space, Sink #1	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Peabody ES	4th Floor, Open Space, Sink #2	3.4		
Peabody ES	4th Floor, Open Space, Sink #2	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Plummer ES	3rd Floor Hallway, Across from Room 212	< 1		
Plummer ES	3rd Floor Hallway, Across from Room 212	< 1		
Plummer ES	3rd Floor Hallway, Across from Room 216	< 1		
Plummer ES	3rd Floor Hallway, Across from Room 216	< 1		
Plummer ES	3rd Floor Hallway, Across from Room 217	< 1		
Plummer ES	3rd Floor Hallway, Across from Room 217	< 1		
Plummer ES	3rd Floor Hallway, Adjacent to Room 219	< 1		
Plummer ES	3rd Floor Hallway, Adjacent to Room 219	< 1		
Plummer ES	2nd Floor, Inside Cafeteria	< 1		
Plummer ES	2nd Floor, Inside Cafeteria	< 1		
Plummer ES	2nd Floor, Inside Room 109	< 1		
Plummer ES	2nd Floor, Inside Room 109	< 1		
Plummer ES	2nd Floor Hallway, Adjacent to Room 132	< 1		
Plummer ES	2nd Floor Hallway, Adjacent to Room 132	< 1		
Plummer ES	2nd Floor Hallway, Across from Room 129	< 1		
Plummer ES	2nd Floor Hallway, Across from Room 129	< 1		
Plummer ES	2nd Floor Hallway, Adjacent to Room 127	< 1		
Plummer ES	2nd Floor Hallway, Adjacent to Room 127	< 1		
Plummer ES	2nd Floor Hallway, Across from Library	< 1		
Plummer ES	2nd Floor Hallway, Across from Library	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Room 34	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Room 34	< 1		
Plummer ES	1st Floor Hallway, Across from Room 37	< 1		
Plummer ES	1st Floor Hallway, Across from Room 37	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Room 39	< 1		
Plummer ES	1st Floor Hallway, Adjacent to Room 39	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Powell ES	2nd Floor Hallway	< 1		
Powell ES	2nd Floor Hallway	1.2		
Powell ES	2nd Floor, Adjacent to Classroom 219	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 219	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 203	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 203	< 1		
Powell ES	1st Floor, Adjacent to Classroom 114	< 1		
Powell ES	1st Floor, Adjacent to Classroom 114	< 1		
Powell ES	1st Floor, Adjacent to Classroom 108	< 1		
Powell ES	1st Floor, Adjacent to Classroom 108	< 1		
Powell ES	1st Floor, Adjacent to Classroom 109	< 1		
Powell ES	1st Floor, Adjacent to Classroom 109	< 1		
Powell ES	1st Floor, Adjacent to Classroom 103	< 1		
Powell ES	1st Floor, Adjacent to Classroom 103	< 1		
Powell ES	1st Floor, Inside Lunch Room	< 1		
Powell ES	1st Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Prospect LC	4th Floor Hallway, Between Rooms 401 & 403	< 1		
Prospect LC	4th Floor Hallway, Between Rooms 401 & 403	< 1		
Prospect LC	4th Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	4th Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	3rd Floor Hallway, Between Rooms 301 & 303	< 1		
Prospect LC	3rd Floor Hallway, Between Rooms 301 & 303	1.3		
Prospect LC	3rd Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	3rd Floor Hallway, Between Boys and Girls Restroom	3.7		
Prospect LC	2nd Floor Hallway, Between Rooms 201 & 203	< 1		
Prospect LC	2nd Floor Hallway, Between Rooms 201 & 203	< 1		
Prospect LC	2nd Floor Hallway, Between Boys and Girls Restroom	1.6		
Prospect LC	2nd Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	1st Floor Hallway, Between Rooms 101 & 103	< 1		
Prospect LC	1st Floor Hallway, Between Rooms 101 & 103	< 1		
Prospect LC	1st Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	1st Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	Ground Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	Ground Floor Hallway, Between Boys and Girls Restroom	< 1		
Prospect LC	Ground Floor, Inside Cafeteria	2.1		
Prospect LC	Ground Floor, Inside Cafeteria	2.2		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Randle Highlands ES	2nd Floor Hallway, Between Restroom and Custodial Closet (Up)	< 1		
Randle Highlands ES	2nd Floor Hallway, Between Restroom and Custodial Closet (Up)	< 1		
Randle Highlands ES	2nd Floor Hallway, Between Restroom and Custodial Closet (Down)	< 1		
Randle Highlands ES	2nd Floor Hallway, Between Restroom and Custodial Closet (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2211 & 2209 (Up)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2211 & 2209 (Up)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2211 & 2209 (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2211 & 2209 (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2206 & 2204 (Up)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2206 & 2204 (Up)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2206 & 2204 (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2206 & 2204 (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2201 & 2203 (Up)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2201 & 2203 (Up)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2201 & 2203 (Down)	< 1		
Randle Highlands ES	2nd Floor, Inside Classrooms, Between 2201 & 2203 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2111 & 2109 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2111 & 2109 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2111 & 2109 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2111 & 2109 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2106 & 2104 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2106 & 2104 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2106 & 2104 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2106 & 2104 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2103 & 2101 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2103 & 2101 (Up)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2103 & 2101 (Down)	< 1		
Randle Highlands ES	1st Floor, Inside Classrooms, Between 2103 & 2101 (Down)	< 1		
Randle Highlands ES	1st Floor Hallway, Outside Library Restroom (Up)	< 1		
Randle Highlands ES	1st Floor Hallway, Outside Library Restroom (Up)	< 1		
Randle Highlands ES	1st Floor Hallway, Outside Library Restroom (Down)	< 1		
Randle Highlands ES	1st Floor Hallway, Outside Library Restroom (Down)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Randle Highlands ES	Ground Floor, Inside Rooms 2011 & 2009 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2011 & 2009 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2011 & 2009 (Down)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2011 & 2009 (Down)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2006 & 2004 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2006 & 2004 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2006 & 2004 (Down)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2006 & 2004 (Down)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2003 & 2001 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2003 & 2001 (Up)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2003 & 2001 (Down)	< 1		
Randle Highlands ES	Ground Floor, Inside Rooms 2003 & 2001 (Down)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Elevator (Up)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Elevator (Up)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Elevator (Down)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Elevator (Down)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Music Room (Up)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Music Room (Up)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Music Room (Down)	< 1		
Randle Highlands ES	Ground Floor Hallway, Outside Music Room (Down)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B09 & 2B11 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B09 & 2B11 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B09 & 2B11 (Down)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B09 & 2B11 (Down)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B06 & 2B04 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B06 & 2B04 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B06 & 2B04 (Down)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Randle Highlands ES	Basement Floor, Inside Rooms 2B06 & 2B04 (Down)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B03 & 2B01 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B03 & 2B01 (Up)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B03 & 2B01 (Down)	< 1		
Randle Highlands ES	Basement Floor, Inside Rooms 2B03 & 2B01 (Down)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 117	1.2		
Raymond ES	1st Floor, Inside Room 117	1.9		
Raymond ES	1st Floor, Inside Room 113	< 1		
Raymond ES	1st Floor, Inside Room 113	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
River Terrace ES	Hallway Outside Air Quality Room	< 1		
River Terrace ES	Hallway Outside Air Quality Room	< 1		
River Terrace ES	Hallway Outside Teacher's Restroom	< 1		
River Terrace ES	Hallway Outside Teacher's Restroom	< 1		
River Terrace ES	Hallway Outside Room 24	< 1		
River Terrace ES	Hallway Outside Room 24	< 1		
River Terrace ES	Hallway Outside Main Office	< 1		
River Terrace ES	Hallway Outside Main Office	< 1		
River Terrace ES	Hallway Outside Boys Restroom	< 1		
River Terrace ES	Hallway Outside Boys Restroom	< 1		
River Terrace ES	Inside Room 14	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
River Terrace ES	Inside Room 14	< 1		
River Terrace ES	Inside Room 15/16 (High)	< 1		
River Terrace ES	Inside Room 15/16 (High)	< 1		
River Terrace ES	Inside Room 15/16 (Low)	< 1		
River Terrace ES	Inside Room 15/16 (Low)	< 1		
River Terrace ES	Hallway Outside Room 19	< 1		
River Terrace ES	Hallway Outside Room 19	< 1		
River Terrace ES	Inside Lunch Room (High)	< 1		
River Terrace ES	Inside Lunch Room (High)	< 1		
River Terrace ES	Inside Nurse's Suite (High)	< 1		
River Terrace ES	Inside Nurse's Suite (High)	< 1		
River Terrace ES	Inside Nurse's Suite (Low)	< 1		
River Terrace ES	Inside Nurse's Suite (Low)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ron Brown MS	1st Floor, Inside Cafeteria Wall A	< 1		
Ron Brown MS	1st Floor, Inside Cafeteria Wall A	< 1		
Ron Brown MS	1st Floor, Inside Cafeteria Wall C	< 1		
Ron Brown MS	1st Floor, Inside Cafeteria Wall C	< 1		
Ron Brown MS	1st Floor, Inside Multi-Purpose Room, Wall C	< 1		
Ron Brown MS	1st Floor, Inside Multi-Purpose Room, Wall C	< 1		
Ron Brown MS	1st Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from SE Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from SE Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from NE Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from NE Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from NW Stairs	< 1		
Ron Brown MS	1st Floor Hallway, Across from NW Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Outside Gymnasium	< 1		
Ron Brown MS	2nd Floor Hallway, Outside Gymnasium	< 1		
Ron Brown MS	2nd Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Across from SE Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Across from SE Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Across from NW Stairs	< 1		
Ron Brown MS	2nd Floor Hallway, Across from NW Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from SW Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from NE Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from NE Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from NW Stairs	< 1		
Ron Brown MS	3rd Floor Hallway, Across from NW Stairs	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ross ES	Outside Water Fountain	< 1		
Ross ES	Outside Water Fountain	< 1		
Ross ES	1st Floor, Inside Room 103	< 1		
Ross ES	1st Floor, Inside Room 103	< 1		
Ross ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Ross ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Ross ES	1st Floor Hallway, Adjacent to Room 101	< 1		
Ross ES	1st Floor Hallway, Adjacent to Room 101	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Ross ES	2nd Floor Hallway, Adjacent to Room 203	< 1		
Ross ES	2nd Floor Hallway, Adjacent to Room 203	< 1		
Ross ES	Basement Hallway, Across from Book Storage	< 1		
Ross ES	Basement Hallway, Across from Book Storage	< 1		
Ross ES	Basement Floor, Inside Cafeteria	< 1		
Ross ES	Basement Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Savoy ES	2nd Floor Hallway, Adjacent to Teacher's Lounge Room 203 (Up)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Teacher's Lounge Room 203 (Up)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Teacher's Lounge Room 203 (Down)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Teacher's Lounge Room 203 (Down)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Room 208 (Up)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Room 208 (Up)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Room 208 (Down)	< 1		
Savoy ES	2nd Floor Hallway, Adjacent to Room 208 (Down)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Bookstore (up)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Bookstore (up)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Bookstore (Down)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Bookstore (Down)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Room 206 (Up)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Room 206 (Up)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Room 206 (Down)	< 1		
Savoy ES	3rd Floor Hallway, Adjacent to Room 206 (Down)	< 1		
Savoy ES	2nd Floor, Inside Library (Up)	< 1		
Savoy ES	2nd Floor, Inside Library (Up)	< 1		
Savoy ES	2nd Floor, Inside Library (Down)	< 1		
Savoy ES	2nd Floor, Inside Library (Down)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 127 TMA Office/Gym (Up)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 127 TMA Office/Gym (Up)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 127 TMA Office/Gym (Down)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 127 TMA Office/Gym (Down)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 107 PE Office (Up)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 107 PE Office (Up)	< 1		
Savoy ES	1st Floor Hallway, Adjacent to Room 107 PE Office (Down)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Savoy ES	1st Floor Hallway, Adjacent to Room 107 PE Office (Down)	< 1		
Savoy ES	1st Floor Hallway, Between Girls/Boys Restroom (Up)	< 1		
Savoy ES	1st Floor Hallway, Between Girls/Boys Restroom (Up)	< 1		
Savoy ES	1st Floor Hallway, Between Girls/Boys Restroom (Down)	< 1		
Savoy ES	1st Floor Hallway, Between Girls/Boys Restroom (Down)	< 1		
Savoy ES	1st Floor, Inside Classroom 109	< 1		
Savoy ES	1st Floor, Inside Classroom 109	< 1		
Savoy ES	1st Floor, Inside Classroom 111	< 1		
Savoy ES	1st Floor, Inside Classroom 111	< 1		
Savoy ES	1st Floor, Inside Classroom 113	< 1		
Savoy ES	1st Floor, Inside Classroom 113	< 1		
Savoy ES	1st Floor, Inside Classroom 122	2.6		
Savoy ES	1st Floor, Inside Classroom 122	< 1		
Savoy ES	1st Floor, Inside Classroom 120	< 1		
Savoy ES	1st Floor, Inside Classroom 120	< 1		
Savoy ES	1st Floor, Inside Classroom 115	< 1		
Savoy ES	1st Floor, Inside Classroom 115	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Seaton ES	3rd Floor, Adjacent to the Bathroom	2		
Seaton ES	3rd Floor, Adjacent to the Bathroom	< 1		
Seaton ES	3rd Floor, Inside Room 309	< 1		
Seaton ES	3rd Floor, Inside Room 309	< 1		
Seaton ES	3rd Floor, Inside Room 307	< 1		
Seaton ES	3rd Floor, Inside Room 307	< 1		
Seaton ES	2nd Floor, Inside Room 206	< 1		
Seaton ES	2nd Floor, Inside Room 206	< 1		
Seaton ES	2nd Floor, Adjacent to Room 206	< 1		
Seaton ES	2nd Floor, Adjacent to Room 206	< 1		
Seaton ES	1st Floor, Inside Room 111	< 1		
Seaton ES	1st Floor, Inside Room 111	< 1		
Seaton ES	1st Floor, Adjacent to Room 106	1.8		
Seaton ES	1st Floor, Adjacent to Room 106	< 1		
Seaton ES	1st Floor, Adjacent to Room 106	2.7		
Seaton ES	1st Floor, Adjacent to Room 106	< 1		
Seaton ES	1st Floor, Inside Room 109	< 1		
Seaton ES	1st Floor, Inside Room 109	< 1		
Seaton ES	1st Floor, Inside Room 122	1.2		
Seaton ES	1st Floor, Inside Room 122	1.5		
Seaton ES	1st Floor, Inside Room 124	6.9		
Seaton ES	1st Floor, Inside Room 124	10		
Seaton ES	1st Floor, Inside Room 127	2.7		
Seaton ES	1st Floor, Inside Room 127	1.1		
Seaton ES	1st Floor, Inside Room 125	1.2		
Seaton ES	1st Floor, Inside Room 125	< 1		
Seaton ES	1st Floor, Inside Lunch Room	< 1		
Seaton ES	1st Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Percentage of Failed Samples				0.00%
Shadd ES	1st Floor, Adjacent to Auditorium	< 1		
Shadd ES	1st Floor, Adjacent to Auditorium	< 1		
Shadd ES	1st Floor, Adjacent to Main Office	< 1		
Shadd ES	1st Floor, Adjacent to Main Office	< 1		
Shadd ES	1st Floor, Adjacent to Library	< 1		
Shadd ES	1st Floor, Adjacent to Library	< 1		
Shadd ES	Basement Floor, Adjacent to Music Room	< 1		
Shadd ES	Basement Floor, Adjacent to Music Room	< 1		
Shadd ES	Basement Floor, Adjacent to Cafeteria	< 1		
Shadd ES	Basement Floor, Adjacent to Cafeteria	< 1		
Shadd ES	2nd Floor, Adjacent to Room 211	< 1		
Shadd ES	2nd Floor, Adjacent to Room 211	< 1		
Shadd ES	2nd Floor, Adjacent to Room 211	< 1		
Shadd ES	2nd Floor, Adjacent to Room 211	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Sharpe Health School	1st Floor Hallway, Outside Kindergarten Room	< 1		
Sharpe Health School	1st Floor Hallway, Outside Kindergarten Room	< 1		
Sharpe Health School	1st Floor Hallway, Outside Tube Feeding Room	< 1		
Sharpe Health School	1st Floor Hallway, Outside Tube Feeding Room	< 1		
Sharpe Health School	1st Floor Hallway, Outside Men's Locker Room	6.9		
Sharpe Health School	1st Floor Hallway, Outside Men's Locker Room	9.1		
Sharpe Health School	1st Floor Hallway, Outside Room 108	< 1		
Sharpe Health School	1st Floor Hallway, Outside Room 108	< 1		
Sharpe Health School	1st Floor Hallway, Outside Dining Room	< 1		
Sharpe Health School	1st Floor Hallway, Outside Dining Room	< 1		
Sharpe Health School	2nd Floor, Outside Room 207	< 1		
Sharpe Health School	2nd Floor, Outside Room 207	< 1		
Sharpe Health School	2nd Floor, Outside Unisex Toilet	< 1		
Sharpe Health School	2nd Floor, Outside Unisex Toilet	< 1		
Sharpe Health School	2nd Floor, Outside Book Room	< 1		
Sharpe Health School	2nd Floor, Outside Book Room	< 1		
Sharpe Health School	Annex Hallway, Outside Room 212	< 1		
Sharpe Health School	Annex Hallway, Outside Room 212	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Shepherd ES	1st Floor, Inside Room 132	< 1		
Shepherd ES	1st Floor, Inside Room 132	< 1		
Shepherd ES	1st Floor, Inside Room 101	< 1		
Shepherd ES	1st Floor, Inside Room 101	< 1		
Shepherd ES	1st Floor, Inside Lunch Room	< 1		
Shepherd ES	1st Floor, Inside Lunch Room	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 214	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 214	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 220	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 220	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Counselor's	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Counselor's	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 122	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 122	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 204	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Shepherd ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 100	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 100	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Simon ES	Ground Floor, Inside Room 1	< 1		
Simon ES	Ground Floor, Inside Room 2	< 1		
Simon ES	Ground Floor, Adjacent to Room 3	< 1		
Simon ES	Ground Floor, Adjacent to Room 3	< 1		
Simon ES	Ground Floor, Adjacent to Room 13	< 1		
Simon ES	Ground Floor, Adjacent to Room 13	< 1		
Simon ES	Ground Floor, Inside Room 15	< 1		
Simon ES	Ground Floor, Inside Room 15	< 1		
Simon ES	1st Floor Lobby, Inside Main Office	< 1		
Simon ES	1st Floor Lobby, Inside Main Office	< 1		
Simon ES	1st Floor, Inside Room 107	< 1		
Simon ES	1st Floor, Inside Room 107	1.7		
Simon ES	1st Floor, Outside Girls Restroom	< 1		
Simon ES	1st Floor, Outside Girls Restroom	< 1		
Simon ES	1st Floor, Outside Boys Restroom	< 1		
Simon ES	1st Floor, Outside Boys Restroom	< 1		
Simon ES	2nd Floor, Adjacent to Room 203	< 1		
Simon ES	2nd Floor, Adjacent to Room 203	< 1		
Simon ES	2nd Floor, Adjacent to Room 213	< 1		
Simon ES	2nd Floor, Adjacent to Room 213	< 1		
Simon ES	3rd Floor, Adjacent to Room 303	< 1		
Simon ES	3rd Floor, Adjacent to Room 303	< 1		
Simon ES	3rd Floor, Adjacent to Room 313	< 1		
Simon ES	3rd Floor, Adjacent to Room 313	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Smothers ES	3rd Floor, Adjacent to Classroom 301	< 1		
Smothers ES	3rd Floor, Adjacent to Classroom 301	< 1		
Smothers ES	3rd Floor, Adjacent to Classroom 310	< 1		
Smothers ES	3rd Floor, Adjacent to Classroom 310	< 1		
Smothers ES	2nd Floor, Adjacent to Classroom 201	< 1		
Smothers ES	2nd Floor, Adjacent to Classroom 201	< 1		
Smothers ES	2nd Floor, Adjacent to Classroom 212	< 1		
Smothers ES	2nd Floor, Adjacent to Classroom 212	< 1		
Smothers ES	1st Floor, Adjacent to Classroom 108	< 1		
Smothers ES	1st Floor, Adjacent to Classroom 108	< 1		
Smothers ES	1st Floor, Adjacent to Classroom 104	< 1		
Smothers ES	1st Floor, Adjacent to Classroom 104	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (Low)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	1st Floor, Left of Stage (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Room B104 1	2.2		
Sousa ES	1st Floor, Inside Room B104 1	< 1		
Sousa ES	1st Floor, Inside Room B104 2	1.1		
Sousa ES	1st Floor, Inside Room B104 2	< 1		
Sousa ES	1st Floor, Inside Room B104 3	5.8		
Sousa ES	1st Floor, Inside Room B104 3	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 5	2.2		
Sousa ES	1st Floor, Inside Room B104 5	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B109 1	1.3		
Sousa ES	1st Floor, Inside Room B109 1	< 1		
Sousa ES	1st Floor, Inside Room B109 2	3.5		
Sousa ES	1st Floor, Inside Room B109 2	2.1		
Sousa ES	1st Floor, Inside Room B109 3	8.7		
Sousa ES	1st Floor, Inside Room B109 3	< 1		
Sousa ES	1st Floor, Inside Room B109 4	1.3		
Sousa ES	1st Floor, Inside Room B109 4	< 1		
Sousa ES	1st Floor, Inside Room B109 5	2.4		
Sousa ES	1st Floor, Inside Room B109 5	< 1		
Sousa ES	1st Floor, Inside Room B109 6	9.7		
Sousa ES	1st Floor, Inside Room B109 6	1.8		
Sousa ES	2nd Floor, Inside Room A209 1	1.2		
Sousa ES	2nd Floor, Inside Room A209 1	< 1		
Sousa ES	2nd Floor, Inside Room A209 2	< 1		
Sousa ES	2nd Floor, Inside Room A209 2	4.1		
Sousa ES	2nd Floor, Inside Room A209 3	1.3		
Sousa ES	2nd Floor, Inside Room A209 3	< 1		
Sousa ES	2nd Floor, Inside Room A209 4	2.2		
Sousa ES	2nd Floor, Inside Room A209 4	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	2nd Floor, Inside Room A209 6	1.4		
Sousa ES	2nd Floor, Inside Room A209 6	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 3	2.2		
Sousa ES	2nd Floor, Inside Room B204 3	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 6	1.9		
Sousa ES	2nd Floor, Inside Room B204 6	1.3		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	1.1		
Sousa ES	3rd Floor, Inside Room B304 3	< 1		
Sousa ES	3rd Floor, Inside Room B304 3	2.3		
Sousa ES	3rd Floor, Inside Room B304 4	2.2		
Sousa ES	3rd Floor, Inside Room B304 4	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B904 1	9		
Sousa ES	3rd Floor, Inside Room B904 1		22	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	3rd Floor, Inside Room B904 2		24	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 2 - Retest</i>	1.5		
Sousa ES	<i>3rd Floor, Inside Room B904 2 - Retest</i>	< 1		
Sousa ES	3rd Floor, Inside Room B904 2	5.7		
Sousa ES	3rd Floor, Inside Room B904 3	3.2		
Sousa ES	3rd Floor, Inside Room B904 3	< 1		
Sousa ES	3rd Floor, Inside Room B904 4	6.8		
Sousa ES	3rd Floor, Inside Room B904 4	< 1		
Sousa ES	3rd Floor, Inside Room B904 5	2.5		
Sousa ES	3rd Floor, Inside Room B904 5	< 1		
Sousa ES	3rd Floor, Inside Room B904 6	7.5		
Sousa ES	3rd Floor, Inside Room B904 6	< 1		
Percentage of Passed Samples				97.96%
Percentage of Failed Samples				2.04%
Stanton ES	3rd Floor, Adjacent to Classroom 308	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 308	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 313	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 313	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 307	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 307	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 209	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 209	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 204	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Stanton ES	2nd Floor, Adjacent to Classroom 204	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 210	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 210	< 1		
Stanton ES	1st Floor, Adjacent to the Bathroom	< 1		
Stanton ES	1st Floor, Adjacent to the Bathroom	< 1		
Stanton ES	1st Floor, Adjacent to Classroom 106	< 1		
Stanton ES	1st Floor, Adjacent to Classroom 106	< 1		
Stanton ES	1st Floor, Adjacent to Main Entrance	< 1		
Stanton ES	1st Floor, Adjacent to Main Entrance	< 1		
Stanton ES	Ground Floor, Inside Lunch Room	< 1		
Stanton ES	Ground Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Stoddert ES	1st Floor, Across from Cafeteria (Tall)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Tall)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Short)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Short)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Tall)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Tall)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Short)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Short)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 2)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 2)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 3)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 3)	< 1		
Stoddert ES	2nd Floor, Inside Room 244 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 244 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 245 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 245 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 246 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 246 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 247 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 247 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 231 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 231 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 232 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 232 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 233 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 233 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 234 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 234 (Sink1)	< 1		
Stoddert ES	1st Floor, Inside Room 134 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 134 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 133 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 133 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 132 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 132 (Sink 1)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Stoddert ES	1st Floor, Inside Room 131 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 131 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 146 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 146 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 145 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 145 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 147 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 147 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 144 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 144 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 142 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 142 (Sink 1)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Stuart Hobson MS	3rd Floor, Adjacent to Bathroom	< 1		
Stuart Hobson MS	3rd Floor, Adjacent to Bathroom	< 1		
Stuart Hobson MS	3rd Floor, Adjacent to Classroom 304	< 1		
Stuart Hobson MS	3rd Floor, Adjacent to Classroom 304	< 1		
Stuart Hobson MS	2nd Floor, Adjacent to Classroom 204	< 1		
Stuart Hobson MS	2nd Floor, Adjacent to Classroom 204	< 1		
Stuart Hobson MS	2nd Floor, Adjacent to Classroom 201B	< 1		
Stuart Hobson MS	2nd Floor, Adjacent to Classroom 201B	< 1		
Stuart Hobson MS	1st Floor, Adjacent to Main Office	< 1		
Stuart Hobson MS	1st Floor, Adjacent to Main Office	< 1		
Stuart Hobson MS	1st Floor, Adjacent to Classroom 104	< 1		
Stuart Hobson MS	1st Floor, Adjacent to Classroom 104	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Exit	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Exit	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Gymnasium Boys Locker Room	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Gymnasium Boys Locker Room	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Gymnasium Girls Locker Room	< 1		
Stuart Hobson MS	Ground Floor, Adjacent to Gymnasium Girls Locker Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Takoma ES	Ground Floor, Inside Gymnasium, Adjacent to Room G107	< 1		
Takoma ES	Ground Floor, Inside Gymnasium, Adjacent to Room G107	< 1		
Takoma ES	Ground Floor, Inside Gymnasium, Adjacent to Room G115	< 1		
Takoma ES	Ground Floor, Inside Gymnasium, Adjacent to Room G115	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Room 327 (Tall)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Room 327 (Tall)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Room 327 (Short)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Takoma ES	3rd Floor Hallway, Adjacent to Room 327 (Short)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Elevator (Tall)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Elevator (Tall)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Elevator (Short)	< 1		
Takoma ES	3rd Floor Hallway, Adjacent to Elevator (Short)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Elevator (Tall)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Elevator (Tall)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Elevator (Short)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Elevator (Short)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Room 234 (Tall)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Room 234 (Tall)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Room 234 (Short)	< 1		
Takoma ES	2nd Floor Hallway, Adjacent to Room 234 (Short)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 133 (Tall)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 133 (Tall)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 133 (Short)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 133 (Short)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 141 (Tall)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 141 (Tall)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 141 (Short)	< 1		
Takoma ES	1st Floor Hallway, Adjacent to Room 141 (Short)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Thomson ES	3rd Floor, Adjacent to the Elevator (Left Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Left Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Right Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Right Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Left Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Left Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Right Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Right Side)	< 1		
Thomson ES	1st Floor, Inside Room 130	< 1		
Thomson ES	1st Floor, Inside Room 130	< 1		
Thomson ES	1st Floor, Inside Room 129	< 1		
Thomson ES	1st Floor, Inside Room 129	< 1		
Thomson ES	1st Floor, Inside Room 124	< 1		
Thomson ES	1st Floor, Inside Room 124	< 1		
Thomson ES	1st Floor, Inside Room 123	< 1		
Thomson ES	1st Floor, Inside Room 123	< 1		
Thomson ES	1st Floor, Inside Room 127	< 1		
Thomson ES	1st Floor, Inside Room 127	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Thomson ES	1st Floor, Inside Room 125	< 1		
Thomson ES	1st Floor, Inside Room 125	< 1		
Thomson ES	1st Floor, Inside Room 113	< 1		
Thomson ES	1st Floor, Inside Room 113	< 1		
Thomson ES	1st Floor, Inside Room 112	< 1		
Thomson ES	1st Floor, Inside Room 112	< 1		
Thomson ES	1st Floor, Inside Room 114	< 1		
Thomson ES	1st Floor, Inside Room 114	< 1		
Thomson ES	1st Floor, Inside Room 115	< 1		
Thomson ES	1st Floor, Inside Room 115	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Left Side)	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Left Side)	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Right Side)	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Right Side)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Truesdell ES	3rd Floor Hallway, Outside Room 300	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 300	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 308	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 308	< 1		
Truesdell ES	2nd Floor, Inside Room 217	< 1		
Truesdell ES	2nd Floor, Inside Room 217	< 1		
Truesdell ES	2nd Floor, Inside Room 216	< 1		
Truesdell ES	2nd Floor, Inside Room 216	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 212	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 212	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 200	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 200	< 1		
Truesdell ES	2nd Floor, Inside Room 201	3.1		
Truesdell ES	2nd Floor, Inside Room 201	2.8		
Truesdell ES	2nd Floor, Inside Room 200	12		
Truesdell ES	2nd Floor, Inside Room 200	1.4		
Truesdell ES	1st Floor, Inside Room 115	< 1		
Truesdell ES	1st Floor, Inside Room 115	< 1		
Truesdell ES	1st Floor, Inside Room 114	< 1		
Truesdell ES	1st Floor, Inside Room 114	< 1		
Truesdell ES	1st Floor Hallway, Outside Room 104	< 1		
Truesdell ES	1st Floor Hallway, Outside Room 104	< 1		
Truesdell ES	1st Floor, Outside Girls/Boys Restroom	< 1		
Truesdell ES	1st Floor, Outside Girls/Boys Restroom	< 1		
Truesdell ES	1st Floor, Inside Multi-Purpose Room	< 1		
Truesdell ES	1st Floor, Inside Multi-Purpose Room	< 1		
Truesdell ES	1st Floor, Inside Room 100	< 1		
Truesdell ES	1st Floor, Inside Room 100	< 1		
Truesdell ES	1st Floor, Inside Room 101	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Truesdell ES	1st Floor, Inside Room 101	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 218	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 218	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 227	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 227	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 126	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 126	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 117	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 117	< 1		
Truesdell ES	Annex, Basement, Inside Nurse's Suite	< 1		
Truesdell ES	Annex, Basement, Inside Nurse's Suite	1.1		
Truesdell ES	Annex, Basement Hallway, Outside Room 013	< 1		
Truesdell ES	Annex, Basement Hallway, Outside Room 013	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Tyler ES	3rd Floor Hallway, Adjacent to Room 303	< 1		
Tyler ES	3rd Floor Hallway, Adjacent to Room 303	< 1		
Tyler ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tyler ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tyler ES	2nd Floor Hallway, Adjacent to Room 202	< 1		
Tyler ES	2nd Floor Hallway, Adjacent to Room 202	< 1		
Tyler ES	2nd Floor Hallway, Adjacent to Room 211	< 1		
Tyler ES	2nd Floor Hallway, Adjacent to Room 211	< 1		
Tyler ES	1st Floor Hallway, Adjacent to Room 120 (Up)	< 1		
Tyler ES	1st Floor Hallway, Adjacent to Room 120 (Up)	< 1		
Tyler ES	1st Floor Hallway, Adjacent to Room 120 (Down)	< 1		
Tyler ES	1st Floor Hallway, Adjacent to Room 120 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 111 (Up)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 111 (Up)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 111 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 111 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 142 (Up)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 142 (Up)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 142 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 142 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 138 (Up))	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Tyler ES	1st Floor Hallway, Opposite to Room 138 (Up))	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 138 (Down)	< 1		
Tyler ES	1st Floor Hallway, Opposite to Room 138 (Down)	< 1		
Tyler ES	Basement, Inside Cafeteria	< 1		
Tyler ES	Basement, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Inside Room 032	4.2		
Walker Jones ES	Basement, Inside Room 032	< 1		
Walker Jones ES	Basement, Inside Room 031	1.8		
Walker Jones ES	Basement, Inside Room 031	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 105	1.1		
Walker Jones ES	1st Floor, Inside Room 105	< 1		
Walker Jones ES	1st Floor, Inside Room 106	3		
Walker Jones ES	1st Floor, Inside Room 106	< 1		
Walker Jones ES	1st Floor, Inside Room 108	1.2		
Walker Jones ES	1st Floor, Inside Room 108	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	1.7		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 119	13		
Walker Jones ES	1st Floor, Inside Room 119	2.4		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 123	1.6		
Walker Jones ES	1st Floor, Inside Room 123	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 128	2.9		
Walker Jones ES	1st Floor, Inside Room 128	< 1		
Walker Jones ES	2nd Floor, Inside Room 201	13		
Walker Jones ES	2nd Floor, Inside Room 201	2.4		
Walker Jones ES	2nd Floor, Inside Room 203	1.5		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	2nd Floor, Inside Room 203	< 1		
Walker Jones ES	2nd Floor, Inside Room 205	5.3		
Walker Jones ES	2nd Floor, Inside Room 205	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	1.3		
Walker Jones ES	2nd Floor, Inside Room 208	1.6		
Walker Jones ES	2nd Floor, Inside Room 208	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 212	3.6		
Walker Jones ES	2nd Floor, Inside Room 212	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	5.9		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	1.5		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	2.8		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	1.2		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 220	1.8		
Walker Jones ES	2nd Floor, Inside Room 220	< 1		
Walker Jones ES	2nd Floor, Inside Room 221	3		
Walker Jones ES	2nd Floor, Inside Room 221	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	2.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	11		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)		54	Lead filter was installed
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)	5.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.4		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.2		
Walker Jones ES	2nd Floor, Inside Room 228	5		
Walker Jones ES	2nd Floor, Inside Room 228	< 1		
Walker Jones ES	2nd Floor, Inside Room 230	3.5		
Walker Jones ES	2nd Floor, Inside Room 230	< 1		
Walker Jones ES	2nd Floor, Inside Main Office	5.8		
Walker Jones ES	2nd Floor, Inside Main Office	2.9		
Walker Jones ES	3rd Floor, Inside Room 300	1.6		
Walker Jones ES	3rd Floor, Inside Room 300	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 310		18	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	1.6		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2.2		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	1.9		
Walker Jones ES	3rd Floor, Adjacent to Room 310		42	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	2.9		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2.9		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2		
Walker Jones ES	3rd Floor, Adjacent to Room 310		59	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	6		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	3.7		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2.6		
Walker Jones ES	3rd Floor, Adjacent to Room 320		35	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	7.3		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320		16	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.7		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	1.1		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320	11		
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.6		
Walker Jones ES	3rd Floor, Adjacent to Room 324	4.2		
Walker Jones ES	3rd Floor, Adjacent to Room 324	1.4		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324		31	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 324	3.8		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 324 - Retest</i>	1.4		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 324 - Retest</i>	1.3		
Percentage of Passed Samples				93.75%
Percentage of Failed Samples				6.25%
Watkins ES	1st Floor Hallway, Adjacent to Recreation Center Office	< 1		
Watkins ES	1st Floor Hallway, Adjacent to Recreation Center Office	< 1		
Watkins ES	1st Floor Hallway, Across from Elevator	< 1		
Watkins ES	1st Floor Hallway, Across from Elevator	< 1		
Watkins ES	1st Floor Hallway, Across from Room 108	< 1		
Watkins ES	1st Floor Hallway, Across from Room 108	< 1		
Watkins ES	1st Floor Hallway, Adjacent to Room 112	< 1		
Watkins ES	1st Floor Hallway, Adjacent to Room 112	< 1		
Watkins ES	2nd Floor Hallway, Across from Elevator	< 1		
Watkins ES	2nd Floor Hallway, Across from Elevator	< 1		
Watkins ES	2nd Floor Hallway, Across from Room 203	< 1		
Watkins ES	2nd Floor Hallway, Across from Room 203	< 1		
Watkins ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Watkins ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Watkins ES	3rd Floor Hallway, Adjacent to Room 307	< 1		
Watkins ES	3rd Floor Hallway, Adjacent to Room 307	< 1		
Watkins ES	3rd Floor Hallway, Across from Room 303	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Watkins ES	3rd Floor Hallway, Across from Room 303	< 1		
Watkins ES	3rd Floor Hallway, Across from Elevator	< 1		
Watkins ES	3rd Floor Hallway, Across from Elevator	< 1		
Watkins ES	4th Floor Hallway, Across from Elevator	< 1		
Watkins ES	4th Floor Hallway, Across from Elevator	< 1		
Watkins ES	4th Floor Hallway, Across from Room 403	< 1		
Watkins ES	4th Floor Hallway, Across from Room 403	< 1		
Watkins ES	4th Floor Hallway, Adjacent to Room 407	< 1		
Watkins ES	4th Floor Hallway, Adjacent to Room 407	< 1		
Watkins ES	4th Floor, Ice Maker, Inside Room 400	< 1		
Watkins ES	4th Floor, Ice Maker, Inside Room 400	< 1		
Watkins ES	1st Floor, Inside Health Suite (Wall B)	3.5		
Watkins ES	1st Floor, Inside Health Suite (Wall B)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Wheatley ES	2nd Floor, Adjacent to Classroom 205 (High)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 205 (High)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 205 (Low)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 205 (Low)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 232 (High)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 232 (High)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 232 (Low)	< 1		
Wheatley ES	2nd Floor, Adjacent to Classroom 232 (Low)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 105 (High)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 105 (High)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 105 (Low)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 105 (Low)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 133 (High)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 133 (High)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 133 (Low)	< 1		
Wheatley ES	1st Floor, Adjacent to Classroom 133 (Low)	< 1		
Wheatley ES	1st Floor, Inside Classroom 131	< 1		
Wheatley ES	1st Floor, Inside Classroom 131	< 1		
Wheatley ES	1st Floor, Inside Classroom 128	< 1		
Wheatley ES	1st Floor, Inside Classroom 128	< 1		
Wheatley ES	1st Floor, Inside Classroom 125	< 1		
Wheatley ES	1st Floor, Inside Classroom 125	< 1		
Wheatley ES	1st Floor, Inside Classroom 107	< 1		
Wheatley ES	1st Floor, Inside Classroom 107	< 1		
Wheatley ES	1st Floor, Inside Classroom 135	< 1		
Wheatley ES	1st Floor, Inside Classroom 135	< 1		
Wheatley ES	1st Floor, Inside Classroom 115	< 1		
Wheatley ES	1st Floor, Inside Classroom 115	< 1		
Wheatley ES	1st Floor, Inside Classroom 114	< 1		
Wheatley ES	1st Floor, Inside Classroom 114	< 1		
Wheatley ES	1st Floor, Inside Classroom 113	< 1		
Wheatley ES	1st Floor, Inside Classroom 113	< 1		
Wheatley ES	1st Floor, Inside Classroom 111	< 1		
Wheatley ES	1st Floor, Inside Classroom 111	< 1		
Wheatley ES	1st Floor, Inside Classroom 103	< 1		
Wheatley ES	1st Floor, Inside Classroom 103	< 1		
Wheatley ES	Ground Floor, Inside Classroom 17 (High)	< 1		
Wheatley ES	Ground Floor, Inside Classroom 17 (High)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Wheatley ES	Ground Floor, Inside Classroom 17 (Low)	< 1		
Wheatley ES	Ground Floor, Inside Classroom 17 (Low)	< 1		
Wheatley ES	Ground Floor, Inside Classroom 05	< 1		
Wheatley ES	Ground Floor, Inside Classroom 05	< 1		
Wheatley ES	Ground Floor, Inside Classroom 08	< 1		
Wheatley ES	Ground Floor, Inside Classroom 08	< 1		
Wheatley ES	Ground Floor, Inside Classroom 31	< 1		
Wheatley ES	Ground Floor, Inside Classroom 31	< 1		
Wheatley ES	Ground Floor, Adjacent to Exit (High)	< 1		
Wheatley ES	Ground Floor, Adjacent to Exit (High)	< 1		
Wheatley ES	Ground Floor, Adjacent to Exit (Low)	< 1		
Wheatley ES	Ground Floor, Adjacent to Exit (Low)	< 1		
Wheatley ES	Ground Floor, Inside Classroom 59	< 1		
Wheatley ES	Ground Floor, Inside Classroom 59	< 1		
Wheatley ES	Ground Floor, Inside Classroom 57	< 1		
Wheatley ES	Ground Floor, Inside Classroom 57	< 1		
Wheatley ES	Ground Floor, Inside Classroom 51	< 1		
Wheatley ES	Ground Floor, Inside Classroom 51	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
West ES	1st Floor, Inside Computer Lab (Left)	< 1		
West ES	1st Floor, Inside Computer Lab (Left)	< 1		
West ES	1st Floor, Inside Computer Lab (Right)	< 1		
West ES	1st Floor, Inside Computer Lab (Right)	< 1		
West ES	1st Floor, Inside Book Storage (Left)	< 1		
West ES	1st Floor, Inside Book Storage (Left)	< 1		
West ES	1st Floor, Inside Book Storage (Right)	< 1		
West ES	1st Floor, Inside Book Storage (Right)	< 1		
West ES	1st Floor, Inside Teacher's Lounge	< 1		
West ES	1st Floor, Inside Teacher's Lounge	< 1		
West ES	1st Floor, Outside Teacher's Lounge	< 1		
West ES	1st Floor, Outside Teacher's Lounge	< 1		
West ES	1st Floor, Inside Lunch Room	< 1		
West ES	1st Floor, Inside Lunch Room	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Left)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Left)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Right)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Right)	< 1		
West ES	1st Floor, Inside Gymnasium (Left)	< 1		
West ES	1st Floor, Inside Gymnasium (Left)	< 1		
West ES	1st Floor, Inside Gymnasium (Right)	< 1		
West ES	1st Floor, Inside Gymnasium (Right)	< 1		
West ES	Ground Floor Hallway, Outside Main Office	< 1		
West ES	Ground Floor Hallway, Outside Main Office	< 1		
West ES	Ground Floor Hallway, Outside Girls Restroom	< 1		
West ES	Ground Floor Hallway, Outside Girls Restroom	< 1		
West ES	Ground Floor, Inside Daycare	< 1		
West ES	Ground Floor, Inside Daycare	< 1		
West ES	Ground Floor, Inside Health Suite	< 1		
West ES	Ground Floor, Inside Health Suite	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
West ES	Ground Floor Hallway, Adjacent to Main Lobby	< 1		
West ES	Ground Floor Hallway, Adjacent to Main Lobby	< 1		
West ES	Inside Pre-K (Left)	< 1		
West ES	Inside Pre-K (Left)	< 1		
West ES	Inside Pre-K (Right)	< 1		
West ES	Inside Pre-K (Right)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Whittier ES	2nd Floor, Across from Room 202	< 1		
Whittier ES	2nd Floor, Across from Room 202	1.6		
Whittier ES	1st Floor, Across from Room 102A	< 1		
Whittier ES	1st Floor, Across from Room 102A	< 1		
Whittier ES	Basement Floor, Across from Room 002	< 1		
Whittier ES	Basement Floor, Across from Room 002	< 1		
Whittier ES	3rd Floor, Across from Room 303C	1.4		
Whittier ES	3rd Floor, Across from Room 303C	2.2		
Whittier ES	3rd Floor, Across from Room 304	2.6		
Whittier ES	3rd Floor, Across from Room 304	2.8		
Whittier ES	2nd Floor, Adjacent to Health Suite	< 1		
Whittier ES	2nd Floor, Adjacent to Health Suite	< 1		
Whittier ES	2nd Floor, Adjacent to Main Office	< 1		
Whittier ES	2nd Floor, Adjacent to Main Office	< 1		
Whittier ES	1st Floor, Across from Auditorium	< 1		
Whittier ES	1st Floor, Across from Auditorium	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Inside Classroom 203	< 1		
Wilkinson ES	2nd Floor, Inside Classroom 203	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Locker Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Locker Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Exit Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Exit Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Teacher's Bathroom	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Teacher's Bathroom	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Main Entrance	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Main Entrance	< 1		
Wilkinson ES	Ground Floor, Inside Lunch Room (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Lunch Room (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Right Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Right Side)	< 1		
Wilkinson ES	Ground Floor, Adjacent to Health Suite	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Wilkinson ES	Ground Floor, Adjacent to Health Suite	< 1		
Wilkinson ES	Ground Floor, Adjacent to Electric Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Electric Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Teacher's Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Teacher's Room	< 1		
Wilkinson ES	Ground Floor, Inside Teacher's Room	7		
Wilkinson ES	Ground Floor, Inside Teacher's Room	2.2		
Wilkinson ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #2	< 1		
Winston ES	2nd Floor, Open Space 1, #2	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #2	1.6		
Winston ES	1st Floor, Open Space 1, #2	1.1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Winston ES	1st Floor, Open Space 1, #3	4.5		
Winston ES	1st Floor, Open Space 1, #3	4.9		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Totals/Percentages of All Tested Schools				
Total Number of Schools Tested				108
Total Passed Samples				3552
Total Failed Samples				12
Total Samples Collected				3564
Percentage of Passed Samples				99.66%
Percentage of Failed Samples				0.34%