



# GOVERNMENT OF THE DISTRICT OF COLUMBIA

## Department of Energy & Environment

### Toxic Substances Division Underground Storage Tank Branch



## Public Record - Summary Information On Motor Fuel Underground Storage Tanks (USTs)

Public Record Posted Date : 12/6/2016

### General Information

Total Number of Active or Temporarily Closed Federal UST Facilities	275
Total Number of Temporarily Closed Federal UST Facilities	21
Total Number of Active or Temporarily Closed Federal UST tanks	625
Total Number of Temporarily Closed Federal UST tanks	56
Total Number of Active and Inactive Federal Leaking UST (LUST) Cases	981
Total Number of Active Federal LUST Cases	115

### Summary Information for On-Site Inspections

Number of UST Facilities Inspected:.....80

Inspection Period Dates: 10/1/2015 to: 9/30/2016

Release Prevention Compliant:.....86.25%

Release Detection Compliant:.....90.00%

Percent Compliance (Combined Measure):..... 78.75%

Note: Tank, facility, and on-site inspection information is based on inspection of UST motor fuel facilities only; heating oil USTs are not included. On-site inspections measure compliance with U.S. EPA regulations governing the prevention and detection of petroleum releases or discharging from underground storage tanks.

### Summary Information for Releases

Number of Confirmed UST Releases:.....13

Release Reporting Period Dates: 10/1/2015 to: 9/30/2016

### Summary Information for Release Sources and Causes - New Federal LUST Cases

Source	Cause							
	Tank		Unknown		Phys/Mech Damage		Totals	
	#	%	#	%	#	%	#	%
Tank	1	8 %	1	8 %	0	0 %	2	15 %
Unknown	0	0 %	9	69 %	0	0 %	9	69 %
Dispenser	0	0 %	0	0 %	1	8 %	1	8 %
imported fill (0 to 80 ft) in area being developed	0	0 %	1	8 %	0	0 %	1	8 %
Totals	1	8 %	11	85 %	1	8 %	13	100 %

# = number

% = percent of releases by source or percent of causes by source

Other (Source) low level contamination, not expected to be a continuing release from a UST system

Other (Release) cause is known but does not fit into other categories