

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Addison ES	2nd Floor Hallway, High Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, High Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, Low Water Fountain Adjacent to Room 206	< 1		
Addison ES	2nd Floor Hallway, Low Water Fountain Adjacent to Room 206	< 1		
Addison ES	1st Floor Hallway, High Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, High Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, Low Water Fountain Adjacent to Room 111	< 1		
Addison ES	1st Floor Hallway, Low Water Fountain Adjacent to Room 111	< 1		
Addison ES	Basement Floor Hallway, High Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, High Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, Low Water Fountain Adjacent to Room B03	< 1		
Addison ES	Basement Floor Hallway, Low Water Fountain Adjacent to Room B03	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Aiton ES	4th Floor, Adjacent to Stairwell	< 1		
Aiton ES	4th Floor, Adjacent to Stairwell	< 1		
Aiton ES	4th Floor, Adjacent to Elevator	< 1		
Aiton ES	4th Floor, Adjacent to Elevator	< 1		
Aiton ES	3rd Floor, Adjacent to Stairwell	< 1		
Aiton ES	3rd Floor, Adjacent to Stairwell	< 1		
Aiton ES	3rd Floor, Adjacent to Elevator	< 1		
Aiton ES	3rd Floor, Adjacent to Elevator	< 1		
Aiton ES	2nd Floor, Adjacent to Stairwell	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Aiton ES	2nd Floor, Adjacent to Stairwell	< 1		
Aiton ES	2nd Floor, Adjacent to Elevator	< 1		
Aiton ES	2nd Floor, Adjacent to Elevator	< 1		
Aiton ES	1st Floor, Inside Room 2	< 1		
Aiton ES	1st Floor, Inside Room 2	< 1		
Aiton ES	1st Floor, Inside Room 1	< 1		
Aiton ES	1st Floor, Inside Room 1	< 1		
Aiton ES	1st Floor, Adjacent to Health Suite	< 1		
Aiton ES	1st Floor, Adjacent to Health Suite	< 1		
Aiton ES	1st Floor, Main Lobby	< 1		
Aiton ES	1st Floor, Main Lobby	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Amidon ES	1st Floor, Across from Room 117	< 1		
Amidon ES	1st Floor, Across from Room 117	< 1		
Amidon ES	1st Floor, Inside Room 117	< 1		
Amidon ES	1st Floor, Inside Room 117	< 1		
Amidon ES	1st Floor, Inside Room 124	< 1		
Amidon ES	1st Floor, Inside Room 124	< 1		
Amidon ES	1st Floor, Adjacent to Room 133	< 1		
Amidon ES	1st Floor, Adjacent to Room 133	< 1		
Amidon ES	2nd Floor, Across from Room 203	< 1		
Amidon ES	2nd Floor, Across from Room 203	< 1		
Amidon ES	2nd Floor, Adjacent to Room 206-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 206-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 219-B	< 1		
Amidon ES	2nd Floor, Adjacent to Room 219-B	< 1		
Amidon ES	2nd Floor, Adjacent to Room 225-A	< 1		
Amidon ES	2nd Floor, Adjacent to Room 225-A	< 1		
Amidon ES	Inside Teacher's Lounge	< 1		
Amidon ES	Inside Teacher's Lounge	< 1		
Amidon ES	Inside Gymnasium	< 1		
Amidon ES	Inside Gymnasium	< 1		
Amidon ES	Outside Gymnasium	< 1		
Amidon ES	Outside Gymnasium	< 1		
Amidon ES	Inside Cafeteria	< 1		
Amidon ES	Inside Cafeteria	< 1		
Amidon ES	Inside Pre-K, Adjacent to Toilet	< 1		
Amidon ES	Inside Pre-K, Adjacent to Toilet	< 1		
Amidon ES	2nd Floor Hallway, Between Girls and Boys Restroom	< 1		
Amidon ES	2nd Floor Hallway, Between Girls and Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 221	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 221	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 224	< 1		
Bancroft ES	2nd Floor Hallway, Main Bldg, Room 224	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 210	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 210	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 213	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Room 213	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Bancroft ES	1st Floor Hallway, Main Bldg, Adjacent to Main Office	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Adjacent to Main Office	< 1		
Bancroft ES	1st Floor Hallway, Main Office, Adjacent to Room 122	< 1		
Bancroft ES	1st Floor Hallway, Main Office, Adjacent to Room 122	< 1		
Bancroft ES	Basement Floor, Inside Cafeteria	< 1		
Bancroft ES	Basement Floor, Inside Cafeteria	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Inside Health Suite	< 1		
Bancroft ES	1st Floor Hallway, Main Bldg, Inside Health Suite	< 1		
Bancroft ES	2nd Floor Hallway, North Bldg, Across from Room 324	< 1		
Bancroft ES	2nd Floor Hallway, North Bldg, Across from Room 324	< 1		
Bancroft ES	1st Floor Hallway, North Bldg, Adjacent to Room 310	< 1		
Bancroft ES	1st Floor Hallway, North Bldg, Adjacent to Room 310	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 313	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 313	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 314	< 1		
Bancroft ES	1st Floor, North Bldg, Inside Room 314	< 1		
Bancroft ES	Basement Floor Hallway, North Bldg, Across from Room 303	< 1		
Bancroft ES	Basement Floor Hallway, North Bldg, Across from Room 303	< 1		
Bancroft ES	Basement Floor, South Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, South Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, North Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, North Side of Pre-K/Learning Center	< 1		
Bancroft ES	Basement Floor, Inside Library Area	< 1		
Bancroft ES	Basement Floor, Inside Library Area	< 1		
Bancroft ES	Playground Area, Southwest Side (High)	1.3		
Bancroft ES	Playground Area, Southwest Side (High)	< 1		
Bancroft ES	Playground Area, Southwest Side (Low)	1.1		
Bancroft ES	Playground Area, Southwest Side (Low)	< 1		
Bancroft ES	Playground Area, Southeast Side (High)	1.4		
Bancroft ES	Playground Area, Southeast Side (High)	1.3		
Bancroft ES	Playground Area, Southeast Side (Low)	1.3		
Bancroft ES	Playground Area, Southeast Side (Low)	1		
Bancroft ES	Playground Area, Northeast Side (High)	< 1		
Bancroft ES	Playground Area, Northeast Side (High)	< 1		
Bancroft ES	Playground Area, Northeast Side (Low)	< 1		
Bancroft ES	Playground Area, Northeast Side (Low)	< 1		
Bancroft ES	Playground Area, Northwest Side (High)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Bancroft ES	Playground Area, Northwest Side (High)	< 1		
Bancroft ES	Playground Area, Northwest Side (Low)	< 1		
Bancroft ES	Playground Area, Northwest Side (Low)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Banneker ES	3rd Floor Hallway, Adjacent to Room 305	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 305	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 321	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 321	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 315	< 1		
Banneker ES	3rd Floor Hallway, Adjacent to Room 315	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 220	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 220	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Girls Restroom	< 1		
Banneker ES	2nd Floor Hallway, Adjacent to Girls Restroom	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 103	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 113	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 113	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 118	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 118	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Right Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Right Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Left Side)	< 1		
Banneker ES	1st Floor, Inside Gymnasium (Left Side)	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Banneker ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Banneker ES	Basement Hallway, Adjacent to Electrical Storage Room	< 1		
Banneker ES	Basement Hallway, Adjacent to Electrical Storage Room	< 1		
Banneker ES	Inside Cafeteria, (Right Side)	< 1		
Banneker ES	Inside Cafeteria, (Right Side)	< 1		
Banneker ES	Inside Cafeteria, (Left Side)	< 1		
Banneker ES	Inside Cafeteria, (Left Side)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Barnard ES	2nd Floor, Across from Art Room (Short)	< 1		
Barnard ES	2nd Floor, Across from Art Room (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 219 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Tall)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Short)	< 1		
Barnard ES	2nd Floor, Across from Room 215 (Short)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Barnard ES	1st Floor, Across from Main Office (Tall)	< 1		
Barnard ES	1st Floor, Across from Main Office (Tall)	< 1		
Barnard ES	1st Floor, Across from Main Office (Short)	< 1		
Barnard ES	1st Floor, Across from Main Office (Short)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Tall)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Tall)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Short)	< 1		
Barnard ES	1st Floor, Adjacent to Room 106 (Short)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Tall)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Tall)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Short)	< 1		
Barnard ES	1st Floor, Across from Room 114 (Short)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Beers ES	Lunch Room Cafeteria	< 1		
Beers ES	Lunch Room Cafeteria	< 1		
Beers ES	Inside Classroom A-112	5.5		
Beers ES	Inside Classroom A-112	< 1		
Beers ES	Inside Classroom A-108	3.4		
Beers ES	Inside Classroom A-108	< 1		
Beers ES	Inside Health Suite	< 1		
Beers ES	Inside Health Suite	< 1		
Beers ES	In Hallway, by Health Suite Office	< 1		
Beers ES	In Hallway, by Health Suite Office	< 1		
Beers ES	In Hallway, by Classroom B-206	< 1		
Beers ES	In Hallway, by Classroom B-206	< 1		
Beers ES	In Hallway, by Classroom B-201	< 1		
Beers ES	In Hallway, by Classroom B-201	< 1		
Beers ES	In Hallway, by Computer Lab in D Building	< 1		
Beers ES	In Hallway, by Computer Lab in D Building	< 1		
Beers ES	In Hallway, by Classroom D-201	< 1		
Beers ES	In Hallway, by Classroom D-201	< 1		
Beers ES	In Hallway,by Planetarium	< 1		
Beers ES	In Hallway,by Planetarium	< 1		
Beers ES	In Hallway, by Classroom D-101	< 1		
Beers ES	In Hallway, by Classroom D-101	< 1		
Beers ES	In Hallway, by Classroom D-109	< 1		
Beers ES	In Hallway, by Classroom D-109	< 1		
Beers ES	In Hallway, by Classroom D-106	< 1		
Beers ES	In Hallway, by Classroom D-106	< 1		
Beers ES	In Hallway, by Classroom D-104	< 1		
Beers ES	In Hallway, by Classroom D-104	< 1		
Beers ES	In Hallway, by Classroom A-208	< 1		
Beers ES	In Hallway, by Classroom A-208	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Brent ES	Inside Cafeteria	< 1		
Brent ES	Inside Cafeteria	< 1		
Brent ES	1st Floor, Inside Room 102	< 1		
Brent ES	1st Floor, Inside Room 102	< 1		
Brent ES	1st Floor, Inside Room 104	< 1		
Brent ES	1st Floor, Inside Room 104	< 1		
Brent ES	1st Floor, Inside Room 108	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Brent ES	1st Floor, Inside Room 108	< 1		
Brent ES	1st Floor, Inside Room 110	< 1		
Brent ES	1st Floor, Inside Room 110	< 1		
Brent ES	1st Floor, Beside Room 111	< 1		
Brent ES	1st Floor, Beside Room 111	< 1		
Brent ES	1st Floor, Inside Room 116	< 1		
Brent ES	1st Floor, Inside Room 116	< 1		
Brent ES	1st Floor, Inside Room 118	< 1		
Brent ES	1st Floor, Inside Room 118	< 1		
Brent ES	2nd Floor, Adjacent to Room 204	< 1		
Brent ES	2nd Floor, Adjacent to Room 204	< 1		
Brent ES	2nd Floor, Adjacent to Room 210	< 1		
Brent ES	2nd Floor, Adjacent to Room 210	< 1		
Brent ES	3rd Floor, Adjacent to Room 304	< 1		
Brent ES	3rd Floor, Adjacent to Room 304	< 1		
Brent ES	3rd Floor, Adjacent to Room 310	< 1		
Brent ES	3rd Floor, Adjacent to Room 310	< 1		
Brent ES	2nd Floor, Inside Teacher's Lounge	< 1		
Brent ES	2nd Floor, Inside Teacher's Lounge	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Brightwood ES	1st Floor, Outside Rooms 104 & 105 (High)	< 1		
Brightwood ES	1st Floor, Outside Rooms 104 & 105 (High)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (Low)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (Low)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (High)	< 1		
Brightwood ES	1st Floor, Beside Mechanical Room 123 (High)	< 1		
Brightwood ES	1st Floor, Inside Room 125	< 1		
Brightwood ES	1st Floor, Inside Room 125	< 1		
Brightwood ES	1st Floor, Inside Room 128	< 1		
Brightwood ES	1st Floor, Inside Room 128	< 1		
Brightwood ES	1st Floor, Inside Room 130	< 1		
Brightwood ES	1st Floor, Inside Room 130	< 1		
Brightwood ES	1st Floor, Inside Room 136	< 1		
Brightwood ES	1st Floor, Inside Room 136	< 1		
Brightwood ES	1st Floor, Inside Room 137	< 1		
Brightwood ES	1st Floor, Inside Room 137	< 1		
Brightwood ES	1st Floor, Inside Room 142	< 1		
Brightwood ES	1st Floor, Inside Room 142	< 1		
Brightwood ES	1st Floor, Inside Room 143	< 1		
Brightwood ES	1st Floor, Inside Room 143	< 1		
Brightwood ES	1st Floor, Inside Room 145	< 1		
Brightwood ES	1st Floor, Inside Room 145	< 1		
Brightwood ES	1st Floor, Inside Room 146	< 1		
Brightwood ES	1st Floor, Inside Room 146	< 1		
Brightwood ES	1st Floor, Inside Room 147	< 1		
Brightwood ES	1st Floor, Inside Room 147	< 1		
Brightwood ES	2nd Floor Hallway (Low)	< 1		
Brightwood ES	2nd Floor Hallway (Low)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Brightwood ES	2nd Floor Hallway (High)	< 1		
Brightwood ES	2nd Floor Hallway (High)	< 1		
Brightwood ES	2nd Floor, Inside Room 206	< 1		
Brightwood ES	2nd Floor, Inside Room 206	< 1		
Brightwood ES	2nd Floor, Inside Room 208	< 1		
Brightwood ES	2nd Floor, Inside Room 208	< 1		
Brightwood ES	2nd Floor, Inside Room 210	< 1		
Brightwood ES	2nd Floor, Inside Room 210	< 1		
Brightwood ES	2nd Floor, Inside Room 212	< 1		
Brightwood ES	2nd Floor, Inside Room 212	< 1		
Brightwood ES	2nd Floor, Inside Room 213	< 1		
Brightwood ES	2nd Floor, Inside Room 213	< 1		
Brightwood ES	2nd Floor, Inside Room 214	< 1		
Brightwood ES	2nd Floor, Inside Room 214	< 1		
Brightwood ES	2nd Floor, Inside Room 216	< 1		
Brightwood ES	2nd Floor, Inside Room 216	< 1		
Brightwood ES	2nd Floor, Inside Room 218	< 1		
Brightwood ES	2nd Floor, Inside Room 218	< 1		
Brightwood ES	2nd Floor, Inside Room 224	< 1		
Brightwood ES	2nd Floor, Inside Room 224	< 1		
Brightwood ES	2nd Floor, Inside Room 228	< 1		
Brightwood ES	2nd Floor, Inside Room 228	< 1		
Brightwood ES	2nd Floor, Inside Room 235	< 1		
Brightwood ES	2nd Floor, Inside Room 235	< 1		
Brightwood ES	2nd Floor, Inside Room 237	< 1		
Brightwood ES	2nd Floor, Inside Room 237	< 1		
Brightwood ES	2nd Floor, Inside Room 239	< 1		
Brightwood ES	2nd Floor, Inside Room 239	< 1		
Brightwood ES	3rd Floor Hallway (Low)	< 1		
Brightwood ES	3rd Floor Hallway (Low)	< 1		
Brightwood ES	3rd Floor Hallway (High)	< 1		
Brightwood ES	3rd Floor Hallway (High)	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 309	< 1		
Brightwood ES	3rd Floor, Inside Room 309	< 1		
Brightwood ES	3rd Floor, Inside Room 310	< 1		
Brightwood ES	3rd Floor, Inside Room 310	< 1		
Brightwood ES	3rd Floor, Inside Room 312	< 1		
Brightwood ES	3rd Floor, Inside Room 312	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 308	< 1		
Brightwood ES	3rd Floor, Inside Room 314	< 1		
Brightwood ES	3rd Floor, Inside Room 314	< 1		
Brightwood ES	3rd Floor, Inside Room 316	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Brightwood ES	3rd Floor, Inside Room 316	< 1		
Brightwood ES	3rd Floor, Inside Room 331	< 1		
Brightwood ES	3rd Floor, Inside Room 331	< 1		
Brightwood ES	3rd Floor, Inside Room 325	< 1		
Brightwood ES	3rd Floor, Inside Room 325	< 1		
Brightwood ES	3rd Floor, Inside Room 325 (Tap)	< 1		
Brightwood ES	3rd Floor, Inside Room 325 (Tap)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Bunker Hill ES	2nd Floor, Across from Room 2-115	< 1		
Bunker Hill ES	2nd Floor, Across from Room 2-115	< 1		
Bunker Hill ES	1st Floor, Across from Room 1-039	< 1		
Bunker Hill ES	1st Floor, Across from Room 1-039	< 1		
Bunker Hill ES	2nd Floor, Across from Library	< 1		
Bunker Hill ES	2nd Floor, Across from Library	< 1		
Bunker Hill ES	2nd Floor, Across from Storage Room	< 1		
Bunker Hill ES	2nd Floor, Across from Storage Room	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-092	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-092	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-088	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-088	< 1		
Bunker Hill ES	1st Floor, Adjacent to Storage Room	< 1		
Bunker Hill ES	1st Floor, Adjacent to Storage Room	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-097	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-097	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-086	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-086	< 1		
Bunker Hill ES	1st Floor, Outside Auditorium	< 1		
Bunker Hill ES	1st Floor, Outside Auditorium	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-123	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-123	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-131	< 1		
Bunker Hill ES	2nd Floor, Adjacent to Room 2-131	< 1		
Bunker Hill ES	1st Floor, Adjacent to Room 1-061	< 1		
Bunker Hill ES	1st Floor, Adjacent to Room 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-061	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-055	< 1		
Bunker Hill ES	1st Floor, Inside Classroom 1-055	< 1		
Bunker Hill ES	Basement Floor, Inside Cafeteria	< 1		
Bunker Hill ES	Basement Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Burrrville ES	1st Floor Lobby, Behind Admin. Office	1.3		
Burrrville ES	1st Floor Lobby, Behind Admin. Office	2.2		
Burrrville ES	1st Floor Hallway, Outside Mechanical Room	< 1		
Burrrville ES	1st Floor Hallway, Outside Mechanical Room	< 1		
Burrrville ES	1st Floor Hallway, Outside Girls and Boys Restroom	3.8		
Burrrville ES	1st Floor Hallway, Outside Girls and Boys Restroom	5.6		
Burrrville ES	1st Floor Hallway, Outisde Room 113/114 (L)	< 1		
Burrrville ES	1st Floor Hallway, Outisde Room 113/114 (L)	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Burrville ES	1st Floor Hallway, Outside Room 113/114 (R)	< 1		
Burrville ES	1st Floor Hallway, Outside Room 113/114 (R)	< 1		
Burrville ES	1st Floor, Inside Room 111	< 1		
Burrville ES	1st Floor, Inside Room 111	< 1		
Burrville ES	1st Floor, Inside Room 113	< 1		
Burrville ES	1st Floor, Inside Room 113	< 1		
Burrville ES	1st Floor, Inside Room 114	< 1		
Burrville ES	1st Floor, Inside Room 114	< 1		
Burrville ES	1st Floor, Inside Room 115	< 1		
Burrville ES	1st Floor, Inside Room 115	< 1		
Burrville ES	1st Floor, Inside Room 110	< 1		
Burrville ES	1st Floor, Inside Room 110	< 1		
Burrville ES	1st Floor, Inside Room 108	< 1		
Burrville ES	1st Floor, Inside Room 108	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Elevator (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (L)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (R)	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Gym Door/Mental Health Room (R)	1.2		
Burrville ES	2nd Floor, Inside Teacher's Lounge	1.9		
Burrville ES	2nd Floor, Inside Teacher's Lounge	3.2		
Burrville ES	2nd Floor, Inside Music Room	< 1		
Burrville ES	2nd Floor, Inside Music Room	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Double Doors/Opp. Room 241	< 1		
Burrville ES	2nd Floor Hallway, Adjacent to Double Doors/Opp. Room 241	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (L)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (L)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (R)	< 1		
Burrville ES	2nd Floor Hallway, Outside Room 228 (R)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 228	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 228	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 227	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 227	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (L)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (L)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (R)	< 1		
Burrville ES	2nd Floor Hallway, Inside Room 223 (R)	< 1		
Burrville ES	2nd Floor, Inside Room 221	< 1		
Burrville ES	2nd Floor, Inside Room 221	< 1		
Burrville ES	2nd Floor, Inside Room 224	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Burrrville ES	2nd Floor, Inside Room 224	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Burroughs ES	Basement Floor Hallway, Adjacent to Room 19	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 19	< 1		
Burroughs ES	Basement Floor, Inside Room 20	< 1		
Burroughs ES	Basement Floor, Inside Room 20	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 20	< 1		
Burroughs ES	Basement Floor Hallway, Adjacent to Room 20	< 1		
Burroughs ES	Basement Floor, Inside Room 21	< 1		
Burroughs ES	Basement Floor, Inside Room 21	< 1		
Burroughs ES	Basement Floor, Inside Room 22	< 1		
Burroughs ES	Basement Floor, Inside Room 22	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 3	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 3	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 8	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 8	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 9	< 1		
Burroughs ES	1st Floor Hallway, Adjacent to Room 9	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 14	< 1		
Burroughs ES	1st Floor Hallway, Across from Room 14	< 1		
Burroughs ES	1st Floor (New Wing) Hallway, Across from Room 27	< 1		
Burroughs ES	1st Floor (New Wing) Hallway, Across from Room 27	< 1		
Burroughs ES	1st Floor (New Wing), Bubbler Attached to Sink Inside Room 34	< 1		
Burroughs ES	1st Floor (New Wing), Bubbler Attached to Sink Inside Room 34	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 35	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 35	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 25	< 1		
Burroughs ES	1st Floor (New Wing), Inside Room 25	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
C.W. Harris ES	2nd Floor, Across from Room 246	< 1		
C.W. Harris ES	2nd Floor, Across from Room 246	< 1		
C.W. Harris ES	1st Floor, Inside Room 149	< 1		
C.W. Harris ES	1st Floor, Inside Room 149	< 1		
C.W. Harris ES	1st Floor, Inside Room 153	< 1		
C.W. Harris ES	1st Floor, Inside Room 153	< 1		
C.W. Harris ES	1st Floor, Across from Boiler Room	< 1		
C.W. Harris ES	1st Floor, Across from Boiler Room	< 1		
C.W. Harris ES	1st Floor, Inside Cafeteria	< 1		
C.W. Harris ES	1st Floor, Inside Cafeteria	< 1		
C.W. Harris ES	1st Floor, Near Room 109	< 1		
C.W. Harris ES	1st Floor, Near Room 109	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Percentage of Passed Samples			100.00%	
Percentage of Failed Samples			0.00%	
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 106	1.8		
Cleveland ES	1st Floor, Inside Room 106	< 1		
Cleveland ES	1st Floor, Inside Room 111	1.1		
Cleveland ES	1st Floor, Inside Room 111	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 212	1.2		
Cleveland ES	2nd Floor, Inside Room 212	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	2.8		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 304	1.2		
Cleveland ES	3rd Floor, Inside Room 304	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 313	1.6		
Cleveland ES	3rd Floor, Inside Room 313	2.1		
Cleveland ES	3rd Floor, Inside Room 314	1.2		
Cleveland ES	3rd Floor, Inside Room 314	< 1		
Cleveland ES	3rd Floor Hallway (Low)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Cleveland ES	3rd Floor Hallway (Low)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Davis ES	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Davis ES	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2.5		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		
Davis ES	1st Floor, Inside Teacher's Lounge	2.3		
Davis ES	1st Floor, Inside Teacher's Lounge	10		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Weight Room	1.3		
Davis ES	Lunch Room, Adjacent to Weight Room	2.1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	3.6		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	1.6		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Drew ES	1st Floor, Auditorium Lobby (Upper)	1.4		
Drew ES	1st Floor, Auditorium Lobby (Upper)	2		
Drew ES	1st Floor, Auditorium Lobby (Lower)	1.8		
Drew ES	1st Floor, Auditorium Lobby (Lower)	2.4		
Drew ES	1st Floor, Inside Cafeteria	2.8		
Drew ES	1st Floor, Inside Cafeteria	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Drew ES	1st Floor Hallway, Outside Health Suite (Lower)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Lower)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Upper)	< 1		
Drew ES	1st Floor Hallway, Outside Health Suite (Upper)	< 1		
Drew ES	1st Floor, Inside Health Suite	12		
Drew ES	1st Floor, Inside Health Suite	< 1		
Drew ES	1st Floor, Inside Room 104	< 1		
Drew ES	1st Floor, Inside Room 104	< 1		
Drew ES	1st Floor, Inside Room 108	< 1		
Drew ES	1st Floor, Inside Room 108	< 1		
Drew ES	1st Floor, Outside Room 107 (Upper)	< 1		
Drew ES	1st Floor, Outside Room 107 (Upper)	< 1		
Drew ES	1st Floor, Outside Room 107 (Lower)	< 1		
Drew ES	1st Floor, Outside Room 107 (Lower)	< 1		
Drew ES	1st Floor, Inside Room 105	< 1		
Drew ES	1st Floor, Inside Room 105	< 1		
Drew ES	1st Floor, Inside Room 107	< 1		
Drew ES	1st Floor, Inside Room 107	5.7		
Drew ES	1st Floor, Inside Room 106	1.8		
Drew ES	1st Floor, Inside Room 106	< 1		
Drew ES	4th Floor Hallway, Outside Room 411	< 1		
Drew ES	4th Floor Hallway, Outside Room 411	< 1		
Drew ES	4th Floor Hallway, Outside Room 404 (Upper)	< 1		
Drew ES	4th Floor Hallway, Outside Room 404 (Upper)	1.4		
Drew ES	4th Floor Hallway, Outside Room 404 (Lower)	1.2		
Drew ES	4th Floor Hallway, Outside Room 404 (Lower)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Upper)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Upper)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Lower)	< 1		
Drew ES	3rd Floor Hallway, Outside Room 300 (Lower)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 200 (Upper)	1.4		
Drew ES	2nd Floor Hallway, Outside Room 200 (Upper)	1.8		
Drew ES	2nd Floor Hallway, Outside Room 200 (Lower)	1.6		
Drew ES	2nd Floor Hallway, Outside Room 200 (Lower)	1.3		
Drew ES	2nd Floor Hallway, Inside Teacher's Lounge	< 1		
Drew ES	2nd Floor Hallway, Inside Teacher's Lounge	< 1		
Drew ES	2nd Floor Hallway, Inside Room 207	< 1		
Drew ES	2nd Floor Hallway, Inside Room 207	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Upper)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Upper)	< 1		
Drew ES	2nd Floor Hallway, Outside Room 207 (Lower)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Drew ES	2nd Floor Hallway, Outside Room 207 (Lower)	< 1		
Drew ES	2nd Floor, Inside Room 207	< 1		
Drew ES	2nd Floor, Inside Room 207	< 1		
Drew ES	2nd Floor, Inside Room 205	1.1		
Drew ES	2nd Floor, Inside Room 205	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Francis JHS	3rd Floor Hallway, Outside Room 304	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 304	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 303	< 1		
Francis JHS	3rd Floor Hallway, Outside Room 303	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 203	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 203	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 204	< 1		
Francis JHS	2nd Floor Hallway, Outside Room 204	< 1		
Francis JHS	1st Floor Hallway, Outside Room 100	< 1		
Francis JHS	1st Floor Hallway, Outside Room 100	< 1		
Francis JHS	1st Floor, Inside Teacher's Lounge	< 1		
Francis JHS	1st Floor, Inside Teacher's Lounge	< 1		
Francis JHS	1st Floor, Inside Students' Cafeteria	< 1		
Francis JHS	1st Floor, Inside Students' Cafeteria	< 1		
Francis JHS	1st Floor Hallway, Outside Electrical Room	< 1		
Francis JHS	1st Floor Hallway, Outside Electrical Room	< 1		
Francis JHS	1st Floor, Inside Room 108	< 1		
Francis JHS	1st Floor, Inside Room 108	< 1		
Francis JHS	1st Floor, Inside Room 110	< 1		
Francis JHS	1st Floor, Inside Room 110	< 1		
Francis JHS	1st Floor, Inside Room 107	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Francis JHS	1st Floor, Inside Room 107	< 1		
Francis JHS	1st Floor, Inside Room 105	< 1		
Francis JHS	1st Floor, Inside Room 105	< 1		
Francis JHS	1st Floor, Inside Room 103	< 1		
Francis JHS	1st Floor, Inside Room 103	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Garfield ES	2nd Floor, Adjacent to Room 2-J	< 1		
Garfield ES	2nd Floor, Adjacent to Room 2-J	< 1		
Garfield ES	1st Floor, Adjacent to Main Office	< 1		
Garfield ES	1st Floor, Adjacent to Main Office	< 1		
Garfield ES	1st Floor, Inside Health Suite	< 1		
Garfield ES	1st Floor, Inside Health Suite	< 1		
Garfield ES	1st Floor, Across from Room 1-F	< 1		
Garfield ES	1st Floor, Across from Room 1-F	< 1		
Garfield ES	Basement Floor, Inside Cafeteria	< 1		
Garfield ES	Basement Floor, Inside Cafeteria	< 1		
Garfield ES	Basement Floor, Inside Cafeteria, Adjacent to Snack Bar	< 1		
Garfield ES	Basement Floor, Inside Cafeteria, Adjacent to Snack Bar	< 1		
Garfield ES	1st Floor, Adjacent to Teacher's Lounge	< 1		
Garfield ES	1st Floor, Adjacent to Teacher's Lounge	< 1		
Garfield ES	1st Floor, Across from Room 102	< 1		
Garfield ES	1st Floor, Across from Room 102	< 1		
Garfield ES	1st Floor, Inside Room 102	< 1		
Garfield ES	1st Floor, Inside Room 102	< 1		
Garfield ES	1st Floor, Inside Room 101	< 1		
Garfield ES	1st Floor, Inside Room 101	< 1		
Garfield ES	2nd Floor, Across from Girls Restroom	< 1		
Garfield ES	2nd Floor, Across from Girls Restroom	< 1		
Garfield ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Garfield ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Garnet-Patterson MS	1st Floor Hallway, Outside Room 110	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Room 110	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Left of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Left of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Right of Kitchen	< 1		
Garnet-Patterson MS	Basement, Inside Cafeteria, Right of Kitchen	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Gymnasium	< 1		
Garnet-Patterson MS	1st Floor Hallway, Outside Gymnasium	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 308	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 308	< 1		
Garnet-Patterson MS	3rd Floor, Inside Teacher's Lounge	< 1		
Garnet-Patterson MS	3rd Floor, Inside Teacher's Lounge	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 303	< 1		
Garnet-Patterson MS	3rd Floor Hallway, Outside Room 303	< 1		
Garnet-Patterson MS	2nd Floor Hallway, Outside Room 216	< 1		
Garnet-Patterson MS	2nd Floor Hallway, Outside Room 216	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Garrison ES	1st Floor, Outside Room 108	< 1		
Garrison ES	1st Floor, Outside Room 108	< 1		
Garrison ES	1st Floor, Inside Room 109	< 1		
Garrison ES	1st Floor, Inside Room 109	< 1		
Garrison ES	1st Floor, Inside Room 110	< 1		
Garrison ES	1st Floor, Inside Room 110	< 1		
Garrison ES	1st Floor, Across from Room 128	< 1		
Garrison ES	1st Floor, Across from Room 128	< 1		
Garrison ES	2nd Floor, Inside Room 201	1.6		
Garrison ES	2nd Floor, Inside Room 201	< 1		
Garrison ES	2nd Floor, Inside Room 207	< 1		
Garrison ES	2nd Floor, Inside Room 207	< 1		
Garrison ES	2nd Floor, Beside Room 212	< 1		
Garrison ES	2nd Floor, Beside Room 212	< 1		
Garrison ES	Outside Library	< 1		
Garrison ES	Outside Library	< 1		
Garrison ES	Outside Main Office	< 1		
Garrison ES	Outside Main Office	< 1		
Garrison ES	Inside Cafeteria	< 1		
Garrison ES	Inside Cafeteria	< 1		
Garrison ES	1st Floor, Beside Room 122	< 1		
Garrison ES	1st Floor, Beside Room 122	< 1		
Garrison ES	Inside Health Suite	< 1		
Garrison ES	Inside Health Suite	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Green ES	3rd Floor Hallway, Outside Room 315	< 1		
Green ES	3rd Floor Hallway, Outside Room 315	< 1		
Green ES	3rd Floor Hallway, Outside Room 308	< 1		
Green ES	3rd Floor Hallway, Outside Room 308	< 1		
Green ES	2nd Floor Hallway, Outside Room 208	< 1		
Green ES	2nd Floor Hallway, Outside Room 208	< 1		
Green ES	2nd Floor Hallway, Outside Room 214	< 1		
Green ES	2nd Floor Hallway, Outside Room 214	< 1		
Green ES	2nd Floor Hallway, Outside Room 218	< 1		
Green ES	2nd Floor Hallway, Outside Room 218	< 1		
Green ES	2nd Floor, Inside Room 225	< 1		
Green ES	2nd Floor, Inside Room 225	< 1		
Green ES	1st Floor, Inside Room 130	< 1		
Green ES	1st Floor, Inside Room 130	< 1		
Green ES	1st Floor, Inside Room 131	< 1		
Green ES	1st Floor, Inside Room 131	< 1		
Green ES	1st Floor Hallway, Outside Room 132	< 1		
Green ES	1st Floor Hallway, Outside Room 132	< 1		
Green ES	1st Floor, Inside All Purpose Room	< 1		
Green ES	1st Floor, Inside All Purpose Room	< 1		
Green ES	1st Floor Hallway, Outside Room 115	< 1		
Green ES	1st Floor Hallway, Outside Room 115	2.5		
Green ES	1st Floor, Inside Nurse's Suite	< 1		
Green ES	1st Floor, Inside Nurse's Suite	3.3		
Green ES	1st Floor Hallway, Outside Room 108	< 1		
Green ES	1st Floor Hallway, Outside Room 108	< 1		
Percentage of Passed Samples				100.00%

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Percentage of Failed Samples				0.00%
Hearst ES	2nd Floor, Adjacent to Room 208	< 1		
Hearst ES	2nd Floor, Adjacent to Room 208	< 1		
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hendley ES	Ground Floor, Inside Cafeteria			
Hendley ES	Ground Floor, Inside Cafeteria			
Hendley ES	Ground Floor Hallway, Adjacent to P.E. Teacher's Office			
Hendley ES	Ground Floor Hallway, Adjacent to P.E. Teacher's Office			
Hendley ES	Ground Floor Hallway, Adjacent to Room 7			
Hendley ES	Ground Floor Hallway, Adjacent to Room 7			
Hendley ES	Ground Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom			
Hendley ES	Ground Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom			
Hendley ES	1st Floor, Inside Health Suite			
Hendley ES	1st Floor, Inside Health Suite			
Hendley ES	1st Floor Hallway, Adjacent to Teacher's Lounge			
Hendley ES	1st Floor Hallway, Adjacent to Teacher's Lounge			
Hendley ES	1st Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom			
Hendley ES	1st Floor Hallway, Annex Bldg, Adjacent to Teacher's Restroom			
Hendley ES	2nd Floor Hallway, Adjacent to Room 206			
Hendley ES	2nd Floor Hallway, Adjacent to Room 206			
Hendley ES	2nd Floor Hallway, Adjacent to Room 201			
Hendley ES	2nd Floor Hallway, Adjacent to Room 201			
Hendley ES	3rd Floor Hallway, Adjacent to Room 301			
Hendley ES	3rd Floor Hallway, Adjacent to Room 301			
Hendley ES	3rd Floor Hallway, Adjacent to Room 306			
Hendley ES	3rd Floor Hallway, Adjacent to Room 306			
Hendley ES	2nd Floor, Inside Room 202			
Hendley ES	2nd Floor, Inside Room 202			
Hendley ES	2nd Floor, Inside Room 203			
Hendley ES	2nd Floor, Inside Room 203			
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Houston ES	2nd Floor, Adjacent to Room 212	< 1		
Houston ES	2nd Floor, Adjacent to Room 212	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Hyde ES	1st Floor Lobby, Adjacent to Classroom 105	< 1		
Hyde ES	1st Floor Lobby, Adjacent to Classroom 105	< 1		
Hyde ES	2nd Floor Lobby, Adjacent to Classroom 203	< 1		
Hyde ES	2nd Floor Lobby, Adjacent to Classroom 203	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
J.O. Wilson ES	3rd Floor, Adjacent to Room 308	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 308	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 312	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 312	< 1		
J.O. Wilson ES	3rd Floor, Across from Room 301	< 1		
J.O. Wilson ES	3rd Floor, Across from Room 301	< 1		
J.O. Wilson ES	2nd Floor, Across from Room 201	< 1		
J.O. Wilson ES	2nd Floor, Across from Room 201	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 212	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 212	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 208	< 1		
J.O. Wilson ES	2nd Floor, Adjacent to Room 208	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 329	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 329	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 328	< 1		
J.O. Wilson ES	3rd Floor, Adjacent to Room 328	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 321	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 321	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 322	< 1		
J.O. Wilson ES	3rd Floor, Inside Room 322	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 221	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 221	< 1		
J.O. Wilson ES	2nd Floor, Room in Classroom 221	< 1		
J.O. Wilson ES	2nd Floor, Room in Classroom 221	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 220	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
J.O. Wilson ES	2nd Floor, Inside Room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 220	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 223	< 1		
J.O. Wilson ES	2nd Floor Adjacent to room 223	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222 (Sink)	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222 (Sink)	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222	< 1		
J.O. Wilson ES	2nd Floor, Inside Room 222	< 1		
J.O. Wilson ES	1st Floor, Inside Lunch Room	< 1		
J.O. Wilson ES	1st Floor, Inside Lunch Room	< 1		
J.O. Wilson ES	1st Floor, Near Custodian's Closet	< 1		
J.O. Wilson ES	1st Floor, Near Custodian's Closet	< 1		
J.O. Wilson ES	1st Floor, Near Mechanical Room	< 1		
J.O. Wilson ES	1st Floor, Near Mechanical Room	< 1		
J.O. Wilson ES	1st Floor, Inside Room 121	4.7		
J.O. Wilson ES	1st Floor, Inside Room 121	2.5		
J.O. Wilson ES	1st Floor, Inside Room 123	< 1		
J.O. Wilson ES	1st Floor, Inside Room 123	< 1		
J.O. Wilson ES	1st Floor, Across from Main Office	< 1		
J.O. Wilson ES	1st Floor, Across from Main Office	< 1		
J.O. Wilson ES	1st Floor, Inside Room 108	< 1		
J.O. Wilson ES	1st Floor, Inside Room 108	< 1		
J.O. Wilson ES	1st Floor, Across from Room 108C	< 1		
J.O. Wilson ES	1st Floor, Across from Room 108C	< 1		
J.O. Wilson ES	1st Floor, Inside Room 109	< 1		
J.O. Wilson ES	1st Floor, Inside Room 109	< 1		
J.O. Wilson ES	1st Floor, Inside Room 112	< 1		
J.O. Wilson ES	1st Floor, Inside Room 112	< 1		
J.O. Wilson ES	1st Floor, Inside Room 111	< 1		
J.O. Wilson ES	1st Floor, Inside Room 111	< 1		
J.O. Wilson ES	1st Floor, Inside Room 110	< 1		
J.O. Wilson ES	1st Floor, Inside Room 110	< 1		
J.O. Wilson ES	1st Floor, Adjacent to Room 110	< 1		
J.O. Wilson ES	1st Floor, Adjacent to Room 110	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor, Inside Room 307	1.4		
Janney ES	3rd Floor, Inside Room 307	1.1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 304	< 1		
Janney ES	3rd Floor, Inside Room 304	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Outside Room 207	< 1		
Janney ES	2nd Floor, Outside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 209	1.1		
Janney ES	2nd Floor, Inside Room 209	1.2		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.7		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.3		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	4.3		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	1.7		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	< 1		
Johnson MS	3rd Floor, Outside Room 315A (Up)	9		
Johnson MS	3rd Floor, Outside Room 315A (Up)	14		
Johnson MS	3rd Floor, Outside Room 315A (Down)	7		
Johnson MS	3rd Floor, Outside Room 315A (Down)	8.7		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	2.6		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.2		
Johnson MS	1st Floor, Adjacent to Elevator	< 1		
Johnson MS	1st Floor, Adjacent to Elevator	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	2.2		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ketcham ES	2nd Floor, Adjacent to Room 204	< 1		
Ketcham ES	2nd Floor, Adjacent to Room 204	< 1		
Ketcham ES	1st Floor, Adjacent to Room 104	< 1		
Ketcham ES	1st Floor, Adjacent to Room 104	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Ketcham ES	Ground Floor, Adjacent to Girls Restroom, Stair F	< 1		
Ketcham ES	Ground Floor, Adjacent to Girls Restroom, Stair F	< 1		
Ketcham ES	1st Floor, Adjacent to Preschool Room 2	< 1		
Ketcham ES	1st Floor, Adjacent to Preschool Room 2	< 1		
Ketcham ES	3rd Floor, Adjacent to Boys and Girls Restroom	< 1		
Ketcham ES	3rd Floor, Adjacent to Boys and Girls Restroom	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 2	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 2	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 1	< 1		
Ketcham ES	1st Floor, Inside Preschool Room 1	< 1		
Ketcham ES	1st Floor, Inside Pre-K Room	< 1		
Ketcham ES	1st Floor, Inside Pre-K Room	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Ketcham ES	Ground Floor, Inside Cafeteria	2.3		
Ketcham ES	Ground Floor, Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Key ES	Outisde, On Playground	< 1		
Key ES	Outisde, On Playground	< 1		
Key ES	Ground Floor, Adjacent to Girls Restroom	< 1		
Key ES	Ground Floor, Adjacent to Girls Restroom	< 1		
Key ES	1st Floor, Adjacent to Room 103	< 1		
Key ES	1st Floor, Adjacent to Room 103	< 1		
Key ES	1st Floor, Across from Room 103	< 1		
Key ES	1st Floor, Across from Room 103	< 1		
Key ES	2nd Floor, Adjacent to Room 207	< 1		
Key ES	2nd Floor, Adjacent to Room 207	< 1		
Key ES	2nd Floor, Across from Room 203	< 1		
Key ES	2nd Floor, Across from Room 203	< 1		
Key ES	2nd Floor, Inside Teacher's Lounge	< 1		
Key ES	2nd Floor, Inside Teacher's Lounge	< 1		
Key ES	1st Floor, Inside Room 106	< 1		
Key ES	1st Floor, Inside Room 106	< 1		
Key ES	1st Floor, Inside Room 105	< 1		
Key ES	1st Floor, Inside Room 105	< 1		
Key ES	1st Floor, Inside Room 104	< 1		
Key ES	1st Floor, Inside Room 104	< 1		
Key ES	1st Floor, Inside Room 103	< 1		
Key ES	1st Floor, Inside Room 103	< 1		
Key ES	1st Floor, Inside Room 102	< 1		
Key ES	1st Floor, Inside Room 102	< 1		
Key ES	1st Floor, Inside Room 101	< 1		
Key ES	1st Floor, Inside Room 101	< 1		
Key ES	2nd Floor, Inside Room 202	< 1		
Key ES	2nd Floor, Inside Room 202	< 1		
Key ES	2nd Floor, Inside Room 201	< 1		
Key ES	2nd Floor, Inside Room 201	< 1		
Key ES	2nd Floor, Inside Room 203	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Key ES	2nd Floor, Inside Room 203	< 1		
Key ES	2nd Floor, Inside Room 204	< 1		
Key ES	2nd Floor, Inside Room 204	< 1		
Key ES	2nd Floor, Inside Room 206	< 1		
Key ES	2nd Floor, Inside Room 206	< 1		
Key ES	2nd Floor, Inside Room 205	< 1		
Key ES	2nd Floor, Inside Room 205	< 1		
Key ES	2nd Floor, Inside Room 207	< 1		
Key ES	2nd Floor, Inside Room 207	< 1		
Key ES	2nd Floor, Inside Room 208	< 1		
Key ES	2nd Floor, Inside Room 208	< 1		
Key ES	2nd Floor, Inside Room 209	< 1		
Key ES	2nd Floor, Inside Room 209	< 1		
Key ES	2nd Floor, Inside Room 210	< 1		
Key ES	2nd Floor, Inside Room 210	< 1		
Key ES	2nd Floor, Inside Room 211	< 1		
Key ES	2nd Floor, Inside Room 211	< 1		
Key ES	2nd Floor, Inside Room 212	< 1		
Key ES	2nd Floor, Inside Room 212	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Kimball ES	2nd Floor, Adjacent to Science Lab	< 1		
Kimball ES	2nd Floor, Adjacent to Science Lab	< 1		
Kimball ES	2nd Floor, Adjacent to Room 200	1.2		
Kimball ES	2nd Floor, Adjacent to Room 200	< 1		
Kimball ES	1st Floor, Adjacent to Room 100	< 1		
Kimball ES	1st Floor, Adjacent to Room 100	< 1		
Kimball ES	1st Floor, Adjacent to Girls Restroom	< 1		
Kimball ES	1st Floor, Adjacent to Girls Restroom	< 1		
Kimball ES	2nd Floor, Outside Auditorium	< 1		
Kimball ES	2nd Floor, Outside Auditorium	1.4		
Kimball ES	1st Floor, Inside Room 102	< 1		
Kimball ES	1st Floor, Inside Room 102	< 1		
Kimball ES	2nd Floor, Adjacent to Teacher's Lounge	< 1		
Kimball ES	2nd Floor, Adjacent to Teacher's Lounge	< 1		
Kimball ES	2nd Floor, Adjacent to Room 212	< 1		
Kimball ES	2nd Floor, Adjacent to Room 212	< 1		
Kimball ES	1st Floor, Adjacent to Room 108	< 1		
Kimball ES	1st Floor, Adjacent to Room 108	< 1		
Kimball ES	1st Floor, Adjacent to Room 112	< 1		
Kimball ES	1st Floor, Adjacent to Room 112	< 1		
Kimball ES	1st Floor, Inside Room 109	< 1		
Kimball ES	1st Floor, Inside Room 109	< 1		
Kimball ES	1st Floor, Inside Principal's Office	< 1		
Kimball ES	1st Floor, Inside Principal's Office	< 1		
Kimball ES	1st Floor, Adjacent to Room 115	< 1		
Kimball ES	1st Floor, Adjacent to Room 115	< 1		
Kimball ES	Basement Floor, Across from Room 004	< 1		
Kimball ES	Basement Floor, Across from Room 004	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Lafayette ES	Team 4 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 4 Floor, Classroom on the Right Side	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Lafayette ES	Team 4 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 4 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 3 Floor, Classroom on the Left Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Right Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Right Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Left Side	< 1		
Lafayette ES	3rd Floor, Lunch Room Left Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 2 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Right Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Team 1 Floor, Classroom on the Left Side	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Washing Machine	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Washing Machine	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Ice Box	< 1		
Lafayette ES	Ground Floor, Pre-K, by the Ice Box	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Right Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Right Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Left Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Gym, Left Side	< 1		
Lafayette ES	Basement Floor, Adjacent to the Exit	< 1		
Lafayette ES	Basement Floor, Adjacent to the Exit	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Langdon ES	Basement Floor, Inside Cafeteria	1.1		
Langdon ES	Basement Floor, Inside Cafeteria	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Speech Clinic Room	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Speech Clinic Room	< 1		
Langdon ES	1st Floor, Inside Health Suite	< 1		
Langdon ES	1st Floor, Inside Health Suite	< 1		
Langdon ES	1st Floor, Inside Auditorium	2.1		
Langdon ES	1st Floor, Inside Auditorium	1.8		
Langdon ES	1st Floor Hallway, Adjacent to Room 111	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Room 111	< 1		
Langdon ES	1st Floor Hallway, Adjacent to Room 116	2.9		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Langdon ES	1st Floor Hallway, Adjacent to Room 116	3.2		
Langdon ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 219	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 214	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 214	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 207	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Langdon ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		
Langley JHS	1st Floor, Inside Room 149	< 1		
Langley JHS	1st Floor, Inside Room 149	< 1		
Langley JHS	1st Floor, Inside Room 143	< 1		
Langley JHS	1st Floor, Inside Room 143	< 1		
Langley JHS	1st Floor, Inside Room 137	< 1		
Langley JHS	1st Floor, Inside Room 137	< 1		
Langley JHS	1st Floor, Inside Room 133	< 1		
Langley JHS	1st Floor, Inside Room 133	< 1		
Langley JHS	1st Floor, Inside Staff Lounge	< 1		
Langley JHS	1st Floor, Inside Staff Lounge	< 1		
Langley JHS	1st Floor, Inside Room 125	< 1		
Langley JHS	1st Floor, Inside Room 125	< 1		
Langley JHS	1st Floor, Inside Room 122	< 1		
Langley JHS	1st Floor, Inside Room 122	< 1		
Langley JHS	1st Floor, Inside Room 113	< 1		
Langley JHS	1st Floor, Inside Room 113	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	1.2		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 301	3.3		
Langley JHS	3rd Floor Hallway, Outside Room 301	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Leckie ES	1st Floor Hallway, Adjacent to Teacher's Restroom	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Teacher's Restroom	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Leckie ES	1st Floor Hallway, Inside Health Suite	< 1		
Leckie ES	1st Floor Hallway, Inside Health Suite	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Room 121	< 1		
Leckie ES	1st Floor Hallway, Adjacent to Room 121	< 1		
Leckie ES	1st Floor, Inside All Purpose Room	< 1		
Leckie ES	1st Floor, Inside All Purpose Room	< 1		
Leckie ES	Basement Floor, Inside Recreation Room	< 1		
Leckie ES	Basement Floor, Inside Recreation Room	< 1		
Leckie ES	Basement Floor, Adjacent to Recreation Room	< 1		
Leckie ES	Basement Floor, Adjacent to Recreation Room	< 1		
Leckie ES	Basement Floor, Inside Room 14	< 1		
Leckie ES	Basement Floor, Inside Room 14	< 1		
Leckie ES	Basement Floor, Inside Room 21	< 1		
Leckie ES	Basement Floor, Inside Room 21	< 1		
Leckie ES	Basement Floor, Inside Room 24	< 1		
Leckie ES	Basement Floor, Inside Room 24	< 1		
Leckie ES	Basement Floor, Inside Room 30	< 1		
Leckie ES	Basement Floor, Inside Room 30	< 1		
Leckie ES	2nd Floor, Adjacent to Room 214	< 1		
Leckie ES	2nd Floor, Adjacent to Room 214	< 1		
Leckie ES	2nd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	2nd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Teacher's Restroom	< 1		
Leckie ES	3rd Floor, Adjacent to Room 312	< 1		
Leckie ES	3rd Floor, Adjacent to Room 312	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Ludlow Taylor ES	3rd Floor Hallway, Adjacent to Stairs	< 1		
Ludlow Taylor ES	3rd Floor Hallway, Adjacent to Stairs	< 1		
Ludlow Taylor ES	3rd Floor Stairs	< 1		
Ludlow Taylor ES	3rd Floor Stairs	< 1		
Ludlow Taylor ES	2nd Floor Hallway, Adjacent to Stairs	< 1		
Ludlow Taylor ES	2nd Floor Hallway, Adjacent to Stairs	< 1		
Ludlow Taylor ES	2nd Floor Stairs	< 1		
Ludlow Taylor ES	2nd Floor Stairs	< 1		
Ludlow Taylor ES	1st Floor, Outside Classroom	< 1		
Ludlow Taylor ES	1st Floor, Outside Classroom	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 100	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 100	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 101	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 101	< 1		
Ludlow Taylor ES	1st Floor Hallway, Adjacent to Classroom	< 1		
Ludlow Taylor ES	1st Floor Hallway, Adjacent to Classroom	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 116A	< 1		
Ludlow Taylor ES	1st Floor, Inside Classroom 116A	< 1		
Ludlow Taylor ES	1st Floor, Adjacent to Gymnasium	< 1		
Ludlow Taylor ES	1st Floor, Adjacent to Gymnasium	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (Low)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (Low)	< 1		
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (High)	< 1		
M.L. King ES	3rd Floor, Adjacent to Boys Restroom (High)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (Low)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (Low)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (High)	< 1		
M.L. King ES	3rd Floor Adjacent to Room 307 (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Malcolm X ES	4th Floor Hallway, Right Side	< 1		
Malcolm X ES	4th Floor Hallway, Right Side	< 1		
Malcolm X ES	4th Floor Hallway, Left Side	< 1		
Malcolm X ES	4th Floor Hallway, Left Side	< 1		
Malcolm X ES	3rd Floor Hallway, Right Side	< 1		
Malcolm X ES	3rd Floor Hallway, Right Side	< 1		
Malcolm X ES	3rd Floor Hallway, Left Side	< 1		
Malcolm X ES	3rd Floor Hallway, Left Side	< 1		
Malcolm X ES	2nd Floor Hallway, Right Side	< 1		
Malcolm X ES	2nd Floor Hallway, Right Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Left Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Left Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Right Side	< 1		
Malcolm X ES	1st Floor Hallway, Pre-K, Right Side	< 1		
Malcolm X ES	1st Floor, Pre-K Classroom	< 1		
Malcolm X ES	1st Floor, Pre-K Classroom	< 1		
Malcolm X ES	1st Floor, Lunchroom	< 1		
Malcolm X ES	1st Floor, Lunchroom	< 1		
Malcolm X ES	1st Floor, Lunchroom, Adjacent to the Exit	< 1		
Malcolm X ES	1st Floor, Lunchroom, Adjacent to the Exit	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Mamie D Lee ES	1st Floor, Inside Room 11	< 1		
Mamie D Lee ES	1st Floor, Inside Room 11	< 1		
Mamie D Lee ES	1st Floor, Inside Room 13	< 1		
Mamie D Lee ES	1st Floor, Inside Room 13	< 1		
Mamie D Lee ES	1st Floor, Inside Room 15	< 1		
Mamie D Lee ES	1st Floor, Inside Room 15	< 1		
Mamie D Lee ES	1st Floor, Inside Room 17	< 1		
Mamie D Lee ES	1st Floor, Inside Room 17	< 1		
Mamie D Lee ES	1st Floor, Inside Room 19	< 1		
Mamie D Lee ES	1st Floor, Inside Room 19	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 20	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 20	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 22	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 22	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 24	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 24	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 26	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 26	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 28	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 28	< 1		
Mamie D Lee ES	1st Floor, Inside Cafeteria	< 1		
Mamie D Lee ES	1st Floor, Inside Cafeteria	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Mamie D Lee ES	1st Floor Hallway, Outside PE Office	< 1		
Mamie D Lee ES	1st Floor Hallway, Outside PE Office	< 1		
Mamie D Lee ES	1st Floor, Inside Room 10	< 1		
Mamie D Lee ES	1st Floor, Inside Room 10	< 1		
Mamie D Lee ES	1st Floor, Inside Room 12	< 1		
Mamie D Lee ES	1st Floor, Inside Room 12	< 1		
Mamie D Lee ES	1st Floor Hallway	< 1		
Mamie D Lee ES	1st Floor Hallway	< 1		
Mamie D Lee ES	1st Floor, Medical and Dental Office	< 1		
Mamie D Lee ES	1st Floor, Medical and Dental Office	< 1		
Mamie D Lee ES	1st Floor, Inside Kitchen	< 1		
Mamie D Lee ES	1st Floor, Inside Kitchen	< 1		
Mamie D Lee ES	1st Floor, Inside Room 14	< 1		
Mamie D Lee ES	1st Floor, Inside Room 14	< 1		
Mamie D Lee ES	1st Floor, Inside Room 16	< 1		
Mamie D Lee ES	1st Floor, Inside Room 16	< 1		
Mamie D Lee ES	1st Floor, Inside Room 18	< 1		
Mamie D Lee ES	1st Floor, Inside Room 18	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 21	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 21	< 1		
Mamie D Lee ES	2nd Floor Hallway	< 1		
Mamie D Lee ES	2nd Floor Hallway	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 23	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 23	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 25	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 25	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 27	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 27	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 29	< 1		
Mamie D Lee ES	2nd Floor, Inside Room 29	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Mann ES	2nd Floor, Adjacent to Room 205	< 1		
Mann ES	2nd Floor, Adjacent to Room 205	< 1		
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	Inside Cafeteria	< 1		
Mann ES	Inside Cafeteria	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Maury ES	Inside Cafeteria	< 1		
Maury ES	Inside Cafeteria	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Up)	1.4		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Maury ES	Basement, Between Rooms W022 & W020 (Up)	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W030	< 1		
Maury ES	Basement, In Room W030	1.2		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E140	< 1		
Maury ES	1st Floor, In Room E140	< 1		
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	2nd Floor, Across from Room 202	< 1		
Meyer ES	2nd Floor, Across from Room 202	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Miner ES	2nd Floor, Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Bathroom (Right Side)	< 1		
Miner ES	2nd Floor, Bathroom (Right Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 209	< 1		
Miner ES	2nd Floor, Inside Classroom 209	< 1		
Miner ES	2nd Floor, Inside Classroom 211	< 1		
Miner ES	2nd Floor, Inside Classroom 211	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 213	< 1		
Miner ES	2nd Floor, Inside Classroom 213	< 1		
Miner ES	2nd Floor, Inside Classroom 215	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Miner ES	2nd Floor, Inside Classroom 215	< 1		
Miner ES	2nd Floor, Inside Classroom 217	< 1		
Miner ES	2nd Floor, Inside Classroom 217	< 1		
Miner ES	2nd Floor, Inside Classroom 219	< 1		
Miner ES	2nd Floor, Inside Classroom 219	< 1		
Miner ES	2nd Floor, Inside Classroom 225	< 1		
Miner ES	2nd Floor, Inside Classroom 225	< 1		
Miner ES	2nd Floor, Inside Classroom 227	< 1		
Miner ES	2nd Floor, Inside Classroom 227	< 1		
Miner ES	2nd Floor, Inside Classroom 229	< 1		
Miner ES	2nd Floor, Inside Classroom 229	< 1		
Miner ES	2nd Floor, Inside Classroom 231	< 1		
Miner ES	2nd Floor, Inside Classroom 231	< 1		
Miner ES	2nd Floor, Inside Classroom 233	< 1		
Miner ES	2nd Floor, Inside Classroom 233	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Pet Room (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 234	1.1		
Miner ES	2nd Floor, Inside Classroom 234	< 1		
Miner ES	2nd Floor, Inside Classroom 238	< 1		
Miner ES	2nd Floor, Inside Classroom 238	< 1		
Miner ES	2nd Floor Bathroom (Right Side)	< 1		
Miner ES	2nd Floor Bathroom (Right Side)	< 1		
Miner ES	2nd Floor Bathroom (Left Side)	< 1		
Miner ES	2nd Floor Bathroom (Left Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 255	< 1		
Miner ES	2nd Floor, Inside Classroom 255	< 1		
Miner ES	2nd Floor, Pet Room (Right Side)	< 1		
Miner ES	2nd Floor, Pet Room (Right Side)	< 1		
Miner ES	2nd Floor, Inside Classroom 251	< 1		
Miner ES	2nd Floor, Inside Classroom 251	< 1		
Miner ES	2nd Floor, Inside Classroom 249	< 1		
Miner ES	2nd Floor, Inside Classroom 249	< 1		
Miner ES	2nd Floor, Inside Classroom 243	< 1		
Miner ES	2nd Floor, Inside Classroom 243	< 1		
Miner ES	2nd Floor, Inside Classroom 241	< 1		
Miner ES	2nd Floor, Inside Classroom 241	< 1		
Miner ES	1st Floor, Adjacent to Room 146 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 146 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Short)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Tall)	< 1		
Miner ES	1st Floor, Adjacent to Room 136 (Tall)	< 1		
Miner ES	1st Floor, Inside Room 135	< 1		
Miner ES	1st Floor, Inside Room 135	< 1		
Miner ES	1st Floor, Inside Room 133	< 1		
Miner ES	1st Floor, Inside Room 133	< 1		
Miner ES	1st Floor, Inside Room 131	< 1		
Miner ES	1st Floor, Inside Room 131	< 1		
Miner ES	1st Floor, Inside Room 129	< 1		
Miner ES	1st Floor, Inside Room 129	< 1		
Miner ES	1st Floor, Inside Room 127	< 1		
Miner ES	1st Floor, Inside Room 127	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Miner ES	1st Floor, Inside Room 123	< 1		
Miner ES	1st Floor, Inside Room 123	< 1		
Miner ES	1st Floor, Inside Room 121	< 1		
Miner ES	1st Floor, Inside Room 121	< 1		
Miner ES	1st Floor, Inside Room 119	< 1		
Miner ES	1st Floor, Inside Room 119	< 1		
Miner ES	1st Floor, Inside Room 117	< 1		
Miner ES	1st Floor, Inside Room 117	< 1		
Miner ES	1st Floor, Inside Room 115	< 1		
Miner ES	1st Floor, Inside Room 115	< 1		
Miner ES	1st Floor, Inside Room 111	< 1		
Miner ES	1st Floor, Inside Room 111	< 1		
Miner ES	1st Floor, Inside Room 109	< 1		
Miner ES	1st Floor, Inside Room 109	< 1		
Miner ES	1st Floor, Inside Room 107	< 1		
Miner ES	1st Floor, Inside Room 107	< 1		
Miner ES	1st Floor, Inside Room 105	< 1		
Miner ES	1st Floor, Inside Room 105	< 1		
Miner ES	1st Floor, Inside Room 103	< 1		
Miner ES	1st Floor, Inside Room 103	< 1		
Miner ES	1st Floor, Inside Room 101	< 1		
Miner ES	1st Floor, Inside Room 101	< 1		
Miner ES	1st Floor Pet Center #2, Adjacent to Room 103	< 1		
Miner ES	1st Floor Pet Center #2, Adjacent to Room 103	< 1		
Miner ES	1st Floor, Inside Room 132	< 1		
Miner ES	1st Floor, Inside Room 132	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 200B	< 1		
Murch ES	2nd Floor, Across from Room 200B	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Nalle ES	1st Floor, Inside Room 118	< 1		
Nalle ES	1st Floor, Inside Room 118	< 1		
Nalle ES	Basement Floor, Across from Room 130	< 1		
Nalle ES	Basement Floor, Across from Room 130	< 1		
Nalle ES	2nd Floor, Across from Room 230	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Nalle ES	2nd Floor, Across from Room 230	< 1		
Nalle ES	2nd Floor, Across from Library	< 1		
Nalle ES	2nd Floor, Across from Library	< 1		
Nalle ES	2nd Floor, Across from Room 206	< 1		
Nalle ES	2nd Floor, Across from Room 206	< 1		
Nalle ES	2nd Floor, Adjacent to Room 211	< 1		
Nalle ES	2nd Floor, Adjacent to Room 211	< 1		
Nalle ES	1st Floor, Adjacent to Room 111	< 1		
Nalle ES	1st Floor, Adjacent to Room 111	< 1		
Nalle ES	1st Floor, Across from Room 106	< 1		
Nalle ES	1st Floor, Across from Room 106	< 1		
Nalle ES	Basement Floor, Across from Room 6	< 1		
Nalle ES	Basement Floor, Across from Room 6	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (1)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (1)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (2)	< 1		
Nalle ES	Basement Floor, Inside Cafeteria (2)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.4		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.8		
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Outside Resourse Room	< 1		
Orr ES	1st Floor, Outside Resourse Room	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Oyster ES	1st Floor, Inside Room 107	< 1		
Oyster ES	1st Floor, Inside Room 107	< 1		
Oyster ES	1st Floor Hallway (Low)	< 1		
Oyster ES	1st Floor Hallway (Low)	< 1		
Oyster ES	1st Floor Hallway (High)	< 1		
Oyster ES	1st Floor Hallway (High)	< 1		
Oyster ES	2nd Floor, Inside Room 201	< 1		
Oyster ES	2nd Floor, Inside Room 201	< 1		
Oyster ES	2nd Floor, Inside Room 202	< 1		
Oyster ES	2nd Floor, Inside Room 202	< 1		
Oyster ES	2nd Floor, Inside Room 210	< 1		
Oyster ES	2nd Floor, Inside Room 210	< 1		
Oyster ES	2nd Floor, Inside Room 211	< 1		
Oyster ES	2nd Floor, Inside Room 211	< 1		
Oyster ES	2nd Floor, Gymnasium (Low)	< 1		
Oyster ES	2nd Floor, Gymnasium (Low)	< 1		
Oyster ES	2nd Floor, Gymnasium (High)	< 1		
Oyster ES	2nd Floor, Gymnasium (High)	< 1		
Oyster ES	3rd Floor, Inside Room 301	< 1		
Oyster ES	3rd Floor, Inside Room 301	< 1		
Oyster ES	3rd Floor, Inside Room 304	< 1		
Oyster ES	3rd Floor, Inside Room 304	< 1		
Oyster ES	3rd Floor, Inside Room 308	< 1		
Oyster ES	3rd Floor, Inside Room 308	< 1		
Oyster ES	3rd Floor, Inside Room 313	< 1		
Oyster ES	3rd Floor, Inside Room 313	< 1		
Oyster ES	3rd Floor Hallway (Low)	< 1		
Oyster ES	3rd Floor Hallway (Low)	< 1		
Oyster ES	3rd Floor Hallway (High)	< 1		
Oyster ES	3rd Floor Hallway (High)	< 1		
Oyster ES	3rd Floor, Inside Room 316	< 1		
Oyster ES	3rd Floor, Inside Room 316	< 1		
Oyster ES	4th Floor, Inside Room 401	< 1		
Oyster ES	4th Floor, Inside Room 401	< 1		
Oyster ES	4th Floor, Inside Room 405	< 1		
Oyster ES	4th Floor, Inside Room 405	< 1		
Oyster ES	4th Floor, Inside Room 407	< 1		
Oyster ES	4th Floor, Inside Room 407	< 1		
Oyster ES	4th Floor, Inside Room 410	< 1		
Oyster ES	4th Floor, Inside Room 410	< 1		
Oyster ES	4th Floor, Inside Room 412	< 1		
Oyster ES	4th Floor, Inside Room 412	< 1		
Oyster ES	4th Floor, Inside Room 415	< 1		
Oyster ES	4th Floor, Inside Room 415	< 1		
Oyster ES	4th Floor Hallway (Low)	< 1		
Oyster ES	4th Floor Hallway (Low)	< 1		
Oyster ES	4th Floor Hallway (High)	< 1		
Oyster ES	4th Floor Hallway (High)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Parkview ES	Basement Floor Hallway to Cafeteria	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Parkview ES	Basement Floor Hallway to Cafeteria	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 101	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 101	< 1		
Parkview ES	Basement Floor, Inside Room 103	< 1		
Parkview ES	Basement Floor, Inside Room 103	< 1		
Parkview ES	Basement Floor, Inside Room 102	< 1		
Parkview ES	Basement Floor, Inside Room 102	< 1		
Parkview ES	Basement Floor, Inside Room 101	< 1		
Parkview ES	Basement Floor, Inside Room 101	< 1		
Parkview ES	Basement Floor Hallway, Adjacent to Room 114	1.2		
Parkview ES	Basement Floor Hallway, Adjacent to Room 114	1.3		
Parkview ES	Basement Floor, Inside Room 114	< 1		
Parkview ES	Basement Floor, Inside Room 114	< 1		
Parkview ES	Basement Floor, Inside Room 113	< 1		
Parkview ES	Basement Floor, Inside Room 113	< 1		
Parkview ES	Basement Floor, Inside Room 112	< 1		
Parkview ES	Basement Floor, Inside Room 112	< 1		
Parkview ES	Basement Floor Hallway to Gymnasium	< 1		
Parkview ES	Basement Floor Hallway to Gymnasium	< 1		
Parkview ES	1st Floor Hallway, Across from Room 208	< 1		
Parkview ES	1st Floor Hallway, Across from Room 208	< 1		
Parkview ES	1st Floor, Inside Room 213	< 1		
Parkview ES	1st Floor, Inside Room 213	< 1		
Parkview ES	1st Floor, Inside Room 214	< 1		
Parkview ES	1st Floor, Inside Room 214	< 1		
Parkview ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Parkview ES	1st Floor Hallway, Adjacent to Main Office	< 1		
Parkview ES	1st Floor Hallway, Across from Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Across from Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Inside Teacher's Lounge 207	< 1		
Parkview ES	1st Floor Hallway, Inside Teacher's Lounge 207	< 1		
Parkview ES	1st Floor, Inside Room 212	< 1		
Parkview ES	1st Floor, Inside Room 212	< 1		
Parkview ES	1st Floor, Inside Room 215	< 1		
Parkview ES	1st Floor, Inside Room 215	< 1		
Parkview ES	2nd Floor Hallway, Across from Library	< 1		
Parkview ES	2nd Floor Hallway, Across from Library	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 301	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 301	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 307	< 1		
Parkview ES	2nd Floor Hallway, Across from Room 307	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Payne ES	1st Floor, Outside Library	< 1		
Payne ES	1st Floor, Outside Library	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Payne ES	1st Floor, Inside Cafeteria	< 1		
Payne ES	1st Floor, Inside Cafeteria	< 1		
Payne ES	1st Floor, Beside Nurse's Suite	< 1		
Payne ES	1st Floor, Beside Nurse's Suite	< 1		
Payne ES	1st Floor, Across from Room 133	< 1		
Payne ES	1st Floor, Across from Room 133	< 1		
Payne ES	2nd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	2nd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	2nd Floor, Beside Room 212	< 1		
Payne ES	2nd Floor, Beside Room 212	< 1		
Payne ES	2nd Floor, Beside Room 224	< 1		
Payne ES	2nd Floor, Beside Room 224	< 1		
Payne ES	3rd Floor, Adjacent to Women's Restroom	< 1		
Payne ES	3rd Floor, Adjacent to Women's Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Peabody ES	1st Floor Outside Main Office	< 1		
Peabody ES	1st Floor Outside Main Office	< 1		
Peabody ES	2nd Floor, Adjacent to Room 6	< 1		
Peabody ES	2nd Floor, Adjacent to Room 6	< 1		
Peabody ES	3rd Floor Outside Room 10	< 1		
Peabody ES	3rd Floor Outside Room 10	< 1		
Peabody ES	4th Floor, Open Space, Sink #1	< 1		
Peabody ES	4th Floor, Open Space, Sink #1	< 1		
Peabody ES	4th Floor, Open Space, Sink #2	3.4		
Peabody ES	4th Floor, Open Space, Sink #2	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Powell ES	2nd Floor Hallway	< 1		
Powell ES	2nd Floor Hallway	1.2		
Powell ES	2nd Floor, Adjacent to Classroom 219	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 219	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 203	< 1		
Powell ES	2nd Floor, Adjacent to Classroom 203	< 1		
Powell ES	1st Floor, Adjacent to Classroom 114	< 1		
Powell ES	1st Floor, Adjacent to Classroom 114	< 1		
Powell ES	1st Floor, Adjacent to Classroom 108	< 1		
Powell ES	1st Floor, Adjacent to Classroom 108	< 1		
Powell ES	1st Floor, Adjacent to Classroom 109	< 1		
Powell ES	1st Floor, Adjacent to Classroom 109	< 1		
Powell ES	1st Floor, Adjacent to Classroom 103	< 1		
Powell ES	1st Floor, Adjacent to Classroom 103	< 1		
Powell ES	1st Floor, Inside Lunch Room	< 1		
Powell ES	1st Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Raymond ES	3rd Floor Hallway, Outside Room 36	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 36	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 117	1.2		
Raymond ES	1st Floor, Inside Room 117	1.9		
Raymond ES	1st Floor, Inside Room 113	< 1		
Raymond ES	1st Floor, Inside Room 113	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
River Terrace ES	Hallway Outside Air Quality Room	< 1		
River Terrace ES	Hallway Outside Air Quality Room	< 1		
River Terrace ES	Hallway Outside Teacher's Restroom	< 1		
River Terrace ES	Hallway Outside Teacher's Restroom	< 1		
River Terrace ES	Hallway Outside Room 24	< 1		
River Terrace ES	Hallway Outside Room 24	< 1		
River Terrace ES	Hallway Outside Main Office	< 1		
River Terrace ES	Hallway Outside Main Office	< 1		
River Terrace ES	Hallway Outside Boys Restroom	< 1		
River Terrace ES	Hallway Outside Boys Restroom	< 1		
River Terrace ES	Inside Room 14	< 1		
River Terrace ES	Inside Room 14	< 1		
River Terrace ES	Inside Room 15/16 (High)	< 1		
River Terrace ES	Inside Room 15/16 (High)	< 1		
River Terrace ES	Inside Room 15/16 (Low)	< 1		
River Terrace ES	Inside Room 15/16 (Low)	< 1		
River Terrace ES	Hallway Outside Room 19	< 1		
River Terrace ES	Hallway Outside Room 19	< 1		
River Terrace ES	Inside Lunch Room (High)	< 1		
River Terrace ES	Inside Lunch Room (High)	< 1		
River Terrace ES	Inside Nurse's Suite (High)	< 1		
River Terrace ES	Inside Nurse's Suite (High)	< 1		
River Terrace ES	Inside Nurse's Suite (Low)	< 1		
River Terrace ES	Inside Nurse's Suite (Low)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Shepherd ES	1st Floor, Inside Room 132	< 1		
Shepherd ES	1st Floor, Inside Room 132	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Shepherd ES	1st Floor, Inside Room 101	< 1		
Shepherd ES	1st Floor, Inside Room 101	< 1		
Shepherd ES	1st Floor, Inside Lunch Room	< 1		
Shepherd ES	1st Floor, Inside Lunch Room	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 214	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 214	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 220	< 1		
Shepherd ES	2nd Floor Hallway, Inside Room 220	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Counselor's Office	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 122	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 122	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Shepherd ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 100	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 100	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Shepherd ES	1st Floor Hallway, Adjacent to Room 102	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Simon ES	Ground Floor, Inside Room 1	< 1		
Simon ES	Ground Floor, Inside Room 2	< 1		
Simon ES	Ground Floor, Adjacent to Room 3	< 1		
Simon ES	Ground Floor, Adjacent to Room 3	< 1		
Simon ES	Ground Floor, Adjacent to Room 13	< 1		
Simon ES	Ground Floor, Adjacent to Room 13	< 1		
Simon ES	Ground Floor, Inside Room 15	< 1		
Simon ES	Ground Floor, Inside Room 15	< 1		
Simon ES	1st Floor Lobby, Inside Main Office	< 1		
Simon ES	1st Floor Lobby, Inside Main Office	< 1		
Simon ES	1st Floor, Inside Room 107	< 1		
Simon ES	1st Floor, Inside Room 107	1.7		
Simon ES	1st Floor, Outside Girls Restroom	< 1		
Simon ES	1st Floor, Outside Girls Restroom	< 1		
Simon ES	1st Floor, Outside Boys Restroom	< 1		
Simon ES	1st Floor, Outside Boys Restroom	< 1		
Simon ES	2nd Floor, Adjacent to Room 203	< 1		
Simon ES	2nd Floor, Adjacent to Room 203	< 1		
Simon ES	2nd Floor, Adjacent to Room 213	< 1		
Simon ES	2nd Floor, Adjacent to Room 213	< 1		
Simon ES	3rd Floor, Adjacent to Room 303	< 1		
Simon ES	3rd Floor, Adjacent to Room 303	< 1		
Simon ES	3rd Floor, Adjacent to Room 313	< 1		
Simon ES	3rd Floor, Adjacent to Room 313	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Sousa ES	1st Floor, Outside Room C101 (High)	< 1		
Sousa ES	1st Floor, Outside Room C101 (High)	< 1		
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (Low)	< 1		
Sousa ES	1st Floor, Left of Stage (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Room B104 1	2.2		
Sousa ES	1st Floor, Inside Room B104 1	< 1		
Sousa ES	1st Floor, Inside Room B104 2	1.1		
Sousa ES	1st Floor, Inside Room B104 2	< 1		
Sousa ES	1st Floor, Inside Room B104 3	5.8		
Sousa ES	1st Floor, Inside Room B104 3	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 5	2.2		
Sousa ES	1st Floor, Inside Room B104 5	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B109 1	1.3		
Sousa ES	1st Floor, Inside Room B109 1	< 1		
Sousa ES	1st Floor, Inside Room B109 2	3.5		
Sousa ES	1st Floor, Inside Room B109 2	2.1		
Sousa ES	1st Floor, Inside Room B109 3	8.7		
Sousa ES	1st Floor, Inside Room B109 3	< 1		
Sousa ES	1st Floor, Inside Room B109 4	1.3		
Sousa ES	1st Floor, Inside Room B109 4	< 1		
Sousa ES	1st Floor, Inside Room B109 5	2.4		
Sousa ES	1st Floor, Inside Room B109 5	< 1		
Sousa ES	1st Floor, Inside Room B109 6	9.7		
Sousa ES	1st Floor, Inside Room B109 6	1.8		
Sousa ES	2nd Floor, Inside Room A209 1	1.2		
Sousa ES	2nd Floor, Inside Room A209 1	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	2nd Floor, Inside Room A209 2	< 1		
Sousa ES	2nd Floor, Inside Room A209 2	4.1		
Sousa ES	2nd Floor, Inside Room A209 3	1.3		
Sousa ES	2nd Floor, Inside Room A209 3	< 1		
Sousa ES	2nd Floor, Inside Room A209 4	2.2		
Sousa ES	2nd Floor, Inside Room A209 4	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		
Sousa ES	2nd Floor, Inside Room A209 6	1.4		
Sousa ES	2nd Floor, Inside Room A209 6	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 3	2.2		
Sousa ES	2nd Floor, Inside Room B204 3	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 6	1.9		
Sousa ES	2nd Floor, Inside Room B204 6	1.3		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	1.1		
Sousa ES	3rd Floor, Inside Room B304 3	< 1		
Sousa ES	3rd Floor, Inside Room B304 3	2.3		
Sousa ES	3rd Floor, Inside Room B304 4	2.2		
Sousa ES	3rd Floor, Inside Room B304 4	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B904 1	9		
Sousa ES	3rd Floor, Inside Room B904 1		22	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	3rd Floor, Inside Room B904 2		24	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 2 - Retest</i>	1.5		
Sousa ES	<i>3rd Floor, Inside Room B904 2 - Retest</i>	< 1		
Sousa ES	3rd Floor, Inside Room B904 2	5.7		
Sousa ES	3rd Floor, Inside Room B904 3	3.2		
Sousa ES	3rd Floor, Inside Room B904 3	< 1		
Sousa ES	3rd Floor, Inside Room B904 4	6.8		
Sousa ES	3rd Floor, Inside Room B904 4	< 1		
Sousa ES	3rd Floor, Inside Room B904 5	2.5		
Sousa ES	3rd Floor, Inside Room B904 5	< 1		
Sousa ES	3rd Floor, Inside Room B904 6	7.5		
Sousa ES	3rd Floor, Inside Room B904 6	< 1		
Percentage of Passed Samples				97.96%
Percentage of Failed Samples				2.04%
Stanton ES	3rd Floor, Adjacent to Classroom 308	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Stanton ES	3rd Floor, Adjacent to Classroom 308	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 313	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 313	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 307	< 1		
Stanton ES	3rd Floor, Adjacent to Classroom 307	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 209	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 209	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 204	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 204	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 210	< 1		
Stanton ES	2nd Floor, Adjacent to Classroom 210	< 1		
Stanton ES	1st Floor, Adjacent to the Bathroom	< 1		
Stanton ES	1st Floor, Adjacent to the Bathroom	< 1		
Stanton ES	1st Floor, Adjacent to Classroom 106	< 1		
Stanton ES	1st Floor, Adjacent to Classroom 106	< 1		
Stanton ES	1st Floor, Adjacent to Main Entrance	< 1		
Stanton ES	1st Floor, Adjacent to Main Entrance	< 1		
Stanton ES	Ground Floor, Inside Lunch Room	< 1		
Stanton ES	Ground Floor, Inside Lunch Room	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Stoddert ES	1st Floor, Across from Cafeteria (Tall)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Tall)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Short)	< 1		
Stoddert ES	1st Floor, Across from Cafeteria (Short)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Tall)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Tall)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Short)	< 1		
Stoddert ES	2nd Floor, Across from Elevator, Adjacent to Boys/Girls Restroom (Short)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 2)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 2)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 3)	< 1		
Stoddert ES	2nd Floor, Inside Room 227 (Sink 3)	< 1		
Stoddert ES	2nd Floor, Inside Room 244 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 244 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 245 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 245 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 246 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 246 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 247 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 247 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 231 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 231 (Sink 1)	< 1		
Stoddert ES	2nd Floor, Inside Room 232 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 232 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 233 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 233 (Sink1)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Stoddert ES	2nd Floor, Inside Room 234 (Sink1)	< 1		
Stoddert ES	2nd Floor, Inside Room 234 (Sink1)	< 1		
Stoddert ES	1st Floor, Inside Room 134 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 134 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 133 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 133 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 132 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 132 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 131 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 131 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 146 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 146 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 145 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 145 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 147 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 147 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 144 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 144 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 142 (Sink 1)	< 1		
Stoddert ES	1st Floor, Inside Room 142 (Sink 1)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Thomson ES	3rd Floor, Adjacent to the Elevator (Left Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Left Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Right Side)	< 1		
Thomson ES	3rd Floor, Adjacent to the Elevator (Right Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Left Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Left Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Right Side)	< 1		
Thomson ES	2nd Floor, Adjacent to Room 201 (Right Side)	< 1		
Thomson ES	1st Floor, Inside Room 130	< 1		
Thomson ES	1st Floor, Inside Room 130	< 1		
Thomson ES	1st Floor, Inside Room 129	< 1		
Thomson ES	1st Floor, Inside Room 129	< 1		
Thomson ES	1st Floor, Inside Room 124	< 1		
Thomson ES	1st Floor, Inside Room 124	< 1		
Thomson ES	1st Floor, Inside Room 123	< 1		
Thomson ES	1st Floor, Inside Room 123	< 1		
Thomson ES	1st Floor, Inside Room 127	< 1		
Thomson ES	1st Floor, Inside Room 127	< 1		
Thomson ES	1st Floor, Inside Room 125	< 1		
Thomson ES	1st Floor, Inside Room 125	< 1		
Thomson ES	1st Floor, Inside Room 113	< 1		
Thomson ES	1st Floor, Inside Room 113	< 1		
Thomson ES	1st Floor, Inside Room 112	< 1		
Thomson ES	1st Floor, Inside Room 112	< 1		
Thomson ES	1st Floor, Inside Room 114	< 1		
Thomson ES	1st Floor, Inside Room 114	< 1		
Thomson ES	1st Floor, Inside Room 115	< 1		
Thomson ES	1st Floor, Inside Room 115	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Ground Floor, Adjacent to Main Entrance	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Left Side)	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Left Side)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Thomson ES	Basement Floor, Inside Lunch Room (Right Side)	< 1		
Thomson ES	Basement Floor, Inside Lunch Room (Right Side)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Truesdell ES	3rd Floor Hallway, Outside Room 300	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 300	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 308	< 1		
Truesdell ES	3rd Floor Hallway, Outside Room 308	< 1		
Truesdell ES	2nd Floor, Inside Room 217	< 1		
Truesdell ES	2nd Floor, Inside Room 217	< 1		
Truesdell ES	2nd Floor, Inside Room 216	< 1		
Truesdell ES	2nd Floor, Inside Room 216	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 212	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 212	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 200	< 1		
Truesdell ES	2nd Floor Hallway, Outside Room 200	< 1		
Truesdell ES	2nd Floor, Inside Room 201	3.1		
Truesdell ES	2nd Floor, Inside Room 201	2.8		
Truesdell ES	2nd Floor, Inside Room 200	12		
Truesdell ES	2nd Floor, Inside Room 200	1.4		
Truesdell ES	1st Floor, Inside Room 115	< 1		
Truesdell ES	1st Floor, Inside Room 115	< 1		
Truesdell ES	1st Floor, Inside Room 114	< 1		
Truesdell ES	1st Floor, Inside Room 114	< 1		
Truesdell ES	1st Floor Hallway, Outside Room 104	< 1		
Truesdell ES	1st Floor Hallway, Outside Room 104	< 1		
Truesdell ES	1st Floor, Outside Girls/Boys Restroom	< 1		
Truesdell ES	1st Floor, Outside Girls/Boys Restroom	< 1		
Truesdell ES	1st Floor, Inside Multi-Purpose Room	< 1		
Truesdell ES	1st Floor, Inside Multi-Purpose Room	< 1		
Truesdell ES	1st Floor, Inside Room 100	< 1		
Truesdell ES	1st Floor, Inside Room 100	< 1		
Truesdell ES	1st Floor, Inside Room 101	< 1		
Truesdell ES	1st Floor, Inside Room 101	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 218	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 218	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 227	< 1		
Truesdell ES	Annex, 2nd Floor Hallway, Outside Room 227	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 126	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 126	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 117	< 1		
Truesdell ES	Annex, 1st Floor Hallway, Outside Room 117	< 1		
Truesdell ES	Annex, Basement, Inside Nurse's Suite	< 1		
Truesdell ES	Annex, Basement, Inside Nurse's Suite	1.1		
Truesdell ES	Annex, Basement Hallway, Outside Room 013	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Truesdell ES	Annex, Basement Hallway, Outside Room 013	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Walker Jones ES	Basement, Across from Room 032 (High)	< 1		
Walker Jones ES	Basement, Across from Room 032 (High)	< 1		
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Inside Room 032	4.2		
Walker Jones ES	Basement, Inside Room 032	< 1		
Walker Jones ES	Basement, Inside Room 031	1.8		
Walker Jones ES	Basement, Inside Room 031	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 105	1.1		
Walker Jones ES	1st Floor, Inside Room 105	< 1		
Walker Jones ES	1st Floor, Inside Room 106	3		
Walker Jones ES	1st Floor, Inside Room 106	< 1		
Walker Jones ES	1st Floor, Inside Room 108	1.2		
Walker Jones ES	1st Floor, Inside Room 108	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	1.7		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 119	13		
Walker Jones ES	1st Floor, Inside Room 119	2.4		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 123	1.6		
Walker Jones ES	1st Floor, Inside Room 123	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 128	2.9		
Walker Jones ES	1st Floor, Inside Room 128	< 1		
Walker Jones ES	2nd Floor, Inside Room 201	13		
Walker Jones ES	2nd Floor, Inside Room 201	2.4		
Walker Jones ES	2nd Floor, Inside Room 203	1.5		
Walker Jones ES	2nd Floor, Inside Room 203	< 1		
Walker Jones ES	2nd Floor, Inside Room 205	5.3		
Walker Jones ES	2nd Floor, Inside Room 205	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	1.3		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	2nd Floor, Inside Room 208	1.6		
Walker Jones ES	2nd Floor, Inside Room 208	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 212	3.6		
Walker Jones ES	2nd Floor, Inside Room 212	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	5.9		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	1.5		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	2.8		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	1.2		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 220	1.8		
Walker Jones ES	2nd Floor, Inside Room 220	< 1		
Walker Jones ES	2nd Floor, Inside Room 221	3		
Walker Jones ES	2nd Floor, Inside Room 221	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	2.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	11		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)		54	Lead filter was installed
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)	5.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.4		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.2		
Walker Jones ES	2nd Floor, Inside Room 228	5		
Walker Jones ES	2nd Floor, Inside Room 228	< 1		
Walker Jones ES	2nd Floor, Inside Room 230	3.5		
Walker Jones ES	2nd Floor, Inside Room 230	< 1		
Walker Jones ES	2nd Floor, Inside Main Office	5.8		
Walker Jones ES	2nd Floor, Inside Main Office	2.9		
Walker Jones ES	3rd Floor, Inside Room 300	1.6		
Walker Jones ES	3rd Floor, Inside Room 300	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 310		18	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	1.6		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	2.2		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	1.9		
Walker Jones ES	3rd Floor, Adjacent to Room 310		42	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	2.9		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	2.9		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	2		
Walker Jones ES	3rd Floor, Adjacent to Room 310		59	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	6		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	3.7		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	2.6		
Walker Jones ES	3rd Floor, Adjacent to Room 320		35	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	7.3		
Walker Jones ES	3rd Floor, Adjacent to Room 320 - Retest	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320 - Retest	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320		16	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.7		
Walker Jones ES	3rd Floor, Adjacent to Room 320 - Retest	1.1		
Walker Jones ES	3rd Floor, Adjacent to Room 320 - Retest	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320	11		
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.6		
Walker Jones ES	3rd Floor, Adjacent to Room 324	4.2		
Walker Jones ES	3rd Floor, Adjacent to Room 324	1.4		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324		31	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 324	3.8		
Walker Jones ES	3rd Floor, Adjacent to Room 324 - Retest	1.4		
Walker Jones ES	3rd Floor, Adjacent to Room 324 - Retest	1.3		
Percentage of Passed Samples				93.75%
Percentage of Failed Samples				6.25%
West ES	Mezzanine, Outside Girls Restroom	< 1		
West ES	Mezzanine, Outside Girls Restroom	< 1		
West ES	1st Floor, Inside Computer Lab (Left)	< 1		
West ES	1st Floor, Inside Computer Lab (Left)	< 1		
West ES	1st Floor, Inside Computer Lab (Right)	< 1		
West ES	1st Floor, Inside Computer Lab (Right)	< 1		
West ES	1st Floor, Inside Book Storage (Left)	< 1		
West ES	1st Floor, Inside Book Storage (Left)	< 1		
West ES	1st Floor, Inside Book Storage (Right)	< 1		
West ES	1st Floor, Inside Book Storage (Right)	< 1		
West ES	1st Floor, Inside Teacher's Lounge	< 1		
West ES	1st Floor, Inside Teacher's Lounge	< 1		
West ES	1st Floor, Outside Teacher's Lounge	< 1		
West ES	1st Floor, Outside Teacher's Lounge	< 1		
West ES	1st Floor, Inside Lunch Room	< 1		
West ES	1st Floor, Inside Lunch Room	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Left)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Left)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Right)	< 1		
West ES	1st Floor, Adjacent to Gymnasium (Right)	< 1		
West ES	1st Floor, Inside Gymnasium (Left)	< 1		
West ES	1st Floor, Inside Gymnasium (Left)	< 1		
West ES	1st Floor, Inside Gymnasium (Right)	< 1		
West ES	1st Floor, Inside Gymnasium (Right)	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
West ES	Ground Floor Hallway, Outside Main Office	< 1		
West ES	Ground Floor Hallway, Outside Main Office	< 1		
West ES	Ground Floor Hallway, Outside Girls Restroom	< 1		
West ES	Ground Floor Hallway, Outside Girls Restroom	< 1		
West ES	Ground Floor, Inside Daycare	< 1		
West ES	Ground Floor, Inside Daycare	< 1		
West ES	Ground Floor, Inside Health Suite	< 1		
West ES	Ground Floor, Inside Health Suite	< 1		
West ES	Ground Floor Hallway, Adjacent to Main Lobby	< 1		
West ES	Ground Floor Hallway, Adjacent to Main Lobby	< 1		
West ES	Inside Pre-K (Left)	< 1		
West ES	Inside Pre-K (Left)	< 1		
West ES	Inside Pre-K (Right)	< 1		
West ES	Inside Pre-K (Right)	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Whittier ES	2nd Floor, Across from Room 202	< 1		
Whittier ES	2nd Floor, Across from Room 202	1.6		
Whittier ES	1st Floor, Across from Room 102A	< 1		
Whittier ES	1st Floor, Across from Room 102A	< 1		
Whittier ES	Basement Floor, Across from Room 002	< 1		
Whittier ES	Basement Floor, Across from Room 002	< 1		
Whittier ES	3rd Floor, Across from Room 303C	1.4		
Whittier ES	3rd Floor, Across from Room 303C	2.2		
Whittier ES	3rd Floor, Across from Room 304	2.6		
Whittier ES	3rd Floor, Across from Room 304	2.8		
Whittier ES	2nd Floor, Adjacent to Health Suite	< 1		
Whittier ES	2nd Floor, Adjacent to Health Suite	< 1		
Whittier ES	2nd Floor, Adjacent to Main Office	< 1		
Whittier ES	2nd Floor, Adjacent to Main Office	< 1		
Whittier ES	1st Floor, Across from Auditorium	< 1		
Whittier ES	1st Floor, Across from Auditorium	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Bathroom	< 1		
Wilkinson ES	2nd Floor, Inside Classroom 203	< 1		
Wilkinson ES	2nd Floor, Inside Classroom 203	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Locker Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Locker Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Exit Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Exit Ground	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Teacher's Bathroom	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Teacher's Bathroom	< 1		
Wilkinson ES	Inside Pre-K, Adjacent to Main Entrance	< 1		

Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Wilkinson ES	Inside Pre-K, Adjacent to Main Entrance	< 1		
Wilkinson ES	Ground Floor, Inside Lunch Room (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Lunch Room (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Left Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Right Side)	< 1		
Wilkinson ES	Ground Floor, Inside Gymnasium (Right Side)	< 1		
Wilkinson ES	Ground Floor, Adjacent to Health Suite	< 1		
Wilkinson ES	Ground Floor, Adjacent to Health Suite	< 1		
Wilkinson ES	Ground Floor, Adjacent to Electric Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Electric Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Teacher's Room	< 1		
Wilkinson ES	Ground Floor, Adjacent to Teacher's Room	< 1		
Wilkinson ES	Ground Floor, Inside Teacher's Room	7		
Wilkinson ES	Ground Floor, Inside Teacher's Room	2.2		
Wilkinson ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Wilkinson ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #2	< 1		
Winston ES	2nd Floor, Open Space 1, #2	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		

Lead in Drinking Water
Sampling Results

School	Location	Pass	Fail	Remediation
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #2	1.6		
Winston ES	1st Floor, Open Space 1, #2	1.1		
Winston ES	1st Floor, Open Space 1, #3	4.5		
Winston ES	1st Floor, Open Space 1, #3	4.9		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
Percentage of Passed Samples				100.00%
Percentage of Failed Samples				0.00%
Totals/Percentages of All Tested Schools				
Total Number of Schools Tested				71
Total Passed Samples				2353
Total Failed Samples				9
Total Samples Collected				2362
Percentage of Passed Samples				99.62%
Percentage of Failed Samples				0.38%