

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor, Inside Teacher's Lounge	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Outside Main Office	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	1st Floor Hallway, Inside Room 101	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 301	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	3rd Floor Hallway, Inside Room 308	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 202	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	2nd Floor Hallway, Inside Room 201	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
Adams ES	1st Floor, Inside Lunch Room	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Cleveland ES	Ground Floor Hallway (Low)	< 1		
Cleveland ES	Ground Floor Hallway (Low)	< 1		
Cleveland ES	Ground Floor Hallway (High)	< 1		
Cleveland ES	Ground Floor Hallway (High)	< 1		
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 101	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 103/104	< 1		
Cleveland ES	1st Floor, Inside Room 106	1.8		
Cleveland ES	1st Floor, Inside Room 106	< 1		
Cleveland ES	1st Floor, Inside Room 111	1.1		
Cleveland ES	1st Floor, Inside Room 111	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 115	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 117	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor, Inside Room 120	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (Low)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	1st Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 201	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 207	< 1		
Cleveland ES	2nd Floor, Inside Room 212	1.2		
Cleveland ES	2nd Floor, Inside Room 212	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#1	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall B#2	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	2.8		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#3	< 1		
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Cleveland ES	2nd Floor, Inside Room 216, Wall D#4	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor, Inside Room 218	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (Low)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	2nd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 301	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 302	< 1		
Cleveland ES	3rd Floor, Inside Room 304	1.2		
Cleveland ES	3rd Floor, Inside Room 304	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 308	< 1		
Cleveland ES	3rd Floor, Inside Room 313	1.6		
Cleveland ES	3rd Floor, Inside Room 313	2.1		
Cleveland ES	3rd Floor, Inside Room 314	1.2		
Cleveland ES	3rd Floor, Inside Room 314	< 1		
Cleveland ES	3rd Floor Hallway (Low)	< 1		
Cleveland ES	3rd Floor Hallway (Low)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
Cleveland ES	3rd Floor Hallway (High)	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Davis ES	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Davis ES	1st Floor Hallway, Adjacent to Boys Restroom	< 1		
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Room 105	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Inside Health Suite	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor, Main Lobby Entrance	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor Hallway, Outside Room 104	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor, Inside Room 101	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor Hallway, Between Girls and Boys Restroom	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	1st Floor, Inside Room 115	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	Basement, Adjacent to Room 16	< 1		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2		
Davis ES	2nd Floor Hallway, Between Girls and Boys Restroom	2.5		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		
Davis ES	2nd Floor, Inside Teacher's Lounge	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Davis ES	1st Floor, Inside Teacher's Lounge	2.3		
Davis ES	1st Floor, Inside Teacher's Lounge	10		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 212	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	2nd Floor Hallway, Adjacent to Room 204	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Boys Restroom	< 1		
Davis ES	Lunch Room, Adjacent to Weight Room	1.3		
Davis ES	Lunch Room, Adjacent to Weight Room	2.1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (Low)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Inside Cafeteria (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (Low)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	< 1		
Deal JHS	Outside Cafeteria, Room NG20 (High)	3.6		
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #1	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #2	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (High) Cooler #3	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		
Deal JHS	Inside Gymnasium (Low) Cooler #4	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (Low)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Between Rooms NG12 and NG07 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (Low)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	Ground Floor, Adjacent to Room CG42 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room W100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (Low)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	1st Floor, Adjacent to Room E100 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room W200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		

Lead in Drinking Water  
Sampling Results

School	Location	Pass	Fail	Remediation
Deal JHS	2nd Floor, Adjacent to Room E200 (Low)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	2nd Floor, Adjacent to Room E200 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room W300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (Low)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	< 1		
Deal JHS	3rd Floor, Adjacent to Room E300 (High)	1.6		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 315	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	3rd Floor Hallway, Outside Room 303	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 208	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor, Inside Music Room	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	2nd Floor Hallway, Outside Room 219	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, Outside Room 120	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Upper Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor Hallway, at Main Entrance (Lower Level)	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
Eaton ES	1st Floor, Inside Nurse's Suite	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Hearst ES	2nd Floor, Adjacent to Room 208	< 1		
Hearst ES	2nd Floor, Adjacent to Room 208	< 1		
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	2nd Floor, Adjacent to Room 200	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Girls Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	1st Floor, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Tall Cooler	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
Hearst ES	Annex Bldg, Adjacent to Boys Restroom	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Houston ES	2nd Floor, Adjacent to Room 212	< 1		
Houston ES	2nd Floor, Adjacent to Room 212	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	2nd Floor, Adjacent to Library	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Room 112	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Adjacent to Storage Room	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Inside Cafeteria	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Across from Teacher's Lounge	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, East Wall, Room 147	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Inside Kindergarten Room, West Wall, Room 154	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
Houston ES	1st Floor, Adjacent to Room 156	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Janney ES	1st Floor Hallway, Outside Room 107	< 1		
Janney ES	1st Floor Hallway, Outside Room 107	< 1		
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 107	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 109	< 1		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 108	1.4		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor, Inside Room 106	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor Hallway, Outside Stairwell 4	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	1st Floor, Inside Nurse's Suite	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor, Inside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		
Janney ES	3rd Floor Hallway, Outside Room 301	< 1		
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor, Inside Room 303	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor Hallway, Outside Room 307	< 1		
Janney ES	3rd Floor, Inside Room 307	1.4		
Janney ES	3rd Floor, Inside Room 307	1.1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 309	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 308	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 306	< 1		
Janney ES	3rd Floor, Inside Room 304	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Janney ES	3rd Floor, Inside Room 304	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 302	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	3rd Floor, Inside Room 300	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor Hallway, Outside Room 201	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Inside Room 203	< 1		
Janney ES	2nd Floor, Outside Room 207	< 1		
Janney ES	2nd Floor, Outside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 207	< 1		
Janney ES	2nd Floor, Inside Room 209	1.1		
Janney ES	2nd Floor, Inside Room 209	1.2		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 208	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 206	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 202	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, Inside Room 200	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 212A	< 1		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	2nd Floor, New Wing, Inside Room 210A	3.8		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.7		
Janney ES	3rd Floor Hallway, New Wing, Outside Girls Restroom	1.3		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 110	< 1		
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		
Janney ES	1st Floor Hallway, New Wing, Outside Room 110	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor, New Wing, Inside Room 113	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (High)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor Hallway, Between Rooms 113 & 115 (Low)	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		
Janney ES	1st Floor, New Wing, Inside Room 115	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 117	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	< 1		
Janney ES	1st Floor, New Wing, Inside Room 112	4.3		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Adjacent to Girls Restroom	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	4th Floor, Outside Room 416	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Elevator	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Up)	< 1		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	1.7		
Johnson MS	3rd Floor, Adjacent to Girls Restroom (Down)	< 1		
Johnson MS	3rd Floor, Outside Room 315A (Up)	9		
Johnson MS	3rd Floor, Outside Room 315A (Up)	14		
Johnson MS	3rd Floor, Outside Room 315A (Down)	7		
Johnson MS	3rd Floor, Outside Room 315A (Down)	8.7		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor Hallway, Outside Room 216	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	2nd Floor, Outside Girls Restroom (Up)	1.1		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	2.6		
Johnson MS	2nd Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Up)	1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.1		
Johnson MS	2nd Floor, Adjacent to Elevator (Down)	1.2		
Johnson MS	1st Floor, Adjacent to Elevator	< 1		
Johnson MS	1st Floor, Adjacent to Elevator	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Up)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	< 1		
Johnson MS	1st Floor, Outside Girls Restroom (Down)	1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Auditorium Hallway, by Exit Door	< 1		
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		
Johnson MS	1st Floor, Opposite to Gym Entrance	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	1st Floor, Inside Weight Room	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, by Gymnasium Door	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	Inside Cafeteria, Outside Kitchen	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	1st Floor, Closed Wing, Adjacent to storage Room	< 1		
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Johnson MS	2nd Floor, Closed Wing, Adjacent to Men's Room	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor Hallway, Outside Main Office	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor, Inside Nurse's Suite	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor Hallway, Outside Auditorium	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	< 1		
Kenilworth ES	1st Floor, Inside Lunch Room	2.2		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Library	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Book Room	< 1		
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	3rd Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Teacher's Lounge	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	2nd Floor Hallway, Outside Room 218	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Girls Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor Hallway, Outside Boys Restroom	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Adjacent to Pre-K	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Pre-Kindergarten	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
Kenilworth ES	1st Floor, Inside Kindergarten, Room 18	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		
Langley JHS	1st Floor Hallway, Outside Principal's Office	< 1		
Langley JHS	1st Floor, Inside Classroom 149	< 1		
Langley JHS	1st Floor, Inside Classroom 149	< 1		
Langley JHS	1st Floor, Inside Classroom 143	< 1		
Langley JHS	1st Floor, Inside Classroom 143	< 1		
Langley JHS	1st Floor, Inside Classroom 137	< 1		
Langley JHS	1st Floor, Inside Classroom 137	< 1		
Langley JHS	1st Floor, Inside Classroom 133	< 1		
Langley JHS	1st Floor, Inside Classroom 133	< 1		
Langley JHS	1st Floor, Staff Lounge	< 1		
Langley JHS	1st Floor, Staff Lounge	< 1		
Langley JHS	1st Floor, Inside Classroom 125	< 1		
Langley JHS	1st Floor, Inside Classroom 125	< 1		
Langley JHS	1st Floor, Inside Classroom 122	< 1		
Langley JHS	1st Floor, Inside Classroom 122	< 1		
Langley JHS	1st Floor, Inside Classroom 113	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Langley JHS	1st Floor, Inside Classroom 113	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	1st Floor Hallway, Outside Room 104	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, Near Room SB34	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	< 1		
Langley JHS	Sub-Basement, Outside Cafeteria, On Left Hallway	1.2		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 201	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 301	3.3		
Langley JHS	3rd Floor Hallway, Outside Room 301	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	3rd Floor Hallway, Outside Room 304	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
Langley JHS	2nd Floor Hallway, Outside Room 204	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Mann ES	2nd Floor, Adjacent to Room 205	< 1		
Mann ES	2nd Floor, Adjacent to Room 205	< 1		
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	2nd Floor, Across from Room 200	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Adjacent to Room 101	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	1st Floor, Across from Room 100	< 1		
Mann ES	Inside Cafeteria	< 1		
Mann ES	Inside Cafeteria	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Maury ES	Inside Cafeteria	< 1		
Maury ES	Inside Cafeteria	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Down)	< 1		
Maury ES	Basement, Between Rooms W022 & W020 (Up)	1.4		
Maury ES	Basement, Between Rooms W022 & W020 (Up)	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W010	< 1		
Maury ES	Basement, In Room W030	< 1		
Maury ES	Basement, In Room W030	1.2		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E125	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E135	< 1		
Maury ES	1st Floor, In Room E140	< 1		
Maury ES	1st Floor, In Room E140	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, Between Rooms E121 & E125	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E230	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	1st Floor, In Room E240	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
Maury ES	2nd Floor, Across from Room E220	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Adjacent to Room 5	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	Basement, Across from Room 14	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Storage Room (101)	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Across from Room 113	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	1st Floor, Outside of All Purpose Room (126)	< 1		
Meyer ES	2nd Floor, Across from Room 202	< 1		
Meyer ES	2nd Floor, Across from Room 202	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Adjacent to Room 205	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
Meyer ES	2nd Floor, Across from Room 213	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 205	< 1		
Murch ES	2nd Floor, Across from Room 200B	< 1		
Murch ES	2nd Floor, Across from Room 200B	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	2nd Floor, Across from Room 200A	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 102	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	1st Floor, Across from Room 100	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	Annex Bldg, Adjacent to Room K3	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Inside Auditorium	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
Murch ES	1st Floor, Adjacent to Room 101	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Orr ES	1st Floor, Outside Main Office	< 1		
Orr ES	1st Floor, Outside Main Office	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 121	< 1		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.4		
Orr ES	1st Floor, Outside Pre-K, Room 124	1.8		
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Orr ES	1st Floor, Outside Kindergarten, Room 131	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Kindergarten, Room 135	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Outside Teacher's Lounge	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Outside Kitchen	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Stage	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Multi-Room, Near Custodian's Office	< 1		
Orr ES	1st Floor, Outside Resource Room	< 1		
Orr ES	1st Floor, Outside Resource Room	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	1st Floor, Inside Nurse's Suite	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	2nd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Girls Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	3rd Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Girls Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		
Orr ES	4th Floor, Adjacent to Boys Restroom	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Raymond ES	3rd Floor Hallway, Outside Room 36	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 36	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	3rd Floor Hallway, Outside Room 32	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 22	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		
Raymond ES	2nd Floor Hallway, Outside Room 26	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Kitchen	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Outside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor, Inside Nurse's Suite	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor Hallway, Adjacent to Room 109	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 111	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Inside Room 110	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		
Raymond ES	1st Floor, Across from Room 115	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 115	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 116	< 1		
Raymond ES	1st Floor, Inside Room 117	1.2		
Raymond ES	1st Floor, Inside Room 117	1.9		
Raymond ES	1st Floor, Inside Room 113	< 1		
Raymond ES	1st Floor, Inside Room 113	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Sousa ES	1st Floor, Outside Room C101 (High)	< 1		
Sousa ES	1st Floor, Outside Room C101 (High)	< 1		
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		
Sousa ES	1st Floor, Outside Room C101 (Low)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (High)	< 1		
Sousa ES	1st Floor, Left of Stage (Low)	< 1		
Sousa ES	1st Floor, Left of Stage (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (High)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	1st Floor, Right of Stage Entrance (Low)	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	3rd Floor Hallway, Outside Room C301	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (High)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	2nd Floor Hallway, Outside Room C201 (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Boys Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (High)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Girls Locker Room (Low)	< 1		
Sousa ES	1st Floor, Inside Room B104 1	2.2		
Sousa ES	1st Floor, Inside Room B104 1	< 1		
Sousa ES	1st Floor, Inside Room B104 2	1.1		
Sousa ES	1st Floor, Inside Room B104 2	< 1		
Sousa ES	1st Floor, Inside Room B104 3	5.8		
Sousa ES	1st Floor, Inside Room B104 3	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 4	< 1		
Sousa ES	1st Floor, Inside Room B104 5	2.2		
Sousa ES	1st Floor, Inside Room B104 5	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B104 6	< 1		
Sousa ES	1st Floor, Inside Room B109 1	1.3		

Lead in Drinking Water  
Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	1st Floor, Inside Room B109 1	< 1		
Sousa ES	1st Floor, Inside Room B109 2	3.5		
Sousa ES	1st Floor, Inside Room B109 2	2.1		
Sousa ES	1st Floor, Inside Room B109 3	8.7		
Sousa ES	1st Floor, Inside Room B109 3	< 1		
Sousa ES	1st Floor, Inside Room B109 4	1.3		
Sousa ES	1st Floor, Inside Room B109 4	< 1		
Sousa ES	1st Floor, Inside Room B109 5	2.4		
Sousa ES	1st Floor, Inside Room B109 5	< 1		
Sousa ES	1st Floor, Inside Room B109 6	9.7		
Sousa ES	1st Floor, Inside Room B109 6	1.8		
Sousa ES	2nd Floor, Inside Room A209 1	1.2		
Sousa ES	2nd Floor, Inside Room A209 1	< 1		
Sousa ES	2nd Floor, Inside Room A209 2	< 1		
Sousa ES	2nd Floor, Inside Room A209 2	4.1		
Sousa ES	2nd Floor, Inside Room A209 3	1.3		
Sousa ES	2nd Floor, Inside Room A209 3	< 1		
Sousa ES	2nd Floor, Inside Room A209 4	2.2		
Sousa ES	2nd Floor, Inside Room A209 4	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		
Sousa ES	2nd Floor, Inside Room A209 5	< 1		
Sousa ES	2nd Floor, Inside Room A209 6	1.4		
Sousa ES	2nd Floor, Inside Room A209 6	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 1	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 2	< 1		
Sousa ES	2nd Floor, Inside Room B204 3	2.2		
Sousa ES	2nd Floor, Inside Room B204 3	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 4	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 5	< 1		
Sousa ES	2nd Floor, Inside Room B204 6	1.9		
Sousa ES	2nd Floor, Inside Room B204 6	1.3		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 1	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	< 1		
Sousa ES	3rd Floor, Inside Room B304 2	1.1		
Sousa ES	3rd Floor, Inside Room B304 3	< 1		
Sousa ES	3rd Floor, Inside Room B304 3	2.3		
Sousa ES	3rd Floor, Inside Room B304 4	2.2		
Sousa ES	3rd Floor, Inside Room B304 4	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 5	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B304 6	< 1		
Sousa ES	3rd Floor, Inside Room B904 1	9		
Sousa ES	3rd Floor, Inside Room B904 1		22	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	<i>3rd Floor, Inside Room B904 1 - Retest</i>	< 1		
Sousa ES	3rd Floor, Inside Room B904 2		24	Lead filter was installed
Sousa ES	<i>3rd Floor, Inside Room B904 2 - Retest</i>	1.5		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Sousa ES	3rd Floor, Inside Room B904 2 - Retest	< 1		
Sousa ES	3rd Floor, Inside Room B904 2	5.7		
Sousa ES	3rd Floor, Inside Room B904 3	3.2		
Sousa ES	3rd Floor, Inside Room B904 3	< 1		
Sousa ES	3rd Floor, Inside Room B904 4	6.8		
Sousa ES	3rd Floor, Inside Room B904 4	< 1		
Sousa ES	3rd Floor, Inside Room B904 5	2.5		
Sousa ES	3rd Floor, Inside Room B904 5	< 1		
Sousa ES	3rd Floor, Inside Room B904 6	7.5		
Sousa ES	3rd Floor, Inside Room B904 6	< 1		
<b>Percentage of Passed Samples</b>				<b>97.96%</b>
<b>Percentage of Failed Samples</b>				<b>2.04%</b>
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Main Lobby, Adjacent to All Purpose Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Adjacent to Restroom, Outside All Purpuse Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside All Purpose Room	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Inside Cafeteria	< 1		
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Short)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Outside Room 109 (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Short)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Adjacent to Health Suite (Tall)	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	1st Floor, Inside Health Suite	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Adjacent to Room 215	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Between Boys and Girls Restroom	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 209 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Short)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	2nd Floor, Across from Room 200 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 309 (Tall)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Short)	< 1		
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Thomas ES	3rd Floor, Across from Room 300 (Tall)	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor, Inside All Purpose Room	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, Outside Counselor's Office	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor Hallway, On Left Side of Multi-Purpose Room Door	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 122	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 121	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 120	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, Inside Room 119	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, CORR 191, Adjacent to Restroom	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 115	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, Inside Room 114	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, CORR 190, Outside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 110	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 113	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 111	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		
Tubman ES	1st Floor, Inside Room 108	< 1		
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Inside Room 106	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Outside Teacher's Lounge	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	1st Floor, Inside Nurse's Suite	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Stairwell B	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 306	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	3rd Floor Hallway, Adjacent to Room 308	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 200	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 206	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		
Tubman ES	2nd Floor Hallway, Adjacent to Room 208	< 1		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
<b>Percentage of Passed Samples</b>			<b>100.00%</b>	
<b>Percentage of Failed Samples</b>			<b>0.00%</b>	
Walker Jones ES	Basement, Across from Room 032 (High)	< 1		
Walker Jones ES	Basement, Across from Room 032 (High)	< 1		
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Across from Room 032 (Low)	< 1		
Walker Jones ES	Basement, Inside Room 032	4.2		
Walker Jones ES	Basement, Inside Room 032	< 1		
Walker Jones ES	Basement, Inside Room 031	1.8		
Walker Jones ES	Basement, Inside Room 031	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	Basement, Inside Room 036	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 103	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 104	< 1		
Walker Jones ES	1st Floor, Inside Room 105	1.1		
Walker Jones ES	1st Floor, Inside Room 105	< 1		
Walker Jones ES	1st Floor, Inside Room 106	3		
Walker Jones ES	1st Floor, Inside Room 106	< 1		
Walker Jones ES	1st Floor, Inside Room 108	1.2		
Walker Jones ES	1st Floor, Inside Room 108	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (High)	< 1		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	1.7		
Walker Jones ES	1st Floor, Adjacent to Room 108 (Low)	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 112	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 115	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 117	< 1		
Walker Jones ES	1st Floor, Inside Room 119	13		
Walker Jones ES	1st Floor, Inside Room 119	2.4		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 120	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 122	< 1		
Walker Jones ES	1st Floor, Inside Room 123	1.6		
Walker Jones ES	1st Floor, Inside Room 123	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 126	< 1		
Walker Jones ES	1st Floor, Inside Room 128	2.9		
Walker Jones ES	1st Floor, Inside Room 128	< 1		
Walker Jones ES	2nd Floor, Inside Room 201	13		
Walker Jones ES	2nd Floor, Inside Room 201	2.4		
Walker Jones ES	2nd Floor, Inside Room 203	1.5		
Walker Jones ES	2nd Floor, Inside Room 203	< 1		
Walker Jones ES	2nd Floor, Inside Room 205	5.3		
Walker Jones ES	2nd Floor, Inside Room 205	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	< 1		
Walker Jones ES	2nd Floor, Inside Room 206	1.3		
Walker Jones ES	2nd Floor, Inside Room 208	1.6		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	2nd Floor, Inside Room 208	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 210	< 1		
Walker Jones ES	2nd Floor, Inside Room 212	3.6		
Walker Jones ES	2nd Floor, Inside Room 212	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Up)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Across from Room 212 (Down)	< 1		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	5.9		
Walker Jones ES	2nd Floor, Inside Room 214 (A)	1.5		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	2.8		
Walker Jones ES	2nd Floor, Inside Room 214 (B)	1.2		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 217	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 219	< 1		
Walker Jones ES	2nd Floor, Inside Room 220	1.8		
Walker Jones ES	2nd Floor, Inside Room 220	< 1		
Walker Jones ES	2nd Floor, Inside Room 221	3		
Walker Jones ES	2nd Floor, Inside Room 221	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 224	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 222	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 226	< 1		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	2.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Near Door)	11		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)		54	Lead filter was installed
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door)	5.9		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.4		
Walker Jones ES	2nd Floor, Inside Room 227 (Away from Door) - Retest	2.2		
Walker Jones ES	2nd Floor, Inside Room 228	5		
Walker Jones ES	2nd Floor, Inside Room 228	< 1		
Walker Jones ES	2nd Floor, Inside Room 230	3.5		
Walker Jones ES	2nd Floor, Inside Room 230	< 1		
Walker Jones ES	2nd Floor, Inside Main Office	5.8		
Walker Jones ES	2nd Floor, Inside Main Office	2.9		
Walker Jones ES	3rd Floor, Inside Room 300	1.6		
Walker Jones ES	3rd Floor, Inside Room 300	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (High)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 309 (Low)	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 310		18	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	1.6		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	2.2		
Walker Jones ES	3rd Floor, Adjacent to Room 310 - Retest	1.9		

## Lead in Drinking Water Sampling Results

School	Location	Pass	Fail	Remediation
Walker Jones ES	3rd Floor, Adjacent to Room 310		42	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	2.9		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2.9		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2		
Walker Jones ES	3rd Floor, Adjacent to Room 310		59	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 310	6		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	3.7		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 310 - Retest</i>	2.6		
Walker Jones ES	3rd Floor, Adjacent to Room 320		35	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	7.3		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320		16	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.7		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	1.1		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 320 - Retest</i>	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 320	11		
Walker Jones ES	3rd Floor, Adjacent to Room 320	1.6		
Walker Jones ES	3rd Floor, Adjacent to Room 324	4.2		
Walker Jones ES	3rd Floor, Adjacent to Room 324	1.4		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324	< 1		
Walker Jones ES	3rd Floor, Adjacent to Room 324		31	Lead filter was installed
Walker Jones ES	3rd Floor, Adjacent to Room 324	3.8		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 324 - Retest</i>	1.4		
Walker Jones ES	<i>3rd Floor, Adjacent to Room 324 - Retest</i>	1.3		
<b>Percentage of Passed Samples</b>				<b>93.75%</b>
<b>Percentage of Failed Samples</b>				<b>6.25%</b>
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #1	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	Inside Gymnasium #2	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #1	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor, Pre-K #2	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Kitchen	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor Lobby, Adjacent to Special Ed. Office	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Between Men's and Women's Restroom	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	3rd Floor, Beside Principal's Office	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	4th Floor, Adjacent to Room 410	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #1	< 1		
Winston ES	2nd Floor, Open Space 1, #2	< 1		

Lead in Drinking Water  
Sampling Results

School	Location	Pass	Fail	Remediation
Winston ES	2nd Floor, Open Space 1, #2	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #3	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 1, #4	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		
Winston ES	2nd Floor, Open Space 2, #5	< 1		
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #6	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #7	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	2nd Floor, Open Space 2, #8	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #1	< 1		
Winston ES	1st Floor, Open Space 1, #2	1.6		
Winston ES	1st Floor, Open Space 1, #2	1.1		
Winston ES	1st Floor, Open Space 1, #3	4.5		
Winston ES	1st Floor, Open Space 1, #3	4.9		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #4	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #5	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #6	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #7	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
Winston ES	1st Floor, Open Space 1, #8	< 1		
<b>Percentage of Passed Samples</b>				<b>100.00%</b>
<b>Percentage of Failed Samples</b>				<b>0.00%</b>
<b>Totals/Percentages of All Tested Schools</b>				
<b>Total Number of Schools Tested</b>			<b>22</b>	
<b>Total Passed Samples</b>			<b>871</b>	
<b>Total Failed Samples</b>			<b>9</b>	
<b>Total Samples Collected</b>			<b>880</b>	
<b>Percentage of Passed Samples</b>			<b>98.98%</b>	
<b>Percentage of Failed Samples</b>			<b>1.02%</b>	